


modeling tools for designers

Training Manual Level 2



Rhinoceros v5.0, Level 2, Training Manual

Updated 1/28/2015 by: Pascal Golay, Jerry Hambly, Mary Fugier

Technical Review: Lambertus Oosterveen

© Robert McNeel & Associates 2014

All Rights Reserved.

Printed in USA

Copyright © by Robert McNeel & Associates

Permission to make digital or hard copies of part or all of this work for personal or classroom use is granted without fee provided that copies are not made or distributed for profit or commercial advantage. To copy otherwise, to republish, to post on servers, or to redistribute to lists requires prior specific permission. Request permission to republish from Publications, Robert McNeel & Associates, 3670 Woodland Park Avenue North, Seattle, WA 98103; FAX (206) 545-7321; e-mail permissions@mcneel.com.

Table of Contents

PART I: Getting Started5
1 Introduction1
Duration1
Prerequisites:1
Course Objectives 1
Schedule A: 3 Classroom Days 3
Schedule B: 6 Half Days (On-line Training) 3
PART II: Interface Customization7
2 Customizing Rhino9
The toolbar layout9
Rules for commands in buttons 15
Command aliases 18
Macro editor 19
Shortcut keys 20
Plug-ins
Scripting24
Template files 25
PART III: Advanced Modeling Techniques
3 NURBS topology
4 Curve creation and continuity 37
Curve degree
Curve and surface continuity 39
Curve continuity and curvature graph 40
Advanced techniques for controlling continuity 49
5 Surface continuity 51
Analyzing surface continuity51
Matching surface continuity51
Add knots to control surface matching 55
Surfacing commands that pay attention to continuity 58
Surface blend options 69
Fillets, blends and corners70
6 Modeling with history79
Activating history
Why is history off by default?
Steps in the History chain 81
History enabled commands 82
History-related commands 82
7 Advanced surfacing techniques 85
Dome-shaped buttons
Creased surfaces

Curve fairing to control surface quality98	
8 Use background bitmaps 103	
9 An approach to modeling111	
10Applying 2-D graphics	121
Make a model from a 2-D drawing126	
11 Surface analysis	131
12 Sculpting	137
Tools to help in control point editing137	
Gumball	
DragMode137	
Nudge 138	
SetPt138	
InsertKnot	
InsertControlPoint138	
13 Deformation tools	145
Deforming objects145	
14Blocks	151
Instances and definitions151	
Defining blocks151	
Insertion points151	
Embedded and linked blocks151	
Layers and blocks151	
Editing blocks	
15 Troubleshooting	155
General strategy155	
Start with a clean file155	
Guidelines for Repairing Files155	
16 Polygon meshes	159
Render meshes159	
Meshes for manufacturing159	
Meshes from NURBS objects160	
PART IV: Rendering165	
17 Rendering	167
Rendering properties169	
Scene lighting171	
Image and bump maps173	
Decals	

List of Exercises

Exercise 1—Trackball mouse (warm-up)	5
Exercise 2—Customizing Rhino's interface	9
Exercise 3—Topology 3	33
Exercise 4—Trimmed NURBS 3	35
Exercise 5—Curve degree	37
Exercise 6—Geometric continuity4	3
Exercise 7—Tangent continuity4	5
Exercise 8—Curvature continuity4	8
Exercise 9—Surface continuity and MatchSrf5	51
Exercise 10—Continuity commands5	58
Exercise 11—Patch options6	51
Exercise 12—Lofting6	62
Exercise 13—Blends 6	63
Exercise 14—Blend options6	69
Exercise 15—Variable radius fillets7	'1
Exercise 16-Variable radius blends and chamfers	'2
Exercise 17—Fillet with patch7	'3
Exercise 18—Soft corners7	'3
Exercise 19—History introduction7	'9
Exercise 20—Soft domed buttons	35
Exercise 21—Surfaces with a crease9)1
Exercise 22—Surfaces with a crease (Part 2)9	95
Exercise 23—Handset10)3
Exercise 24—Cutout11	1
Exercise 25—Importing an Adobe Illustrator file12	21
Exercise 26—Flow the logo onto a freeform surface with history	23
Exercise 27—Making a detergent bottle	
Exercise 28—Surface analysis	
Exercise 29—Dashboard	39
Exercise 30—Using cage editing to deform an object 14	15
Exercise 31—Using other deformation tools14	8
Exercise 32—Block basics	52
Exercise 33—Inserting files as blocks	53
Exercise 34—Troubleshooting15	57
Exercise 35—Meshing15	59
Exercise 36—Rhino rendering16	67
Exercise 37—Rendering a scene	69

PART I: Getting Started

1 Introduction

This course guide accompanies the Level 2 training sessions in Rhinoceros. This course is designed for individuals who will be using and/or supporting Rhino.

The course explores advanced techniques in modeling to help participants better understand how to apply Rhino's modeling tools in practical situations.

In class, you will receive information at an accelerated pace. For best results, practice at a Rhino workstation between class sessions, and consult the Rhino Help system from the *Help menu: Help Topics*.

Duration

3 days

Prerequisites:

Completion of Level 1 training or equivalent, plus three months (minimum) experience using Rhino.

Course Objectives

In Level 2, you learn how to:

- · Customize toolbars and toolbar collections
- Create simple macros
- Use advanced object snaps
- Use distance and angle constraints with object snaps
- Construct and modify curves that will be used in surface building using control point editing methods
- Evaluate curves using the curvature graph
- Use a range of strategies to build surfaces
- Rebuild surfaces and curves
- Control surface curvature continuity
- Create, manipulate, save and restore custom construction planes
- Create surfaces and features using custom construction planes
- Group objects
- Visualize, evaluate, and analyze models utilizing shading features
- Place text around an object or on a surface
- Map planar curves to a surface
- Create 3-D models from 2-D drawings and scanned images
- Clean up imported files and export clean files
- Use rendering tools

Schedule A: 3 Classroom Days

Day 1	Торіс
8-9:30AM	Introduction and warm up exercise.
9:30AM-12PM	Interface and customization
12-1PM	Lunch
1-3PM	NURBS topology and curve degree
3-5PM	Curve and surface continuity
Day 2	Торіс
8-10AM	History, advanced surfacing and CPlane tools
10AM-12PM	More CPlanes, mapping objects to surfaces
12-1PM	Lunch
1-3PM	Surface analysis
3-5PM	Putting it all together—Scoop exercise
Day 3	Торіс
8-10AM	More CPlanes, mapping objects to surfaces
10AM-12PM	Surface analysis, direct surface manipulation
12-1PM	Lunch
1-3PM	Blocks, troubleshooting, Meshing
3-5PM	Rendering (time allowing)

Class schedules are suggested.

Actual class schedule will be set by the instructor.

Schedule B: 6 Half Days (On-line Training)


Session 1	Торіс	
9-10:45AM	Introduction and warm up exercise.	
11AM-12:30PM	Interface and customization	
Session 2	Торіс	
9-10:45AM	NURBS topology and curve degree	
11AM-12:45PM	Curve and surface continuity	
Session 3	Торіс	
9-10:45AM	History, advanced surfacing and CPlane tools	
11AM-12:45PM	More CPlanes, mapping objects to surfaces	
Session 4	Торіс	
9-10:45AM	Surface analysis	
11AM-12:45PM	Putting it all together—Scoop exercise	
Session 5	Торіс	
9-10:45AM	More CPlanes, mapping objects to surfaces	
11AM-12:45PM	Surface analysis, direct surface manipulation	
Session 6	Торіс	
9-10:45AM	Blocks, troubleshooting, Meshing	
11AM-12:45PM	Rendering (time allowing)	
All Sessions Questions:	12:45-1PM	

End of Class 1:00PM

Exercise 1—Trackball mouse (warm-up)

- 1 Begin a new model, save it as Trackball.3dm.
- 2 Model a trackball mouse on your own.

The dimensions are in millimeters. Use the dimensions as guides only.



PART II: Interface Customization

2 Customizing Rhino

This chapter discusses customizing Rhino's interface with the following tools:

- Toolbar layout
- Macro Editor
- Shortcut keys
- Scripting
- Template files

The toolbar layout



The toolbar layout is the arrangement of toolbars containing command buttons on the screen. The toolbar layout is stored in a file with the .rui extension that you can open and save. Rui files contain command macros, icons in three sizes, as well as tooltips and button text. Rhino comes with a default toolbar file and automatically saves the active toolbar layout before closing unless the .rui file is read-only. You can create your own custom toolbar files and save them for later use.

You can have more than one toolbar file open at a time. This allows greater flexibility to display toolbars for particular tasks.

Rhino's customization tools make it easy to create and modify toolbars and buttons. Adding to the flexibility is the ability to combine commands into macros to accomplish tasks that are more complex. In addition to toolbar customization, it is possible to set up command aliases and shortcut keys to accomplish tasks in Rhino.

Exercise 2—Customizing Rhino's interface

In this exercise, we will create buttons, toolbars, macros, aliases, and shortcut keys that will be available to use throughout the class.

To create a custom toolbar collection

There are times that the standard commands and buttons do not do exactly what you want. For example, Zoom Extents will look at all of the objects in a model and then zoom to the extents of these objects. In this exercise, we will open a model that has several objects including some light objects.

Let us say we want to use Zoom Extents to zoom to the objects, but we do not want the command to consider the light objects. In this exercise, we will make a new toolbar with a button that will Zoom Extents while ignoring any light objects in the model.

1 Open the model ZoomLights.3dm.

2 From the Tools menu, click Toolbar Layout.

This opens the Rhino Options dialog on the Toolbars page.

3 Highlight the **Default** toolbar file.

🛃 Rhino Options		x
Annotation	▲ File Edit Tools	
Grid		
- Mesh	Files	
- Neon		
- Notes		
Rendering		
⊞ Rhino Render		
⊞ Units	C:\Users\Jerry\AppData\Roaming\McNeel\Rhinoceros\5.0\UI\default.rui	
Web Browser	· · · ·	
E Rhino Options	Toolbars	
Alerter	🗆 🧏 3-D Digitizing	
Aliases		
Appearance Context Menu	Align	_
	Analyze 🗠 🛶	
	E Animation	
- Idle Processor	Animation Preview	
Keyboard	Animation Setup	
Libraries	0 Annotate	
- Licenses		
🖽 Modeling Aids	Arc	
- Mouse	Array	
Plug-ins	🗆 🗊 Background Bitmap	
Rendering	Block	
- Rhino Render Options		
RhinoScript Selection Menu	Box	
Selection Menu Toolbars	🗌 🗆 🎼 Cage	Ŧ
Updates and Statistics		
	Restore Defaults OK Cancel Help	
E VICW	Restore Defaults OK Cancel Help	

- 4 On the **Toolbars** page click the **File** menu, click **Save As**.
- 5 Type Level 2 Training in the File name box and click Save.

A copy of the current default toolbar file is saved with the new name.

Toolbar files are saved with a .rui extension. You will use this new toolbar file to do some customization.

In the Rhino Options dialog, on the Toolbars page, all the open toolbar files are listed along with a list of all the individual toolbars for the selected toolbar file.

Check boxes show the current state of the toolbars. A checked box indicates that the toolbar is displayed.

File Edit Tools	File Edit Tools
D New	Files 🧳
🎼 Open	Level 2 Training
🚽 Close	2 I I I I I I I I I I I I I I I I I I I
Close All	
Save McNeel\Rhinoce	s/Jeny/AppData\Noaming\McNeel/Rhinoceros\55
🛃 Save As	Toolbars
Save Al 1	🗆 🧏 3-D Digitizing
Properties	🗆 📼 Align
💒 Import Toolbars	🗆 🚈 Analyze
🛃 Export Groups	Animation
- E Animation Preview	🗆 💌 Animation Preview
🗆 💠 Animation Setup	Animation Setup
🗆 🛈 Annotate	🗆 🛈 Annotate
	Arc
□ III Array	🖬 🖬 Array 🕈
🗆 🗟 Background Bitmap	🗆 🖸 Background Bitmap
🗆 🚳 Block	🗆 🚳 Block
🗆 🍘 Box	🖕 🗆 🥥 Box
🗆 🐲 Cage	Cage
Restore Defaults OK	Restore Defaults OK

To create a new toolbar

- 1 On the **Toolbars** page click the **Edit** menu, click **New Toolbar**.
- 2 In the Toolbar Properties dialog, name the toolbar Zoom, and click OK.A new single button toolbar appears.

4


3 Close the Rhino Options dialog.

File Edit Tools	
Files - 🚽 New Group	
Level 2 New Toolbar	
Delete	😵 Loolbar Properties
Properties	
sWery AppData \Roaming \McNeel\Rhinoceros\5.0	Toolbar
	Text: Zoom
	Edit bitmap
□ ½ 3 D Digitizing	Toolbar button appearance
🔟 👓 Align 🦿	 Image only
🗆 🛲 Analyze 🥒	
🗆 🖽 Animation 🛛 💊	C Text only
Animation Preview	Both image and text
🗆 🜩 Animation Setup	Sidebar
□ O Annotate	▼
⊐ ﷺ Array	
🗆 🖻 Background Bitmap	
🗆 🚳 Block	
🗆 🤪 Box	
🗆 🖗 Cage 🍦	
ŧ	OK Cancel Help
Restore Defaults OK	

Another way to work with toolbars is to use the title bar of a floating toolbar.

Right-click on the title bar of the new toolbar you created.

A popup list of toolbar options and commands displays.



To edit the new button

1 Hold down the *Shift key* and *right-click* the smiley face button in the new toolbar.

The **Button Editor** dialog appears with fields for commands for the left and right mouse buttons, as well as for the tooltips.

2 In the Button Editor dialog, click Image only.

In the Text box, type Zoom No Lights.

3 For the Left mouse button Tooltip, type Zoom Extents except lights

For the **Right mouse button** Tooltip, type **Zoom Extents except lights all viewports**.

earance Inherit appearance from tab		Edit 🔀
Image only		
Text only		
🔘 Both image and text		
Text Zoom No Lights		
⁵ Left mouse button		[®] Right mouse button
Fooltip:		Tooltip:
Zoom Extents except lights		Zoom Extents except lights all viewports
Command:		Command:
_SetRedrawOff_SetNone _SetLight _Invert Zoom _Selected _SetNone _SetRedrawOn	×	!_SetRedrawOff_SelNone_SetLight_Invert _Zoom_All_Selected_SetNone_SetRedrawOn
▲	•	
ed toolbar		
(No link)		

- 4 In the Left mouse button Command box, type ! _SelNone _SelLight _Invert _Zoom _Selected _SelNone.
- 5 In the Right bouse button Command box, type
 ! _SelNone _SelLight _Invert _Zoom _All _Selected _SelNone.

Debug the new button

Combine above macro with **SetRedrawOff/SetRedrawOn**. This will make the macro run without flashing and without too much info being reported to command history.

Your macro will work regardless of adding **SetRedrawOff/SetRedrawOn**. However, this is good practice to make your macro work more elegantly.

- 1 In the Left mouse button Command box, type !_SetRedrawOff_SelNone_SelLight_Invert_Zoom_Selected_SelNone_SetRedrawOn.
- 2 In the Right bouse button Command box, type !_SetRedrawOff_SelNone_SelLight _Invert _Zoom _All _Selected _SelNone _SetRedrawOn.


To change the bitmap image for the button

1 In the **Button Editor** dialog, click the **Edit...** next to the button icon in the upper right to open the **Bitmap Editor**.

The bitmap editor is a simple paint program that allows editing of the icon bitmap. It includes a grab function for capturing icon-sized pieces of the screen, and an import file function.

2 In the Edit Bitmap dialog, click the File menu, click Import Bitmap to Fit, and select the ZoomNoLights_32.bmp.


You can import any bitmap image. If the bitmap is too large, it will be scaled to fit as it is imported.



3 In the **Edit Bitmap** dialog, make any changes to the picture, and click **OK**.

Double-click on the color swatches to the right of the standard color bar to access the **Select Color** dialog for more color choices.

4 Click **OK** in the **Select Color** dialog.



To change the bitmap image to use an alpha channel


Notice that the new button's background color does not match the background color of the other buttons. We will change the image background using an alpha channel, so that it matches the Windows 3D Objects color like the other buttons.

- 1 Hold down the *Shift* key and right-click the **ZoomNoLights** button.
- 2 In the **Button Editor** dialog, click **Edit** to open the **Bitmap Editor**.
- 3 Left-click the upper right color swatch to the right of the black color. Change the alpha color number, labeled **A**, for the button color from **255** to **1**.

This will make the current paint color transparent.

- 4 Change to the **Fill** tool, then **right-click** in the background area of the button image.
- 5 Click **OK** in the **Edit Bitmap** dialog, and then click **OK** in the **Button Editor** dialog.

The color matches the Windows 3D Objects color.



To use the new button

- 1 Click the **ZoomNoLights** button.
- **2** Use the button to zoom the model two ways.

You will notice that it ignores the lights when doing a **Zoom Extents**.

Rules for commands in buttons

You can enter the commands or command combinations in the appropriate boxes, using these rules:

Item	Sample	Description
Space	!_Line	A space is interpreted as Enter. Commands do not have spaces (for example, SelLight) but you must leave a space between commands.
Ν ΙΙ		If your command string refers to a file, toolbar, layer, object name, or directory for which the path includes spaces, the path, toolbar name, or directory location must be enclosed in double-quotes.
! (Exclamation mark)	!circle	An ! (Exclamation mark) followed by a space is interpreted as Cancel. Generally, it is best to begin a button command with an exclamation mark (!) if you want to cancel any other command that may be running when you click the button.
' (apostrophe)		View manipulation commands like Zoom can be run in the middle of other commands. For example, you can zoom and pan while picking curves for a loft. An '(apostrophe) prior to the command name indicates that the next command is a nest able command.

Item	Sample	Description
_ (underscore)		An underscore (_) runs a command as an English command name.
		Rhino can be localized in many languages. The non-English versions will have commands, prompts, command options, dialogs, menus, etc., translated into their respective languages. English commands will not work in these versions. For macros written in English to work on all computers (regardless of the language of Rhino), the macros need to force Rhino to interpret all commands as English command names, by using the underscore.
- (Hyphen)	Sweep2	Commands with dialogs can be run at the command-line with command-line options. To suppress the dialog and use command-line options, prefix the command name with a hyphen (-).
Pause		User input and screen picks are allowed in a macro by putting the Pause command in the macro. Commands that use dialogs, such as Revolve, do not accept input to the dialogs from macros. Use the hyphen form of the command (-Revolve) to suppress the dialog and control it entirely from a macro.

Note: These rules also apply to scripts run using the **ReadCommandFile** command and pasting text at the command prompt. More sophisticated scripting is possible with the Rhino Script plug-in, but quite a lot can be done with the basic commands and macro rules.

Some very useful commands for macros are SelLast, SelPrev, SelName, Group, SetGroupName, SelGroup, Invert, SelAll, SelNone, ReadCommandFile, and SetWorkingDirectory.

To link a toolbar to a button

- 1 Shift+right-click the Zoom Extents button in the Standard toolbar.
- 2 In the Button Editor dialog, click in the Linked toolbar area, select Zoom from the list, and click OK.

Now the **Zoom Extents** button has a small black triangle in the lower right corner indicating it has a linked toolbar.

3 Click and hold the **Zoom Extents** button to fly out your newly created single button toolbar.

If you close the **Zoom** toolbar you just created, you can always re-open it using the linked button.

4 Try the new linked button.

Button Editor			? <mark>- x -</mark>
Appearance Appearance from tab Image only Text only			Edit
 Both image and text Text: Zoom extents 			
Eft mouse button Tooltip: Zoom extents		 Right mouse button Tooltip: Zoom extents all viewports 	
Command:		Command:	
_Zoom _Extents	*	_Zoom _All _Extents	*
4	F F	4	The second secon
Linked toolbar			
Zoom			
Float to top		0	K Cancel

To add a command to an existing button

- 1 Hold the *Shift* key and **right-click** the **Move** button on the **Main** toolbar.
- 2 In the Button Editor dialog, in the Right mouse button Command box, type !_Move_Pause_Vertical
- 3 In the Button Editor dialog, in the Right mouse button Tooltip box, type Move Vertical.

This button will allow you to duplicate objects in the same location. We will use this command several times during the class.

4 Select one of the objects in the model and **right-click** on the **Move** button.

5 Move the selected object vertically from the construction plane.

Button Editor	? ***
Appearance Inherit appearance from tab Image only Text only Both image and text Text: Move	Edit
9 Left mouse button Tooltip: Move	 Right mouse button Tooltip: Move Vertical
Command: !_Move	Command: !_Move_Pause_Vertical
Linked toolbar	4 F
Transform	•
Float to top	OK Cancel

Command aliases

The same commands and macros that are available for buttons are also available for command aliases. Command aliases are like using shorthand in Rhino. They are commands and macros that are activated whenever commands are allowed, but are often used as a keyboard shortcut followed by **Enter**, **Spacebar** or clicking the **right mouse button**.

Use aliases for command sequences that you use often or frequently.

Note: When making aliases, use keys that are close to each other or repeat the same character 2 or 3 times, so they will be easy to use.

To make a command alias

- 1 Open the model Aliases.3dm.
- 2 From the Tools menu, click Options.
- 3 In the **Rhino Options** dialog, on the **Aliases** page, you can add aliases and command strings or macros.

4 Click **New** to make a new alias.

We will make aliases to mirror selected objects vertically and horizontally across the origin of the active construction plane. These are handy when making symmetrical objects built centered on the origin.

H Units		- Jul	
		DisplayAttrsMgr	!_OptionsPage _AdvancedSettings
····· Web Browser		M	!_Move
Rhino Options		mx	!_Mirror_Pause_XAxis
Alerter		my	!_Mirror_Pause_YAxis
Aliases		0	' Ortho
🛓 Appearance		Р	' Planar
🛓 Context Menu		PlugInManager	OptionsPage PlugIns
🗟 - Files		POff	PointsOff
General	=	POn	PointsOn
Idle Processor		S	- Snap
Keyboard		U	Undo
Libraries		W	' SelWindow
Licenses		Z	Zoom
🛓 Modeling Aids		ZE	'Zoom Extents
Mouse		ZEA	Zoom All Extents
Plug-ins		ZS	'Zoom Selected
Rendering		ZSA	Zoom All Selected
···· Rhino Render Options			
Rhino Script		Import Ex	oprt New Delete
a second s	- 	an grad and see	have a state of the second

5 In the Alias column, type **mx**.

In the Command Macro column, type ! _Mirror _Pause _XAxis

The alias is in the left column and the command string or macro is in the right column. The same rules apply here as with the buttons. Aliases can be used within other aliases' macros or button macros.

- 6 Click **New** to make another new alias.
- 7 In the Alias column, type my.

In the Command Macro column, type ! _Mirror _Pause _YAxis.

To try the new aliases

Select some geometry and type **mx** or **my** and press **Enter**.

If no objects are pre-selected, the Pause in the script prompts you to select objects, and an Enter will complete the selection set.

Macro editor

When making macros that are more complicated, it is good practice to use Rhino's built-in macro editor. Macros can be edited and run directly from the editor. This allows you to quickly test whether command options and syntax are correct.

CUSTOMIZING RHINO

To use the macro editor

In the following example we will make a mirror macro that allows you to mirror across the construction plane. We will use the **Macro Editor** to build and test the macro before we add it to the **Alias** list.

- 1 From the Tools menu, click Command, then click Macro Editor.
- 2 In the Macro Editor type !_Mirror _Pause _3Point 0 1,0,0 0,1,0.
- **3** To test the macro, click the **Run** icon in the **Macro Editor**.
- **4** If the macro runs as expected, select the text and copy it to the clipboard.
- 5 Open the **Options** dialog on the **Alias** page and make a new alias **mc**. Paste the text from the **Macro Editor** into the **Alias** command column.
- 6 Select some geometry and try the new alias out. Type **mc** and press **Enter**.

To Export and Import Options

There are times when you might want to copy all or some of the options from one computer to another. An example might be a desktop computer and a laptop computer. This is especially true for aliases, keyboard shortcuts, and display modes. Rhino has commands that Export options to a file as well as Import options from a file.

- **1** From the **Tools** menu, click **Export Options**.
- 2 In the Save As dialog, for the File Name, type Level2_Options.

The current options are saved to a file.

- **3** Now, delete one of the aliases you previously made.
- 4 From the **Tools** menu, click **Import Options**.
- 5 In the **Import Options** dialog, select the file you just saved.
- 6 For the **Options to import**, click **Aliases**, **Appearance**, or any other options you wish to import.

Check to see if the alias you deleted is back.

Shortcut keys

The same commands, command strings, and macros that you can use for buttons and aliases are also available for keyboard shortcuts. Shortcuts are commands and macros that are activated by certain combinations of function keys, *Ctrl*, *Alt*, and alphanumeric keys.

To make a shortcut key

- **1** From the **Tools** menu, click **Options**.
- 2 In the **Rhino Options** dialog, on the **Keyboard** page, you can add command strings or macros.
- 3 Click in the column next to the F4 to make a new shortcut.
- 4 Type _DisableObject snap _Toggle for the shortcut.

This shortcut will make it easy to toggle the state of running object snaps.

Rhinoceros	(3) ×	
Macro Editor		
⊳× ⊗		
!_Mirror_Pause_3Point 0 1,0,0 0,1,0		

5 Close the dialog and try it out.

There are several shortcut keys that already have commands assigned. The same rules apply here as with the buttons and aliases.

Document Properties		Key:	Command macro:
🛓 Annotation		F1	' Help
Grid		F2	! Command History
Mesh		E3	Properties
Neon		F4	_DisableOsnap _Toggle
··· Notes		F5	
Rendering		FG	!_Camera _Toggle
🖮 Rhino Render		F7	noecho - Grid ShowGrid ShowGridAxes Enter
🖮 Units		F8	_Ortho
Web Browser		Г9	'_Shap
Rhino Options		F10	!_PointsOn
Alerter		F11	!_PointsOff
···· Aliases		F12	'_DigClick
Appearance		Cirl+F1	' SetMaximizedViewport Top
👜 Context Menu	=	Cil (F2	'_SetMaximizedViewport Front
🖮 Files		Ctrl+F3	_SetMaximizedViewpolt Right
General		Cid+F4	_SetMaximizedViewport Perspective
Idle Processor		Cul+F5	
Keybcard		Cirl+F6	
Libraries		Cirl+F7	
··· Licenses		Crl+F8	
Modeling Aids		Cirl+F9	
Mouse		Cil+F10	
Plug-Ins		Cirl+F11	
···· Rendering		Ctrl+F12	
Rhino Render Options		Oul+Shift+F1	
RhinoScript			
Selection Menu			

Plug-ins

Plug-ins are programs that extend the functionality of Rhino. Plug-in classifications include:

Included plug-ins

Shipped and installed with Rhino. Some of these plug-ins are loaded, for example Rhino Render, Render Development Kit, Rhino Toolbars and Menus, BoxEdit, etc. Others are installed, but not loaded. Most of these plug-ins are Import/Export plug-ins. They are generally enabled and will get loaded when they are used for the first time.

Rhino 5.0 Labs plug-ins

Experimental plug-ins developed in-house. These plug-ins are being considered for inclusion in future service releases or the next version of Rhino. They are available for download from the <u>Rhino 5.0 Labs Tools</u> website.

McNeel plug-ins

Flamingo nXt, Penguin, Brazil (rendering) and Bongo (animation) are McNeel products that are available for purchase.

Third-party plug-ins

These are programs and utilities that are developed by third-party developers. Some of these are free, but most are available for purchase. A few of the programs are stand-alone applications that work with Rhino, but are not plug-ins. Generally, they add some specific capability to Rhino. For example RhinoCam is a CAM application, VRay is a rendering application, RhinoGold is jewelry design software, etc. For more information about these programs visit the Rhino <u>Resources</u> website.

🔽 Rhino Options			X
Document Properties Annotation Grid Grid Nesh Notes Rendering P. Units Web Browser Prino Options	Unloaded Plug-ins All Plug-ins Leaded Plug-ins Unloaded Plug-ins Plug-ins that do not ship with Rhino Enabled Plug-ins Disabled Plug-ins Disabled Plug-ins ACIS Export Adobe Illustrator Export Adobe Illustrator Export AutoCAD file export : export_AC AutoCAD file export : export_AC	Enabled V V V V V	

To load a plug-in

For this example we have included a plug-in from the Rhino 5.0 labs page for you to install and use.

- **1** From the **Tools** menu, click **Options**.
- 2 Click Plug-ins.

A list of currently loaded and available plug-ins is displayed.

- 3 On the **Plug-ins** page, click **Install**.
- 4 In the Load Plug-In dialog, navigate to the Level 2/Models/Plug-ins folder, then, depending on which version of Rhino 5.0 you're running, click either RhinoPolyhedra_x64.rhp or RhinoPolyhedra_x86.rhp (needed for 32-bit version of Rhino 5.0).
- **5** To run the command, type **Polyhedron** on the command-line.

6 In the **Polyhedron** dialog, select one of the polyhedrons from the list, then click a center point and a radius point.

🛃 Rhino Options					×
Annotation		A Plugins		6	
Grid		/v ring ins	· .		
···· Mesh		Name -	Loaded	Enabled	
- Neon		3D Studio Export		1	
Notes		3D Studio Import		~	=
Rendering		3D Systems InVision			
Here Rhno Render		3Dconnexion 3D Mouse	Yes	√	
🖶 Units		ACIS Export	15.2		
·····Web Browser		Adobe Ilustrator Export		v	
Rhino Options		Adobe interator export	Yes	~	
Alerter			Tes		
Aliases				V	
Appearance		AutoCAU file export : export_AC		N	
🗈 Context Menu		AutoCAD file import: import_ACAD		V	
🔁 🛱 Files		BlockEdit		V	
General	Ξ	🔁 Eongo 2.0	Yes	V	
Idle Processor		▶ Fongot 12(v40		1	
Keyboard		🔁 BoxEdit		1	
Libraries		Calo		V	
Licenses		Comma Separated Value Export		W	
🗓 Medeling Aida				V	
Mouae		Gult3D Export		V	
		Delft Spline Systems Desk Proto		V	
Rendering		Dimension Catalyst			-
Rhino Render Options				10.	
RhnoScrpt		Properties			
Selection Menu		Ask to load disabled plug-ins			
🕂 - I oolbars		Ask to load disabled plug-ris			
	Ŧ		ОК	Cancel He	lp

To load a plug-in using drag and drop

- **1** Open a Windows Explorer window.
- 2 Navigate to the folder that has the plug-in you want to install.
- **3** Simply click and hold the plug-in file, drag it and drop it into the Rhino window.

🔛 Load Plug-in				x
🕞 🕞 🗸 🕹 Level 2 🕨 Models 🕨 Plug-ir	15 👻 🖣	Search Plu	ıg-ins	٩
Organize 🔻 New folder			= - 1	0
Name	Date modified	Туре	Size	
🔯 RhinoPolyhedra_x64.rhp	11/27/2012 10:25	RHP File	4,977 KB	
🐼 RhinoPolyhedra_x86.rhp	11/27/2012 10:28	RHP File	3,520 KB	
File name: RhinoPolyhed	ra_x64.rhp 👻	All compati Open	ble file types (*.rh	

Scripting

Rhinoceros supports scripting using RhinoScript and Rhino.Python.

To script Rhino, you must have some programming skills. Fortunately, scripting is easy to learn and there are materials available to help you get started.

For more information, go to the <u>Developer Wiki</u>. In addition, Rhino installs with Help for both scripting tools. See the **EditScript** and **EditPythonScript** commands for details.

We will not cover how to write a script in this class, but we will learn how to run a script and apply it to a button.

The following script will list information about the current model.

To load a RhinoScript

- 1 From the Tools menu, click RhinoScript, then click Load.
- 2 In the Load Script File dialog, click Add.
- 3 In the **Open** dialog, select **CurrentModelInfo.rvb**, then click **Open**.

Note: You may get a message that Rhino "Cannot find the script file CurrentModelInfo.rvb.


If that happens you will need to include the full path to the folder where the script file is located or add a search path in the **Files** section of **Rhino Options**.

4 In the Load Script File dialog, highlight CurrentModelInfo.rvb, then click Load.

Select a script file to load:		
		Load Cluse Add Remove Help
<	•	V Save list

- **5 Save** the current model. If you do not have a saved version of the model, no information is possible.
- 6 From the **Tools** menu, click **RhinoScript**, then click **Run**.
- 7 In the **Run Script Subroutine** dialog, click **CurrentModelInfo** and then click **OK**.

A dialog describing the current information about this model displays.



Current Model Information	x
Full Path: C:\Rhino V5\en-us\Training\Training Guides\Level 2 Models\Aliases.3dm File Name: Aliases.3dm File Type: Rhino 3-D Model File Attributes: Archive Date Created: 1/15/2013 12:57:17 PM Last Date Accessed: 1/15/2013 12:57:17 PM Last Date Modified: 1/15/2013 12:57:17 PM File Size (Bytes): 56301	'\PG
	ок

To edit the script file


- 1 From the **Tools** menu, click **RhinoScript**, then click **Edit**.
- 2 On the Rhino Script Editor window, from the File menu, click Open.
- 3 On the **Open** dialog, select **CurrentModelInfo.rvb**, then click **Open**.

We will not be editing script files in this class. This exercise is to show how to access the editing feature if needed.


4 Close the Rhino Script Editor window.


To make a button that will load or run a script

- **1** From the **Tools** menu, click **Toolbar Layout**.
- 2 In the **Toolbars** dialog, check the **File** toolbar then close the dialog.
- **3** Right-click on the title bar of the **File** toolbar, then click **New Button** from the popup menu.
- **4** In the **Button Editor** dialog, in the **Left mouse button** Tooltip, type **Current Model Information**.
- 5 In the **Right mouse button** Tooltip, type **Load Current Model Information**.



- 7 In the Left mouse button Command box, type ! -_RunScript (CurrentModelInfo)
- 8 In the **Right mouse button** Command box, type **! -_LoadScript "CurrentModelInfo.rvb"**





To add a custom bitmap

- 1 In the **Button Editor** dialog, click **Edit**.
- 2 In the Edit Bitmap dialog, from the File menu, click Import Bitmap, and Open the CurrentModelInfo.bmp, then click Open.
- 3 In the Button Editor dialog, click OK.
- **4** Try the new button.

Template files

A template is a Rhino model file you can use to store basic settings. Templates include all the information that is stored in a Rhino 3DM file: objects, blocks, layouts, grid settings, viewport layout, layers, units, tolerances, render settings, dimension settings, notes, and any setting in document properties.

You can use the default templates that are installed with Rhino or save your own templates to base future models on. You will likely want to have templates with specific characteristics needed for particular types of model building.

The standard templates that come with Rhino have different viewport layouts or unit settings, but no geometry, and default settings for everything else. Different projects may require other settings to be changed. You can have templates with different settings for anything that can be saved in a model file, including render mesh, angle tolerance, named layers, lights, and standard pre-built geometry and notes.

If you include notes in your template, they will show in the **Open Template File** dialog.

The **New** command begins a new model with a template (optional). It will use the default template unless you change it to one of the other templates or to any other Rhino model file.

To change the template that opens by default when Rhino starts up, choose **New** and select the template file you would like to open when Rhino starts, then check the **Use this file when Rhino starts** box.

To create a template

- 1 Start a new model.
- 2 Select the Small Objects Inches.3dm file as the template.
- 3 From the Render menu, click Current Renderer, and then click Rhino Render.

To set the Document Properties


- **1** From the **File** menu, click **Properties**.
- 2 In the Document Properties dialog, on the Grid page, change the Snap spacing to 0.1, the Minor grid lines every to 0.1, the Major lines every to 10, and the Grid line count to 10.

Document Properties			1	Crosses
Document Properties Annotation Grid Mesh Necn Notes Rendering Rhino Render Units Model Layout Web Browser Rhino Options Aletter Aliases Appearance Context Menu Files	III	Apply grid changes to Active viewport only (P Active viewports only (P All viewports Grid properties Grid line count Minor grid lines every: Major lines every: Show grid lines Show grid axes Show world axes icon Grid snap	erspective) 10.0 0.1 10	inches minor grid lines
General Idle Processor		Snap spacing:	0.1	inches
-Keyborut		المحلي المراجر المراجر الم	pres .	and and and

3 On the **Mesh** page change the setting to **Smooth & slower**.

Socument Properties		9 (
Document PropertiesAnnolationGridMeshNeonNotes	Render mesh quality Jagged & faster Smooth & slower Custom	Preview

4 On the Rhino Render page, check Use lights on layers that are off.



5 On the **Units** page, change the **Angle tolerance** to **0.5**, click **OK**.

The end tangent normals will be determined by this setting.

S Document Properties				X
Document Properties	Units and tolerances ——			
Annotation				
Gnd	Model units:	Inches		T
Mesh				
Neon	Absolute tolerance:	0.001	units	
Notes	Relative tolerance:	1.0		
Rendering	Relative tolerance:	1.0	percent	
🖃 Rhino Hender	Angle tolerance:	0.5	degrees	
··· Render Details	- Angle tore refreet		adgrees	
Focal Blur	Custom units			
Moděl	Name:	Units		
Layout	Units per meter	1.0		
Web Browser	Child per inecer	1.0		
Rhino Options	⊟ Distance display ———			
Alerter				
Alases	Oecimal			
Appearance	Fractional			
⊟- Context Menu	Feet & Inches			
	Disalau anaisian	.		
General	Display precision:	1.000		
Idle Processor				
Keyboard	and the second second	A care	and the second	1

To set up the layers

1 Open the Layers panel and rename Layer 05 to **Spotlights**, Layer 04 to **Curves**, Layer 03 to **Surfaces**, and Default to **Reference**.


Make the **Spotlights** layer current.

Delete Layer 01 and Layer 02 layers.

Rhinoceros				÷ (
🖲 Layers 🔪				
$D \oplus X$	\blacksquare ∇	4 🍸 🗎	Þ 😡	
Name		Material	Linetype	Print Width
Reference			Continuous	🔶 Default
Curves	°6∎		Continuous	Default
Surfaces	<mark>ଚ</mark> ମ 🛛	0	Continuous	🔶 Default
Spotlights	V [10	Continuo	Oefault

2 Set up a spotlight so that it points at the origin and is approximately 45 degrees in the **Top** viewport and tilted 45 degrees in the **Front** viewport.

- **3** Use the **my** alias to mirror the light to make a second one.
- **4** To make the Curves layer the only visible layer, from the **Edit** menu, click **Layers** then click **One Layer On**. Select the **Curves** layer.




To set save notes

1 From the **Panel** menu, click **Notes**.

Type the details about this template in the Notes panel.

2 From the File menu, click Save As Template.

Name the template Small Objects – Decimal Inches - 0.001.3dm.



This file with all of its settings is now available any time you start a new model.

CUSTOMIZING RHINO

To set a default template

- 1 From the File menu, click New.
- **2** Select the template you want to use as the default template.
- 3 In the **Open Template File** dialog, check the **Use this file when Rhino starts** checkbox.

You should make custom templates for the kind of modeling that you do regularly to save set up time.

Open Template	File				
Look in.	🐌 Template Files		•	G 🤌 📂 🛄 -	
Recent Places Recent Places Desktop Libraries Computer	 Large Objects Large Objects Large Objects Large Objects Small Objects 	- Inches.3dm - Meters.3dm - Millimeters.3dm - Centimeters.3dm - Decimal Inches - 0.001 - Feet.3dm - Inches.3dm			
	File name:	Small Objects - Decimal Inch	es - 0.00)1.3dm 🔻	Open U
	Files of type:	Rhino 3D Models (*.3dm)		▼]	Cancel
	🔽 Use this file when	Rhino starts			No Template

PART III: Advanced Modeling Techniques

3 NURBS topology

The underlying geometry of NURBS surfaces have a rectangular topology in UV, or *parameter* space. Rows of surface points, and parameterization, are organized in two directions (U and V). These two directions are crosswise to each other, at more or less 90 degrees on an ideal surface, though this is not always possible. This structure is not always obvious when creating or manipulating a surface. Remembering this structure is useful in deciding which strategies to use when creating or editing geometry.

Exercise 3—Topology

This exercise will demonstrate how NURBS topology is organized and discuss some special cases that need consideration when creating or editing geometry.


1 Open the model **Topology.3dm**.


There are several surfaces visible on the current layer.

2 Turn on the control points of the simple rectangular plane on the left.

It has four control points, one at each corner this is a simple untrimmed planar surface that shows the rectangular topology.

3 Now, turn on the control points of the curvier surface.





There are many more points, but it is clear that they are arranged in a rectangular fashion.

1 Select the cylinder.

It appears as a continuous circular surface, but it also has a rectangular boundary.

2 Use the **ShowEdges** command (*Analyze menu: Edge Tools* > *click Show Edges*) to highlight the surface edges.


Notice that there is a seam highlighted on the cylinder. The seam that is highlighted represents two edges of the rectangle, while the other two edges are circular at the top and the bottom. The rectangular topology is present here, also.


3 Select the sphere.


It appears as a closed continuous object.


4 Use the **ShowEdges** command to highlight the edges.

Notice that there is a seam highlighted on the sphere. The highlighted seam represents two edges of a rectangular NURBS surface, while the other two edges are collapsed to a single point at the poles. When all of the points of an untrimmed edge are collapsed into a single point, it is called a singularity.









The rectangular topology is present here, also, though very distorted.

- 1 Turn on the **Control Points** for the sphere.
- 2 Zoom Target (View menu: Zoom > Zoom Target) draw a select window very tight around one of the poles of the sphere.
- **3** Select the point at one pole of the sphere and start the **Smooth** (*Transform menu: Smooth*) command.
- 4 In the **Smooth** dialog, uncheck **Smooth Z**, then click **OK**.

A hole appears at the pole of the sphere. There's no longer a singularity at this pole of the sphere. **ShowEdges** will highlight this as an edge as well.

5 Use the **Home** key to zoom back out.

This is the fastest way to step back through view changes.

To select points

- **1** Open the **Select Points** toolbar.
- **2** Select a single point at random on the sphere.
- **3** From the **Select Points** toolbar, click **Select U**.

An entire row of points is selected.

- **4** Clear the selection by clicking in an empty area and select another point on the sphere.
- ©ेःःःःः सिःहःःः वि U⇒ V⇒ †is € Select U

Select Points

3

X

Cancel

🥪 Smooth

🔽 Smooth Y

Smooth X

Smooth Z Fix Boundaries

World coordinates
 CPlane coordinates

Smooth factor: 0.2

OK.




5 From the **Select Points** toolbar, click **Select V**.

A row of points in the other direction of the rectangle is selected. This arrangement into uand v-directions is always the case in NURBS surfaces.

6 Try the other buttons in this toolbar on your own.

() U→ U→ 1°3 1°3 () V→ U→ 1°3 1°3 () Select V	Select Points			🔅 × 🥸
	9 :::	-0-0	0 0 0 0 0 0	🔣 🗹 🗌
	$\stackrel{U\rightarrow}{{_{\rightarrow\rightarrow}}} \stackrel{U\rightarrow}{{_{\rightarrow\rightarrow}}} \stackrel{U\rightarrow}{{_{\rightarrow\rightarrow}}}$	†0-0 V0-0	†13 Voo	Select V




Exercise 4—Trimmed NURBS

1 Open the model Trimmed NURBS.3dm.

This surface has been trimmed out of a much larger surface. The underlying four sided surface data is still available after a surface has been trimmed, but it is limited by the trim curves (edges) on the surface.

2 Select the surface and turn on the control points, then drag a few control points.



Control points can be manipulated on the trimmed part of the surface or the rest of the surface, but notice that the trimming edges move around as the underlying surface changes. The trim curve always stays on the surface.


3 Use the **Undo** command to undo the point manipulation.


To remove the trims from a surface

- 1 Start the **Untrim** (*Surface menu: Surface Edit Tools > Untrim*) command.
- **2** Select the single edge of the trimmed surface.

The original underlying surface appears and the trim boundary disappears.

3 Use the **Undo** command to return to the previous trimmed surface.







To detach a trimming curve from a surface

- 1 Start the **Untrim** command with the **KeepTrimObjects** option set to **Yes** (*Surface menu: Surface Edit Tools > Detach Trim*).
- **2** Select the edge of the surface.

The original underlying surface appears. The boundary edges are converted to curves, which are no longer associated with the surface.

3 Undo, to return to the previous trimmed surface.






To shrink a trimmed surface

- **1** Start the **ShrinkTrimmedSrf** command (*Surface menu: Surface Edit Tools > Shrink Trimmed Surface*).
- 2 Select the surface and press **Enter** to end the command.

The underlying untrimmed surface is replaced by a one with a smaller range that matches the old surface exactly in that range. You will see no visible change in the trimmed surface. Only the underlying untrimmed surface is altered.



Curve creation and continuity 4

We will begin this part of the course by reviewing a few concepts and techniques related to NURBS curves that will simplify the learning process during the rest of the class. Curve building techniques have a significant effect on the surfaces that you build from them.

Curve degree


The degree of a curve refers to the highest degree polynomial in the equation for the curve. In practice, it relates to the extent of the influence a single control point has over the length of the curve.

For higher degree curves, a control point has less local influence and a more broad influence over the entire length of the curve. It also has higher internal continuity.


In the example below, the five curves have their control points at the same six points. Each curve has a different degree. The degree can be set with the Degree option in the **Curve** command.

Exercise 5—Curve degree

- Open the model Curve 1 Degree.3dm.
- Use the **Curve** command (Curve 2 *menu: Free-Form > Control Points)* with **Degree** set to **1**, using the Point object snap to snap to each of the points.
- 3 Repeat the **Curve** command with Degree set to 2.




Degree 1: Control points on curveno bending.




Degree 2: Control points off curve.


- Repeat the Curve command with 4 Degree set to 3.
- Repeat the Curve command with Degree set to 4.

Repeat the **Curve** command with **Degree** set to **5**.





Degree 4



Degree 5

5


6

Analyzing the curvature of a curve


 Use the CurvatureGraph command (Analyze menu: Curve > Curvature Graph On) to turn on the curvature graph for one of the curves. Set the DisplayScale to a number that shows the graph as in the illustration—between 110-120 should work well.


The graph indicates the curvature on the curve this is the inverse of the radius of curvature. The smaller the radius of curvature at any point on the curve, the larger the amount of curvature.

 Curvature Graph 🛛 🗙
Display scale 120
Density
Curve hair
Surface hair
Add Objects Remove Objects



- 2 Turn on the control points for the curve you have graphed and view the curvature graph as you drag some control points. Note the change in the curvature hairs as you move points.
- 3 Repeat this process for each of the curves. You can use the Curvature Graph dialog buttons to remove or add objects from the graph display.





Note:

- **Degree 1** curves have no curvature and no graph displays.
- **Degree 2** curves are internally continuous for tangency—the steps in the graph indicate this condition. Note that only the graph is stepped not the curve.
- **Degree 3** curves have continuous curvature—the graph will not show steps but may show hard peaks and valleys. Again, the curve is not kinked at these places—the graph shows an abrupt but not discontinuous change in curvature.
- In higher degree curves, higher levels of continuity are possible.
- For example, a **Degree 4** curve is continuous in the rate of change of curvature—the graph doesn't show any hard peaks.
- A **Degree 5** curve is continuous in the rate of change of the rate of change of curvature. The graph doesn't show any particular features for higher degree curves but it will tend to be smooth.
- Changing the degree of the curve to a higher degree with the ChangeDegree command with Deformable=No will not improve the internal continuity, but lowering the degree will adversely affect the continuity.
- Rebuilding a curve with the **Rebuild** command will change the internal continuity.


Curve and surface continuity


Since creating a good surface so often depends upon the quality and continuity of the input curves, it is worthwhile clarifying the concept of continuity among curves.

For most curve building and surface building purposes we can talk about four useful levels of continuity:

Not continuous

The curves or surfaces do not meet at their end points or edges. Where there is no continuity, the objects cannot be joined.







Positional continuity (G0)

Curves meet at their end points, surfaces meet at their edges.

Positional continuity means that there is a kink at the point where two curves meet. The curves can be joined in Rhino into a single curve but there will be a kink and the curve can still be exploded into at least two sub-curves.







Similarly two surfaces may meet along a common edge but will show a kink or seam, a hard line between the surfaces. For practical purposes, only the end points of a curve or the last rows of points along the edges of two untrimmed surfaces need to match to determine G0 continuity.

Tangency continuity (G1)

Curves or surfaces meet and the directions of the tangents at the endpoints or edges is the same. You should not see a crease or a sharp edge.

Tangency is the direction of a curve at any particular point along the curve







Where two curves meet at their endpoints the tangency condition between them is determined by the direction in which the curves are each heading exactly at their endpoints. If the directions are collinear, then the curves are considered tangent. There is no hard corner or kink where the two curves meet. This tangency direction is controlled by the direction of the line between the end control point and the next control point on a curve.

In order for two curves to be tangent to one another, their endpoints must be coincident (G0) and the second control point on each curve must lie on a line passing through the curve endpoints. A total of four control points, two from each curve, must lie on this imaginary line.

Curvature continuity (G2)

Curves or surfaces meet, their tangent directions are the same and the radius of curvature is the same for each at the endpoint.





Curvature Continuity includes the above G0 and G1 conditions and adds the further requirement that the radius of curvature be the same at the common endpoints of the two curves. Curvature continuity is the smoothest condition over which the user has any direct control, although smoother relationships are possible.

For example, G3 continuity means that not only are the conditions for G2 continuity met, but also that the rate of change of the curvature is the same on both curves or surfaces at the common end points or edges.

G4 means that the rate of change of the rate of change is the same. Rhino has tools to build such curves and surfaces, but fewer tools for checking and verifying such continuity than for G0-G2.

G5+ has no visible evidence of more continuity.

Curve continuity and curvature graph


Rhino has two analysis commands that will help illustrate the difference between curvature and tangency. In the following exercise, we will use the **CurvatureGraph** and the **Curvature** commands to gain a better understanding of tangent and curvature continuity.

To show continuity with a curvature graph


1 Open the model Curvature_Tangency.3dm.


There are five sets of curves, divided into three groups.

One group has positional (G0) continuity at their common ends.





Group (a-c) has tangency (G1) continuity at their common ends.





Group (b- d) has curvature (G2) continuity at their common endpoints.





2 Use Ctrl+A to select all of the curves. Then, turn on the Curvature Graph (Analyze menu: Curve > Curvature Graph On) for the curves. Set the Display Scale in the floating dialog to 100 for the moment. Change the scale if you cannot see the curvature hair.

The depth of the graph at this setting shows, in model units, the amount of curvature in the curve.

3 First, notice the top sets of curves (**a**-**b**). These have two straight lines and a curve in between.


The lines do not show a curvature graph—they have no curvature.



The image just to the right shows what is meant by the curvature not being continuous—the sudden jump in the curvature graph indicates a discontinuity in curvature.

Nevertheless the line-arc-line is smoothly connected. The arc picks up the exact *direction* of one line and then the next line takes off at the exact direction of the arc at its end.

On the other hand, the G2 curves (b) again show no curvature on the lines, but the curve joining the two straights is different from the G1 case. This curve shows a graph that starts out at zero—it comes to a point at the end of the curve, then increases rapidly but smoothly, then tails off again to zero at the other end where it meets the other straight. It is not a constant curvature curve and thus not a constant radius curve. The graph does not have a sudden jump in the curvature graph; it goes smoothly from zero to its maximum.



The G1 middle curve is an arc. It shows a constant curvature graph as expected because the curvature of an arc never changes, just as the radius never changes.

G2

For the G2 middle curve, the graph ramps up from zero to some maximum height along a curve and then slopes back to zero, matching the zero curvature again on the other straight line.

Thus, there is no discontinuity in curvature from the end of the straight line to end of the curve. The curve starts and ends at zero curvature just like the lines have. So, the G2 case not only is the direction of the curves the same at the endpoints, but the curvature is the same there as well—there is no jump in curvature and the curves are considered G2 or curvature continuous.

4 Next, look at the c and d curves.

These are also G1 and G2 but are not straight lines so the graph shows up on all of the curves.

Again, the G1 set shows a step up or down in the graph at the common endpoints of the curves. This time the curve is not a constant arc—the graph shows that it increases in curvature out towards the middle.

On G2 curves, the graph for the middle curve shows the same height as the adjacent curves at the common endpoints—there are no abrupt steps in the graph.

The outer curve on the graph from one curve stays connected to the graph of the adjacent curve.

To show continuity with a curvature circle

1 Start the **Curvature** command (*Analyze menu: Curvature circle*) and select the middle curve in set **c**.

The circle that appears on the curve indicates the radius of curvature at that location—the circle that would result from the center and radius measured at that point on the curve.

2 Drag the circle along the curve.

Notice that where the circle is the smallest, the graph shows the largest amount of curvature. The curvature is the inverse of the radius at any point.

3 Click the MarkCurvature option on the command-line.

Slide the circle, snap to an endpoint of the curve, and click to place a curvature circle.


4 Stop the command and restart it for the other curve sharing the endpoint just picked.


Place a circle on this endpoint as well.


The two circles have greatly different radii. Again, this indicates a discontinuity in curvature. These curves are G1 / tangent only, so the curvature at the tangent meeting point is different for the two curves, and that is where the curvature graph would take a jump.


5 Repeat the same procedure to get circles at the ends of the curves in set **d**.

Notice that this time the circles from each curve at the common endpoint are the same radius. These curves are curvature continuous.









6 Lastly, turn on the control points for the middle curves in c and d. Select the "middle" control point on either curve and move it around.

Notice that while the curvature graph changes greatly, the continuity at each end with the adjacent curves is not affected.

The G1 curve graphs stay stepped, though, the size of the step changes.

The G2 curve graphs stay connected, although there is a peak that forms there.

7 Look at the graphs for the **G0** curves.

Notice that there is a gap in the graph—this indicates that there is only G0 or positional continuity.

The curvature circles, on the common endpoints of these two curves, are not only different radii, but they are also not tangent they cross each other. There is a discontinuity in direction at the ends.

Exercise 6—Geometric continuity

1 Open the model **Curve Continuity.3dm**.

The two curves are clearly not tangent. Verify this with the continuity checking command **GCon**.


- **2** Start the **GCon** command (*Analyze menu: Curve > Geometric Continuity*).
- **3** Click near the common ends (1 and 2) of each curve.


Rhino displays a message on the command-line indicating the curves are out of tolerance—the endpoints of the two curves are not close enough to each other to be considered the same.


Curve end difference = 0.030 millimeters Radius of curvature difference = 126.531 millimeters Curvature direction difference in degrees = 10.277 Tangent difference in degrees = 10.277 Curve ends are out of tolerance.


Often, imported curves are often "out of tolerance" and need this kind of repair for accurate modeling.


To make the curves have position continuity

















- 1 Turn on the control points for both curves and zoom in on the common ends.
- 2 Turn on the **Point** object snap and drag one of the endpoints onto the other.
- 3 Repeat the GCon command.

The command-line message is different now:

Curve end difference = 0.000 millimeters Radius of curvature difference = 126.771 millimeters Curvature direction difference in degrees = 10.307Tangent difference in degrees = 10.307Curves are G0.

4 Undo the previous operation.

To make the curves have position continuity using Match

Rhino has a tool for making this adjustment automatically in the **Match** command.


- 1 To try this, start the **Match** command (*Curve menu: Curve Edit Tools* > *Match*).
- 2 Pick near the common end of one of the curves.
- **3** Pick near the common end of the other curve.


By default, the curve you pick first will be the one that is modified to match the other curve. You can make both curves change to an average of the two by checking the **Average Curves** option in the following dialog.

- 4 In the Match Curve dialog, for Continuity check Position, for Preserve other end check Position, check Average Curves.
- 5 Repeat the GCon command.


The command-line message indicates:

Curve end difference = 0.000 millimeters Radius of curvature difference = 126.708 millimeters Curvature direction difference in degrees = 10.265 Tangent difference in degrees = 10.265 Curves are G0.





oin



Exercise 7—Tangent continuity

It is possible to establish a tangency (G1) condition between two curves by aligning the control points in a particular way. The endpoints at one end of the curves must be coincident and these points in addition to the next point on each curve must fall in a line with each other. This can be done automatically with the **Match** command, although it is also easy to do by moving the control points using the normal Rhino transform commands.

We will use Move, SetPt, Rotate, Zoom Target, PointsOn (F10), PointsOff (F11) commands and the object snaps End, Point, Along, Between and the Tab lock to move the points in various ways to achieve tangency.

First, we will create some aliases that will be used in this exercise.

To make Along and Between aliases

Along and **Between** are one-time object snaps that are available in the **Tools** menu under **Object snaps**. They can be used only after a command has been started and apply to only one pick. We will create new aliases for these object snaps.

- 1 In the **Rhino Options** dialog on the **Aliases** page, click the **New** button
- 2 In the Alias column, type a.

In the Command macro column, type _Along.

- 3 In the **Alias** column type **b**.
- 4 In the Command macro column, type _Between.
- 5 Close the Rhino Options dialog.

Alias:	Command macro:
а	Along
AdvancedDisplay	! _ OptionsPage _ AdvancedSettings
b	Between


To change the continuity by adjusting control points using Rotate and the Tab direction lock


The Tab direction lock locks the movement of the cursor when the **Tab** key is pressed. It can be used for moving objects, dragging, or curve and line creation.

To activate Tab direction lock press and release the **Tab** when Rhino is asking for a location in space. The cursor will be constrained to a line between its location in space at the time the **Tab** key is pressed and the location in space of the last clicked point.

When the direction is locked, it can be released with another press and release of the **Tab**, and a new, corrected direction set with yet another **Tab** press.

- **1** Turn on the control points for both curves.
- **2** Select the control point (1) second from the end of one of the curves.
- **3** Start the **Rotate** command (*Transform menu: Rotate*).
- 4 Using the **Point** object snap, select the common endpoints (2) of the two curves for the **Center** of rotation.
- **5** For the **First reference point**, snap to the current location of the selected control point.






- For the Second reference point, make sure 6 the point object snap is still active. Hover the cursor, but do not click, over the second point (3) on the other curve. While the **Point** object snap flag is visible on screen, indicating the cursor is locked onto the control point, press and release the **Tab** key. Do not click with the mouse.
- Bring the cursor back over to the other curve--7 notice that the position is constrained to a line between the center of rotation and the second point on the second curve; that is, the location of the cursor when you hit the **Tab** key. You can now click the mouse on the side opposite the second curve.


During rotation, the Tab direction lock knows to make the line from the center and not from the first reference point.

The rotation endpoint will be exactly in line with the center of rotation and the second point on the second curve.


To change the continuity by adjusting control points using the Between object snap

- Use the **OneLayerOn** command to turn on only 1 the **3D Curves** layer.
- 2 Check the continuity of the curves with the GCon command.
- 3 Turn on the control points for both curves.
- 4 Window select the common endpoints of both curves (1).
- 5 Use the **Move** command (*Transform menu*: Move) to move the points.
- 6 For the **Point to move from** snap to the same point (1).
- 7 For the **Point to move to**, type **b** and press Enter to use the Between object snap.
- For the First point, snap to the second 8 point (2) on one curve.
- 9 For the Second point, snap to the second point (3) on the other curve.










÷Π


The common points are moved in-between the two second points, aligning the four points.



To change the continuity by adjusting control points using the Along object snap

- **1 Undo** the previous operation.
- **2** Select the second point (3) on the curve on the right.
- **3** Use the **Move** command (*Transform menu: Move*) to move the point.
- 4 For the **Point to move from**, snap to the selected point.





- 5 For the **Point to move to**, type **A** and press **Enter** to use the **Along** object snap.
- 6 For the **Start of tracking line**, snap to the second point (2) on the other curve.
- **7** For the **End of tracking line**, snap to the common points (1).

The point tracks along a line that goes through the two points, aligning the four points.







Click to place the point. Check the continuity.

8

9


To edit the curves without losing tangency continuity

With the Tab technique, we can adjust the meeting point of the curves, or the shape of either curve near the meeting point, without losing the G1 continuity.

1 Window select the common endpoints or select the second point on either curve.

Turn on the **Point** object snap and drag the point(s) to the next one of the four critical points.

2 When the **Point** object snap flag shows on the screen, use the **Tab** direction lock by pressing and releasing the **Tab** key without releasing the mouse button.



- 3 Drag the point(s) and the tangency is maintained since the drag direction is constrained to the Tab direction lock line.
- **4** Release the left mouse button at any point to place the point(s).

Note: To maintain G1 continuity make sure that any point manipulation of the critical four points takes place along the line on which they all fall.

Once you have G1 continuity you can still edit the curves near their ends without losing continuity, using the Tab direction lock.

This technique only works after tangency has been established.

Exercise 8-Curvature continuity


Adjusting points to establish curvature continuity is not as straightforward as for tangency. Curvature at the end of a curve is determined by the position of the last three points on the curve, and their relationships to one another are not as straightforward as it is for tangency.

To establish curvature or G2 continuity, the Match command is the only practical way in most cases.

To match the curves

1 Use the Match command (Curve menu: Curve Edit Tools > Match) to match the magenta (1) curve to the red (2) curve. Set Continuity to Curvature, Preserve other end to Curvature, and uncheck Average curves.


When you use Match with Curvature checked on these particular curves, the third point on the curve to be changed is constrained to a position calculated by Rhino to establish the desired continuity.



Ð

The curve being changed is significantly altered in shape.

Moving the third point by hand will break the G2 continuity at the ends, though G1 will be maintained



Advanced techniques for controlling continuity


There are two additional methods to edit curves while maintaining continuity in Rhino. (1) The **EndBulge** command constrains points at the end to maintain continuity with the adjacent curve. (2) Adding knots will allow more flexibility when changing the curve's shape.

To edit the curve with end bulge

- **1 Right-click** on the **Copy** button to make a duplicate of the magenta curve and then Lock it.
- 2 Start the **EndBulge** command (*Edit menu: Adjust End Bulge*).
- **3** Select the magenta curve.


Notice that there are more points displayed than were on the original curve.

The **EndBulge** command adds more control points to the curve if the curve has less than the required control point count.



4 Select the third point, drag it, and click to place the point, press **Enter** to end the command.

If the endpoint of the curve has G2 continuity with another curve, the G2 continuity will be preserved, because **EndBulge** preserves the curvature at the endpoint of the curve.



Note: Adjusting control points will work to match curvature only in the simple case of matching to a straight line.


To add a knot

Adding a knot or two to the curve will put more points near the end so that the third point can be nearer the end. Knots are added to curves and surfaces with the **InsertKnot** command.

- **1** Undo your previous adjustments.
- 2 Start the InsertKnot command (Edit menu: Control Points > Insert Knot).
- **3** Select the magenta curve.
- **4** Pick a location on the curve to add a knot in between the first two knot markers.

In general, a curve or surface will tend to behave better in point editing if new knots are placed midway between existing knots, thus maintaining a uniform distribution.

Adding knots also results in added control points.



Knots and control points are not the same thing and the new control points will not be added at exactly the new knot location.

The **Automatic** option automatically inserts a new knot in each span exactly half way between existing knots.


If you only want to place knots in some of the spans, you should place these individually by clicking on the desired locations along the curve.

Existing knots are highlighted in white.



5 Match the curves after inserting a knot into the magenta curve.

Inserting knots closer to the end of curves will change how much **Match** changes the curve.





5 Surface continuity

The continuity characteristics for curves can also be applied to surfaces. Instead of dealing with the endpoint, second, and third points, entire rows of points at the edge, and the next two positions away from the edge are involved. The tools for checking continuity between surfaces are different from the simple **GCon** command.

Analyzing surface continuity

Rhino takes advantage of the OpenGL display capability to create false color displays for checking curvature and continuity within and between surfaces. These tools are located in the **Analyze** menu, under **Surface**. The tool, which most directly measures G0-G2 continuity between surfaces, is the **Zebra** command. Zebra analysis simulates reflection of a striped background on the surface.

Note: An OpenGL graphics accelerator card is not necessary to use these tools, although they may work faster with OpenGL acceleration.

Matching surface continuity

The command used to establish G0, G1 or G2 continuity between surfaces is the MatchSrf command.

Match surface options

Option	Description
Average surfaces	Both surfaces are modified to an intermediate shape.
Refine match	Determines if the match results should be tested for accuracy and refined so that the faces match to a specified tolerance.
Match edges by closest points	The surface being changed is aligned to the edge it is being matched to by pulling each edge point to the closest point on the other edge.
Preserve other end	If the surface does not have enough points its degree is raised (up to a maximum of 5), until there are enough points.

Isocurve direction adjustment

Specifies the way the parameterization of the matched surfaces is determined.

Option	Description
Automatic	Evaluates the target edge, then uses Match target isocurve direction if it is an untrimmed edge or Make perpendicular to target edge if it is a trimmed edge.
Preserve isocurve direction	As closely as possible, keeps the existing isocurve directions the same as they were in the surface before matching.
Match target isocurve direction	Makes the isocurves of the surface that is being adjusted parallel to those of the surface it matches.
Make perpendicular to target edge	Makes the isocurves of the surface that is being adjusted perpendicular to the edge being matched.

Exercise 9—Surface continuity and MatchSrf


The **MatchSrf** command takes surface edges as input and modifies one or both of the surfaces. You need to tell the command exactly which edge to change and then which edge to match to the target surface. We will match the white surface's edge to the green one first. Both the edge to change and the edge to match to are untrimmed on these surfaces.

While **MatchSrf** is generally used to adjust surfaces that are fairly close to being at the desired continuity, this example is somewhat exaggerated in order to clearly show the functionality and options.

- 1 Open the model Surface Continuity.3dm.
- 2 Start the **MatchSrf** command (*Surface menu: Surface Edit Tools* > *Match*).
- **3** Select the edge of the white surface on the edge nearest the green surface.
- **4** Select the edge of the green surface near the same location as the selection point on the white surface edge and press **Enter**.
- 5 In the Match Surface dialog, choose Position as the desired Continuity, choose None for Preserve other end, uncheck Refine match, and choose Automatic for Isocurve direction adjustment.

Make sure all other check boxes are unchecked.


A shaded preview is automatically generated so you can see what the result will be like.



🦢 Match Surface				
Continuity Postion Tangeney Curvature				
Preserve other end -				
 Average surfaces Match edges by closest points Refine match 				
Distance: Tanceney:	0.001	unita degraca		
Curvature:	0.05	percent		
Socurve direction adjustment Automatic Preserve isocurve direction Match target isocurve direction Nake perpendicular to target edge OK Cancel				

6 Click OK.

The edge of the white surface is pulled over to match the edge of the green one.




To check the continuity with Zebra analysis

 Check the surfaces with **Zebra** analysis tool (Analyze menu: Surface > Zebra).

This command relies on an approximation of the surface for its display information.

2 By default, the mesh generated by Zebra may be too coarse to get a good analysis of the surfaces. If the display shows very angular stripes rather than smooth stripes on each surface, click the Adjust mesh button on the Zebra dialog.



In general, the analysis mesh should be much finer than the normal shade and render mesh meshes.

It is a good habit to set these meshes the first time you use a surface analysis display mode in a model. This setting is then saved in the file.

3 Use the detailed controls to set mesh parameters.

For this type of mesh, it is often easiest to zero out (disable) the Maximum angle setting and rely entirely on the Minimum initial grid quads setting. This number can be quite high but may depend upon the geometry involved.


Polygon Mesh Detailed Options		
Density:	0.5	
Maximum angle:	0.0	
Maximum aspect ratio:	0.0	
Minimum edge length:	0.0001	
Maximum edge length:	0.0	
Maximum distance, edge to surface.	0.0	
Minimum initial grid quads:	5000	
Refine mesh Jagged seams Pack Textures Simple planes OK Cancel Help Preview Simple Controls		z y

In this example, a setting here of 5000 to 10000 will generate a very fine and accurate mesh.

4 The analysis can be further improved by joining the surfaces to be tested. **Join** the two surfaces.

This will force a refinement of the mesh along the joined edge and help the Zebra stripes act more consistently.

There is no particular correlation between the stripes on one surface and the other except that they touch, indicating G0 continuity.



To match the surface to tangency


 Use the MatchSrf command (Surface menu: Surface Edit Tools > Match) again with the Tangency option for Continuity.


When you pick the edge to match you will get direction arrows that indicate which surface edge is being selected. The surface that the direction arrows are pointing toward is the surface whose edge is selected.


2 Check the surfaces with **Zebra** analysis. **Rotate** the view to view along the seam.

The ends of the stripes on each surface meet the ends on the other cleanly, though at an angle.

This indicates G1 continuity.








To match the surface to curvature


1 Use the **MatchSrf** command (*Surface menu: Surface Edit Tools > Match*) with the **Curvature** option.



2 Check the surfaces with **Zebra** analysis.

The stripes now align themselves smoothly across the seam. Each stripe connects smoothly to the counterpart on the other surface.

This indicates Curvature (G2) continuity.



Note: Doing these operations one after the other may yield different results than going straight to **Curvature** without first using **Position**. This is because each operation changes the surface near the edge, so the next operation has a different starting surface.

Add knots to control surface matching

As in matching curves, **MatchSrf** will sometimes distort the surfaces more than is acceptable in order to attain the desired continuity. We will add knots to surfaces to limit the influence of the **MatchSrf** operation. The new second and third rows of points will be closer to the edge of the surface.

Surfaces can also be adjusted with the **EndBulge** command.

To add a knot to a surface

- **1 Undo** the previous operation.
- **2** Use the **InsertKnot** command (*Edit menu: Control Points > Insert Knot*) to insert a row of knots near the end of the white surface.

When this command is used on a surface, it has more options. You can choose to insert a row of knots in the U-direction, the V-direction, or both. Choose Symmetrical to add knots at opposite ends of a surface.

3 Use **MatchSrf** to curvature match the surface to the other.


Notice that the new matched surface is different from the old one.

To adjust the surface using end bulge

The **EndBulge** command lets you edit the shape of a surface without changing the tangent direction and the curvature at the edge of the surface. This is useful when you need to alter the shape of a surface that has been matched to another surface.

EndBulge allows you to move control points at a specified location on the surface. These points are constrained along a path that keeps the direction and curvature from changing.

The surface can be adjusted equally along the entire selected edge or along a section of the edge. In the latter case, the adjustment takes place at the specified point and tapers out to zero at either end of the range. Either the start or endpoint of the range can be coincident with the point to adjust, thus forcing the range to be entirely to one side of the adjustment point.



- Start the **EndBulge** command (*Edit menu: Adjust End Bulge*). 1
- 2 For the **surface edge to adjust**, pick the edge of the surface on the right.
- For the **Point to edit**, pick a point on the edge at which the actual 3 adjustment will be controlled.

You can use object snaps and reference geometry to select a point with precision.

- For the Start of region to edit, pick 4 a point along the common edges to define the region to be adjusted.
- For the **End of region to edit**, pick 5 another point to define the region to be adjusted.

To select a range at this point, slide the cursor along the edge and click at the beginning and endpoints of the range. If the whole edge is to be adjusted equally, simply press Enter.


6 For the **Point to adjust**, select one of the points that are displayed.

Rhino shows three points, of which you are allowed to manipulate only two. When you move the second point, Rhino also moves the third point that is not being directly manipulated in order to maintain the continuity. If you move the third point it won't change the second point

Drag the point and click to adjust the 7 surface.


If maintaining the G2 curvature-matching condition at the edge is not needed, use the Continuity=Tangency option to turn off one of the two points available for editing. Only G1 will be preserved.


Press Enter to end the command. 8





OnCrv





SURFACE CONTINUITY

Robert McNeel & Associates

To match an untrimmed surface to a trimmed surface

 Start the MatchSrf command (Surface menu: Surface Edit Tools > Match).

CHAPTER 5

3

4

5

edge.

2 Select the edge of the green surface on the edge nearest the blue surface.

The edge will not select and you will see the following message on the command-line:

Edge must be on the edge of a surface (not a trimmed edge). Select untrimmed surface edge to change (MultipleMatches).

In the Match Surface dialog,

Preserve other end, check

and choose Automatic for

A preview is automatically

only extends as far as the

closest point from the original

the result will be like.

are unchecked.

surface.

choose **Curvature** as the desired **Continuity**, choose **None** for

Match edges by closest points,


Isocurve direction adjustment.


Make sure all other check boxes


generated so you can see what

Notice that the blue surface does

not include the entire untrimmed edge of the green surface. It









Select the trimmed edge of the green surface near the same location as the selection point on the blue surface

Instead, select the untrimmed edge of the blue surface on the edge nearest the green surface.



- 6 In the Match Surface dialog, uncheck Match edges by closest points, and check Refine match.
- 7 Change the **Isocurve direction** adjustment and the **Preserve** other end options to see what happens to the matched surface. When finished press **OK**.

Match Surface		x	
Continuity			
Position			
Tangency			
Ourvature			
Preserve other end -			
None			
Position			
Tangency			
Curvature			
Average surfaces			
Match edges by d	osest points		
🔽 <u>R</u> efine match			
D <u>i</u> stance:	0.001	units	
Tangency:	1.0	degrees	
<u>C</u> urvature:	0.05	percent	
Isocurve direction adjustment Image: Automatic Image: Preserve isocurve direction Image: Match target isocurve direction			
	ок	Cancel	



Surfacing commands that pay attention to continuity

Rhino has several commands that can build surfaces using the edges of other surfaces as input curves. They can build the surfaces with G1 or G2 continuity to those neighboring surfaces. The commands are:

- NetworkSrf
- Sweep2
- Patch (G1 only)
- Loft (G1 only)
- BlendSrf (G1 to G4)

The following exercises will provide a quick overview of these commands.

Exercise 10-Continuity commands

To create a surface from a network of curves


1 Open the model Continuity Commands.3dm.

On the **Surfaces** layer, two joined surfaces have been trimmed leaving a gap. This gap needs to be closed up with continuity to the surrounding surfaces.

2 Turn on the **Network** layer, if it is not already on, and make it current.

Several curves already in place define the required cross sections of the surface.

3 Use the **NetworkSrf** command (*Surface menu: Curve Network*) to close the hole with an untrimmed surface using the curves and the edges of the surfaces as input curves.



4 For the **Select curves in network**, select the four edges that border the opening and the four curves inside the opening and press **Enter**.

Note that there is a maximum of four edge curves as input. You can also specify the tolerances or maximum deviation of the surface from the input curves.

By default, the edge tolerances are the same as the model's Absolute Tolerance setting. The interior curves' tolerance is set 10 times looser than that by default.

5 In the Surface From Curve Network dialog, choose Curvature continuity for all the edges, and click OK.


The surface that is created has curvature continuity on all four edges.


6 Check the resulting surface with **Zebra** analysis.


To make the surface with a two-rail sweep


- 1 Use the **OneLayerOn** command to open the **Surfaces** layer by itself again, and then click in the layers panel of the status bar, and select the **Sweep2** layer.
- 2 Start the **Sweep2** command (*Surface menu: Sweep 2 Rails*) and select the long surface edges as the rails.
- **3** Select one short edge, the crosssection curves, and the other short edge as profiles.
- 4 Choose **Curvature** for both **Rail curve** options.


Since the rails are surface edges, the display labels the edges, and the **Sweep 2 Rails Options** dialog gives the option of maintaining continuity at these edges.












SURFACE CONTINUITY



- 5 Click OK.
- 6 Check the resulting untrimmed surface with **Zebra** analysis.

Sweep 2 Rail Options
Cross-section curve options
Do not simplify
C Rebuild with 5 control points
Refit within 0.01
Preserve first shape
Preserve last shape
🔲 Maintain height
Rai curve options
Fasition 🔘 🔘
Tangency 🔘 🔘
Curvature 🙆 🙆
Cbsed sweep Add Sash
OK Cancel Preview Help



To make a patch surface

The **Patch** command builds a trimmed surface, if the bounding curves form a closed loop. Patch can match continuity to G1 if the bounding curves are edges. The **Patch** command:

- Can use unlimited curves or points for input
- Ignores noise of many control points
- Is good for scanned data
- Is good for reverse engineering
- 1 Turn on the **Surfaces**, and **Patch** layers.

Turn all other layers off.

- 2 Start the **Patch** command (*Surface menu: Patch*).
- **3** Select the edge curves and the interior curves, and then press **Enter**.
- 4 In the **Patch Surface Options** dialog, set the following options:

Set Sample point spacing to 1.0.

Set Stiffness to 1.

Set Surface U and V spans to 10.

Check Adjust tangency and Automatic trim, and then click OK.

	Patch Surface Option	ns X
	General	
	Sample point spacing:	1.0
	Surface U spans:	10 🚖
	Surface V spans:	10 🚔
	Stiffness:	1
	Adjust tangency	
	Automatic trim	
The nominal 3-D distance	Starting surface	
between points sampled ' / / from input curves / / ,	Select Starting Surface	:e
	Starting surface pull:	1
Rows and columns /	Preserve edges	
The bigger the number, the / /	✓ Delete input	
"stiffer" and more / /	OK Cancel	Preview
rectangular and planar the resulting surface will be		

Takes the structure of a selected surface

5 Join the surfaces.


6 Use the **ShowEdges** command (*Analyze menu: Edge tools > Show Edges*) to display naked edges.

If there are naked edges between the new patch surface and the existing polysurface the settings may need to be refined.

7 Check the results with **Zebra** analysis.



Edge Analysis




Exercise 11—Patch options

To make a patch from an edge and points

Patch can use point objects as well as curves and surface edges as input. This exercise will use point and edge inputs to demonstrate how the **Stiffness** setting works.

- 1 Open the model Patch Options.3dm.
- 2 Start the **Patch** command *(Surface menu: Patch)* and select the two point objects and the top edge of the surface as input.
- 3 Check Adjust tangency and Automatic trim, set the Surface spans to 10 in each direction.
- **4** To get a good view of the two point objects, make the **Front** viewport the active viewport and set it to a **wireframe** or **ghosted** view.
- 5 Set the **Stiffness** to **0.1** and click the **Preview** button.

With lower setting for stiffness, the surface fits through the points while maintaining tangency at the surface edge. This can show abrupt changes or wrinkles in the surface.



6 Set the **Stiffness** to **5** and click the **Preview** button again.


With higher stiffness settings, the patch surface is made stiffer and it may not pass through the input geometry. On the other hand, the surface is less apt to show abrupt changes or wrinkles, often making a smoother and better surface.


With very high stiffness numbers, the edges also may have a tendency to pull away from the intended input edges.


High stiffness number = the more rectangular and planar the resulting surface will be

Low stiffness number = the smoother (fairer) the resulting surface will be

More spans = greater density of control points







Exercise 12—Lofting


To make a lofted surface


The Loft command also has built in options for surface continuity.

1 Open the model Loft.3dm.

- 2 Start the **Loft** command (*Surface menu: Loft*).
- **3** Select the lower edge curve, the curve, then the upper edge curved, and press **Enter**.

When picking the curves, pick near the same end of each curve. This will insure that you do not get a twist in the surface.





- CHAPTER 5
- 4 In the Loft Options dialog, make sure the Style is set to Normal, and check the boxes for Match start tangent and Match end tangent are both checked. Press Enter when done.

The new surface has G1 continuity to the original surfaces.

5 Check the results with **Zebra** analysis.

Exercise 13—Blends

The next command that pays attention to continuity with adjoining surfaces is **BlendSrf**.

The three blends in this file will serve to illustrate the basic features of the **BlendSrf** command. The controls inside **BlendSrf** can be used to vary the character of the blended shape.

To make a surface blend (BlendSrf 1)

In BlendSrf 1, we will create the transition between the trunk lid and side surfaces of the car body.

😽 Loft Options

Normal

Closed loft

🐺 Match start tangent

Match end tangent

Cross-section curve options

Split at tangents

Align Curves...

Do not simplify

Bofil within

0K

Rebuild with 10

0.001

Cancel Preview

control points


Help

millimeters

Style

- 1 Open the model Blend.3dm.
- 2 Start the **BlendSrf** command (Surface menu: Blend Surface).
- **3** For the **Select segment for first edge**, select an edge along the red polysurface of the car body as marked in the file.

Notice that only one surface edge segment is selected initially, but we want to blend the full length of the gap between the white side surface and the red surfaces.



Normal


Loose

Tight


Uniform


Straight sections

Developable



BlendSrf 3





4 You can select the next edge segment by clicking on it, or by clicking on Next at the command-line.

The edge from the adjacent surface is selected.

- **5** Press **Enter** to finish the selection for the first edge.
- **6** For the **Select segment for second edge**, select the top edge of the white side surface at the end of the edge nearest your initial pick for the first edge. Press **Enter** to finish edge selection.

The **Adjust Surface Blend** dialog with several controls appears.

Adjust Surface Blend dialog

The sliders refer to the two default shape curves at the ends of the blend. Clicking the lock icon will force both sides of the blend to be adjusted at the same time.

A button allows the user to add shape curves. These new shape curves have adjustable handles on them exactly like the default shape curves.

Note that while it is sometimes useful to add shape curves, you should try to add as few as possible to achieve the shape you want. Interpolation among the shape curves is better if they are not too close together.

The radio buttons are for setting the continuity at each side of the blend; the edges are labeled 1 and 2 in the viewport.

There are check boxes for further options. These options will be discussed later in a separate exercise.


7 Uncheck the boxes for **Same height** and **Planar sections**. Make sure the continuity radio buttons are set to **Curvature**.


There is a check box to show a preview of the blend surface.


In the viewport, you will notice a default pair of shape curves with points. These points are called handles.


The number of handles available on the shape curves varies according to the settings in the dialog.

For example, if the continuity is set to **Curvature** (bold) for both shape curves 1 and 2, the curves will have six points (three for each curve).









the blend shape.

they are crowded near the apex of the shape curve.

change the shape of the blend.

Pressing **Alt** while adjusting handles rotates the handles and thus the direction of the shape curve relative to the edge.

Try adjusting the handles on the shape curves. For example, at the rear

of the car, make the blend sharper by moving the handles out so that

Moving the handles changes the shape on one side of one shape curve.


Pressing Shift while moving the handles forces both ends of the shape curve to be adjusted together. This is useful in maintaining symmetry on


The handles can be adjusted interactively on each shape curve to


Moving the handle at an end of a shape curve changes the location of the shape curve.


8

1











Using the sliders in the dialog changes all shape curves together.

The top slider modifies all the shape curves near the original edge #1, and the lower slider modifies all the shape curves near the original edge #2.






9 Adjust the settings in the dialog to the default value of 1.0, and then press OK to make the blend surface.

		_
e -	1.0]
	1.0	
	1 2	
Position	Add Shapes	
Tangency	Planar sections	
Curvature		
G3	Same height	
G4	Preview	
ок	Cancel Help	n İ
		J

💹 Adjust Surface Rlei



To make a surface blend (BlendSrf 2)

Next, we will blend between the roof rail and the side window.


- **1** Start the **BlendSrf** command (Surface menu: Blend Surface).
- 2 For the **Select segment for first edge**, select an edge along the rear window of the car as marked in the file.


Notice that only a small part of the edge is selected. Although the window is a single surface, the edges are split up into small pieces, making it inconvenient to select all of them.

3 Use the **All** option on the command-line to force chaining the edge fragments together.

Notice that the edge of the roof panel is also added, since the edges are contiguous and tangent to one another.

Press **Enter** to finish the first edge selection.







4 For the **Select segment for second edge**, select the edge at the top of the side window.

Notice the default shape curve shows an S-shape at the lower end of the blend area.

5 Press the *Alt* key while dragging the handles to align the blend curve in a more natural way.







To clean up the excess surfaces

To clean up the excess surfaces, we will trim the surfaces to each other. Since the intersections of the surfaces do not go all the way to the edges of all of the surfaces, we can make intersection curves, join them, and then extend them as needed on the surfaces.

- 1 Start the **IntersectTwoSets** command (*Curve menu: Curve from Objects* > *Intersection of Two Sets*).
- **2** As the **first set of objects to intersect**, select the side window and the roof blend surface you just completed. Press **Enter**.
- **3** As the **second set of objects to intersect with the first set**, select the first blend surface you made. Press **Enter**.
- **4 Join** the resulting curves.
- **5** Select the joined curve.
- **6** Start **ExtendCrvOnSrf** (*Curve menu: Extend Curve > Curve on Surface*) and choose the lower blend surface as the surface to extend on.
- **7 Trim** the bottom of the side window, the lower end of the roof rail blend, and the side blend inside the roof and glass area.







To make a surface blend (BlendSrf 3)

Lastly, we will blend between the wheel arch and the side of the car.

- 1 Start the **BlendSrf** command (Surface menu: Blend Surface).
- 2 For the **Segment for first edge**, select an edge of the wheel arch on the side of the car and Press **Enter**.
- **3** For the **Segment for second edge**, select the other edge of the wheel arch.





4 Change the continuity settings in the dialog so that one edge has **Position** continuity (G0) and the other has **Curvature** continuity (G2), and check the **Preview** checkbox.

This will allow you to have a hard edge at one of the edges.

5 Switch the continuity settings to the opposite edges to change the character of the blend.


You will probably have to rotate the shape curves at both sides of the wheel arch so that they align with the bottom edge of the side.

In this case, it is easier to do this in the **Front** viewport.

6 Press the *Alt* key while dragging the handles to align the blend curve to the bottom edge of the side.

7 Press **OK** in the dialog to make the blend surface.





🥪 Adjust Surface Blend

2

۲

1

00

0 0

 \bigcirc

00

Cancel

c

Position

Tangency

Curvature

OK

G3

G4

1.0

1.0


Help


Add Shapes


Planar sections


Same height

Preview











Exercise 14-Blend options

To make a surface blend

In the following exercise, we will first make a surface blend that creates a self-intersecting surface. Then we will use the surface blend options to correct the problem.


- 1 Open the model BlendSrf Options.3dm.
- 2 Start the **BlendSrf** command (*Surface menu: Blend Surface*) and select the deeply curved edges of the pair of surfaces marked **0**.






- 3 In the dialog, make sure **Same height** is **not checked**, and the bulge sliders are set to **1.0**, and then click **OK**.
- **Zoom** in on the surface you just created in the **Top** viewport.

Look closely at the middle of the blend surface in this view using a wireframe viewport. Notice the blend has forced the surface to be selfintersecting in the middle. The isocurves cross each other and make a pinch or crease here.





Surface blend options

To avoid self-intersecting or pinched surfaces when creating a blend you can **Adjust Blend Bulge** sliders, use **Same height shapes**, or use the **Planar sections** option.


In the following examples, we will look at each of these options.


To make a surface blend with options

1 Start the **BlendSrf** command and select the edges of the pair of surfaces marked **1**.

Adjust the sliders to make the bulge of the surface less than 1. A number between **0.2** and **0.3** seems to work best.

The profiles of the cross sections at each end of the blend as well as any you may add between will update to preview the bulge. Notice that the surface is not pinched in the middle.





Start the BlendSrf command and select the edges of the pair of surfaces marked 2. Change the Bulge to 0.5, but check Same height shapes.

The **Same height shapes** option overrides the tendency of the blend surface to get fatter or deeper according to how far apart the edges are. The height will be the same in the center as it is at each end. This also has the effect of making the sections of the blend push out less and therefore not cross each other out in the middle area.

- **3** Start the **BlendSrf** command and select the edges of the pair of surfaces marked **3**.
- 4 Pick the edges in the usual way.

Use the same bulge settings as the last pair of surfaces.

5 Check **Planar sections** in the dialog and uncheck **Same height**.

You are now asked to define which plane the sections of the surface should be parallel to. This is defined by clicking two points in any viewport.


6 Click once anywhere in the **Top** viewport **A** then with **Ortho** on, click again in the **Top** viewport **B** in the direction of the y-axis.


The resulting surface has its isocurves arranged parallel to the plane defined in the **Planar sections** portion of the command. The isocurves do not intersect in the middle of the surface since they are parallel the y-axis.

Fillets, blends and corners


In this exercise, we will discuss a variety of ways to fill holes and make transitions using the **NetworkSrf**, **Loft**, **Sweep1**, **Sweep2**, **Blend**, **Fillet** and **Patch** commands.


While Rhino has automated functions for making fillets, several situations take manual techniques. In this section, we will discuss making corners with different fillet radii, variable radius fillets and blends, and fillet transitions.





В





Exercise 15–Variable radius fillets


To make a corner fillet with three different radii:

- 1 Open the model Corner Fillet.3dm.
- 2 Use the **FilletEdge** command (Solid menu: Fillet Edge > Fillet Edge) to fillet edge (1) with a radius of **5mm**.

3 Use the FilletEdge command (Solid menu: Fillet Edge > Fillet Edge) to fillet edge (2) with a radius of 2mm, and edge (3) with a radius of 3mm, and the edge created by the previous fillet with a radius of 2.5mm.

Note: Change the value for **CurrentRadius** before selecting the next edge.


- Use the AddHandle option to add a
 2.0 radius handle at the end of edge
 2, and a 3.0 radius handle at the end of edge 3.
- **5 Preview** the results, and then press **Enter** to make the fillet.





2mm

3mm

√5mm








Exercise 16—Variable radius blends and chamfers


To make a variable radius blend


- 1 Open the model Sandal Sole.3dm.
- 2 Use the **BlendEdge** command (*Solid menu: Fillet Edge > Blend Edge*) to make a variable radius blend on the bottom of the sole. Start with a radius of **3mm**.
- **3** Use the **AddHandle** option to add additional radii around the bottom of the sole.

Add another 3mm radius to the front of the sole and then add a 7mm radius to the instep on both sides.

4 **Preview** the blend and adjust the handles as needed, and then press **Enter** to make the blend.









To make an edge chamfer

 Use the ChamferEdge command (Solid menu: Fillet Edge > Chamfer Edge) to make a 2mm chamfer around the top edge of the sole.

This command, like the **FilletEdge** command and the **BlendEdge** command, allow for the addition of handles with different values to create a variable distance chamfer.

 Preview the chamfer and make adjustments as needed, then press
 Enter to make the chamfer.






Exercise 17—Fillet with patch


To make a six-way fillet using a patch

- 1 Open the model Fillet Edge.3dm.
- 2 Use the FilletEdge command (Solid menu: Fillet Edge > Fillet Edge), with Radius=1, to fillet all the joined edges at the same time.

- **3** Use the **Patch** command *(Surface menu: Patch)* to fill in the opening at the center.
- **4** Select all six edges to define the patch.
- 5 In the Patch Options dialog, check Adjust Tangency and Automatic Trim. Change the Surface U and V Spans to 10, and the Stiffness to 2.



.000



Note: When the area to fill has more than four edges, the **Patch** command works better than the **NetworkSrf** command.

Exercise 18—Soft corners

There are several ways to approach making a soft box shape like the illustration below.

In this exercise, we explore two different methods to make the surfaces using the same underlying curves. Our design curves in this example are all tangent arcs.

The first method will use the curves directly. For second method, we will plan ahead and try to take into account the simple underlying shapes suggested by the design curves.

The two approaches are different, but one is not inherently better or contradictory to the other.



Robert McNeel & Associates

To make a rectangular shape with a curved top and soft corners (Part 1)

- **1 Open** the model **Soft Corners.3dm**.
- 2 Use the **Join** command (*Edit menu: Join*) to join the arcs that form the base rectangular shape.
- **3** Change to the **03 Sweeps** layer.
- 4 Use the **Sweep1** command (*Surface menu: Sweep 1 Rail*) to make the first surface.
- 5 In the Sweep 1 Rail Options dialog, check Closed sweep, then click OK.
- 6 Repeat the **Sweep1** command to make the second surface.
- 7 Pick the top edge of the surface you just created, then select the cross-sections in order, and press **Enter**.
- 8 In the Sweep 1 Rail Options dialog, change the Style to Align with surface, and then click OK.

This will insure tangent continuity with the first surface.

9 Use the **Patch** command (*Surface menu: Patch*) to fill in the opening at the center.

- **10** Select the surfaces you made.
- 11 Start the EMap command (Analyze menu: Surface > Environment map). Click Adjust mesh and refine the mesh in a similar way that you did for the Zebra surface analysis command. Choose the Arches.png or Space Needle.png from the drop-down list in the EMap Options dialog.
- **12** Tumble the view around.


Note the top surface has a pronounced X-shape in the pseudoreflections. The surface is not a clean interpretation of the original input curves- there is this extra distortion across the top surface. So, even though we have hit all the input curves, our surfaces are not necessarily very nice.


To make a rectangular shape with a curved top and soft corners (Part 2)


This time, we will look at the input curves and make some judgments about the best way to construct the surfaces.

One thing to keep in mind is that it is more important to make our primary surfaces have good curvature characteristics, and less important for transitional surfaces.


s.3dm. nenu: the












Primary surfaces will be the ones that define the overall shape. They tend to have relatively even curvature, and less curvature than the transitions. Transition surfaces, as the term implies, provide transitions between the primary shape surfaces. These surfaces tend to have higher curvature than the primary surfaces. Fillets and blends, for example, are generally added as transition surfaces.

In this example, we have the four side surfaces and the top surface as primary surfaces. We will add the corners afterwards as fillets. Since in our example the input curves are entirely made up of tangent arcs, we can define the side and top surfaces as revolved surfaces. This type of surface is very exact and simple.


- 1 Change to the **02 Separate Curves** layer and turn all the other layers off.
- 2 **Hide** the fillet curve at each corner, and the green cross-section curves.
- **3** Lock the red curves.
- 4 Use the Extend command (Curve menu: Extend Curve) with an ExtensionLength=10 to extend both ends of the cyan curves and the top of each black arc, press Enter to complete the command.




each black arc, press **Enter** to complete Each arc is extended at each end using the existing arc radius.

The goal is to extend the arcs enough that they will intersect one another as in the illustration. The exact amount is not critical.

- 5 Change to the **04 Surfaces** layer.
- 6 Use the **Revolve** command (*Surface menu: Revolve*) to make surfaces from two adjacent extended vertical curves.
- 7 Snap to the center of the base curve to place the **Start of revolve axis**.
- 8 Press Enter to use CPlane z-axis direction for the End of revolve axis.







If you are in a **Perspective** viewport, this option will automatically set the axis vertical and save the trouble of locating the second point.


 Pick the **Start angle** as shown in the image that is somewhere outside the span of the desired final surface. Make sure **Ortho** is not on at this stage.


The goal is to make a surface that is larger than will eventually be needed to make the box, so the exact starting and ending points are not critical.







2 Pick another point for **Revolution angle** to create the vertical surface.








4 Use the **MX** and **MY** aliases you made on the first day to **Mirror** each of the surfaces around the origin.




To make the top surface

In this example, we will make the top surface by revolving one of the top curves around the center of the other top curve. Since we will be working in the perspective view, it will be necessary to change the construction plane for that viewport.

- 1 Use the **Revolve** command (*Surface menu: Revolve*) to make the top surface from the longer top arc.
- 2 Snap to the center of the shorter top arc in the **Right** viewport to place the **Start of revolve axis**.





- **3** Press Enter to use CPlane z-axis direction for the End of revolve axis.
- 4 Pick the **Start angle** as shown.
- 5 Pick another point for **Revolution** angle to create the top surface.
- 6 Use the **CutPlane** command (*Surface menu: Plane* > *Cutting Plane*) to make a cutting plane at the origin in the z-axis.

- To make the surfaces into a solid
- 1 Use the **CreateSolid** command (*Solid menu: Create Solid*) to join and trim the surfaces into a closed solid.
- 2 Use the FilletEdge command (Solid menu: Fillet Edge > Fillet Edge) to fillet the edges. Set the CurrentRadius to 15, select the four vertical edges, and press Enter to make the fillets.
- 3 Repeat the FilletEdge command to fillet the top edges. Set the CurrentRadius to 10, select the eight top edges, and press Enter to make the fillets.

The resulting surface is very clean and smooth with no hard edges.


Note: You may notice a defect in a shaded viewport at one or more of the corners. This is a render mesh related defect. There is nothing wrong with the geometry.


10


10


















To fix the mesh

- **1** Use the **Options** command to change the mesh settings.
- 2 On the Mesh page, change to a Custom mesh.Use the settings on the right.



The visual defect goes away.

Rhino Options			×
Document Properties Arnotation Grid Mesh Notes Rendering Rendering Rendering Rendering Web Browser Notes Anoreance Alases Appearance Gonoral Ide Processor Keyboard	•	Render mesh quality Jagged & faster Sincoth & slower Custom options Density: Maximum angle: Maximum angle: Maximum edge length: Maximum edge length: Maximum edge length: Maximum edge length: Maximum edgenength: Maximum initial grid quads:	Preview 0.0
Ubratica Ubrates B Modeling Aids Mouse - Plug-ins - Rendering - Rhine Sander Optione - Rhine Sander - Selection Menu (-) Toolbare - Updates and Statistics	Ŧ	Refine mesh Jagged seams Simple planee	Simple controls


6 Modeling with history

History allows editing or updating objects by editing the input geometry that was used to create the objects. History is useful when there is a need to edit the input of a command or when transformed copies of an object need to stay matched to the original. Only certain commands support history.

A list of commands in Rhino that support history is on page 82.

History is not the same as a "feature" or "parametric." History information is saved in the Rhino *.3dm file.


A simple example would be the following:




Draw a circle.

000

Turn on **Record History** and **Array** the circle.



Scale the original.



Gumball Record History

Always Record History


Watch the arrayed circles update.


Exercise 19—History introduction

To make a lofted surface

- 1 Open the model History_Intro.3dm.
- 2 Select the four cyan colored curves.
- 3 Start the Loft command (Surface menu: Loft), select Normal style, and click OK.

Loft the curves to generate a smooth surface.





4 Turn on the control points and edit the surface.

Turning on surface control points allows the surface to be edited directly as always. However editing the input curves does nothing to change the surface.

5 Undo or delete the loft.



Smart Track

Activating history

History recording is off by default. It must be turned on before running a command to record history for that command. The status of history recording is indicated on the **Record History** pane on the status bar. If the text in this pane is bold, recording is active. Click the pane to change the status.

To record history for a particular command, click the **Record History** pane, and then start a command that pays attention to history.

Why is history off by default?

- Unpredictable results. For example, if you Copy with history and make a change, all of the children start to update.
- File size is larger with history enabled.

To make a lofted surface with history

- 1 Click in the **Record History** pane in the status bar to make it bold and active.
- **2** Select the four cyan colored curves.
- 3 Start the Loft command (Surface menu: Loft), select Normal style, click OK.

Notice the **Record History** pane is no longer bold once a command has run.


4 Select one of the input curves and move it.


The loft surface updates to reflect this new position.


- **5** Turn on control points of the input curves.
- **6** Edit the points and the surface will update.
- 7 Select the curves and **Rebuild** (*Edit menu: Rebuild*) them to **10** points.


The lofted surface updates to reflect this change as well. Changing degree of the parent curves will also change the degree of the child surface in that direction.


8 Undo the three previous steps.














Steps in the History chain

- The command must support History. A list of commands that support History is on the next page.
- History recording must be active when the command is actually run. By default, History recording is turned off and must be activated each time a command is run for which the user wants to record history.
- History updating must be on. This is on by default. When it is on, edits to input objects are immediately reflected in the updated output.
- History can be nested; for example, a curve can be projected onto a lofted surface, and the curve will follow the changes to the lofted surface.

To project a curve onto a surface with history

This part of the exercise will demonstrate an example of nested history. We will be projecting the wheel cutout curves onto the lofted surface.

1 First, we will change the CPlane for the **Perspective** viewport. On the **CPlanes** toolbar tab, click **Set**


CPlane World Right


- 2 Click in the **Record History** pane in the status bar to make it active.
- 3 Use the **Project** command (Curve menu: Curve from Object > Project) to project the two wheel cutout curves onto the lofted surface.
- **4 Set** the **CPlane** back to **World Top** (*CPlanes toolbar tab, Set CPlane World Top*).
- **5** Select one of the input curves for the loft. Modify it by:
 - Moving or scaling
 - Control point editing


Hint: Gumball can be helpful here.

The projected wheel cutout curves update to follow the surface.

Note: Any editing of the outputs will 'break' History and the connection between inputs and outputs will be lost. Rhino will put up a warning box when this happens and the user can either Undo to restore the connection, or continue editing and accept the break in History.







History enabled commands

Transforms	Surfacing	Solid	Curve from object	Annotation	Point
Array	EdgeSrf	Pipe	ArcBlend	Dim	Divide
ArrayCrv	ExtrudeCrv	Slab	Blend	DimAligned	
ArrayCrvOnSrf	ExtrudeCrvAlongCrv	ExtrudeSrf	Crv2View	DimAngle	
ArrayPolar	ExtrudeCrvTapered		CSec	DimArea	
ArraySrf	ExtrudeCrvToPoint		CrvThroughPolyline	DimCurveLength	
Bend (Copy option)	ExtrudeSrfToPoint		CrvThroughPt	DimDiameter	
Сору	ExtrudeSrfAlongCrv		Helix (AroundCurve option)	DimOrdinate	
Orient (Copy option)	ExtrudeSrfTapered		Intersect	DimRadius	
OrientCrvToEdge (Copy option)	Loft		Offset	DimRotated	
OrientOnCrv (Copy option)	NetworkSrf		Project	Hatch	
OrientOnSrf (Copy option)	OffsetSrf		Pull		
Rotate (Copy option)	Patch		Spiral (AroundCurve option)		
Scale (Copy option)	PlanarSrf		TweenCurves		
Mirror (Copy option)	RailRevolve				
Flow	Revolve (Copy option)				
FlowAlongSrf	Ribbon				
ProjectToCPlane	Sweep1				
RemapCPlane (Copy option)	Sweep2				
Rotate (Copy option)	TweenSurfaces				
Rotate3D (Copy option)					
Scale (Copy option)					
Scale1D (Copy option)					
Scale2D (Copy option)					
ScaleByPlane (Copy option)					
ScaleNU (Copy option)					
SetPt					
Shear					
Stretch					
Symmetry					
Taper (Copy option)					

History-related commands

History HistoryPurge SelObjectsWithHistory SelChildren SelParents

Twist



Inputs to a History-enabled command are called Parents in Rhino and the outputs are called Children.

Right-click the **Record History** pane to change the following options:

Always Record History

History Options

This option changes the default behavior so any eligible command will always record history. Use this option with caution. In addition to unnecessarily increasing the file size, it can lead to unexpected behavior. To clear history on particular objects or on all objects, use the **HistoryPurge** command.

Update Children

Causes child objects to update each time the parent object changes. This increases the time it takes to update complex objects. For very complex edits on the parent objects, turn off updating, make the changes, and then turn Update Children on so that the update happens only once.

Lock Children

This option sets child objects to a locked state. Since directly editing the child objects breaks the connection to the parent objects, locking the child objects prevents accidental editing. In addition, selecting child objects can be cumbersome if they are in the same location as the parent objects. Locked child objects still update when the parent objects are edited.

History Break Warning

This option displays a warning if an operation breaks the connection of a child object to its parent objects. The **Undo** command will restore history.

Use the History command to control history recording, updating, locking, and warnings.


To change history options

1 Click on a curve to get the multi-select box.

If you edit the surface in any way, History for the object will break and Rhino will warn you about this.

2 Select the surface and drag it. Rhino will warn you that dragging broke history. Click **OK**.

🔄 Histor	y Warning
	Dragging broke history on 1 object.
	To restore history and undo your changes, run the Undo command.
	Don't show this message again
	ок



Make sure to **Undo** after getting a "broken History" warning to restore the connection between inputs and output.

3 Right-click in the **Record History** pane and check **Lock Children**.

This will make it impossible to edit a child in any way that will break history, but you can select it to change its object properties or layer, etc.

7 Advanced surfacing techniques

There are an infinite number of complex and tricky surfacing problems. In this chapter, we will look at several 'tricks' that help in getting certain types of surfaces built cleanly. The goal, apart from showing you a few specific techniques used in these examples, is to suggest ways in which the Rhino tools can be combined creatively to help solve surfacing problems.

In this chapter, you will learn to make soft domed button shapes, creased surfaces, and how to use curve-fairing techniques.

Dome-shaped buttons

The surfacing goal in this exercise is to create a dome on a shape like a cell phone button where the top must conform to the general contour of the surrounding surface but maintain its own shape as well. There are a number of ways to approach this; we will look at three methods.



Exercise 20—Soft domed buttons

1 Open the model Button Domes.3dm.

The key to this exercise is defining a custom construction plane that represents the closest plane through the area of the surface that you want to match. Once you get the construction plane established, there is a variety of approaches available for building the surface.


There are several ways to define a construction plane. In this exercise, we will discuss four methods: construction plane through three points, construction plane perpendicular to a curve, construction plane tangent to a surface, and fitting a plane to an object.


2 Use **OneLayerOn** to turn on the **Surfaces to Match** layer to see the surface that determines the cut of the button.

To create a custom construction plane using three points method

- 1 Start the **CPlane** command with the 3Point option (*View menu: Set CPlane > 3 Points*).
- 2 In the **Perspective** viewport, using the **Near** object snap, pick three points on the edge of the trimmed hole.

The construction plane now goes through the three points. Notice the construction plane origin is at the first point.






3 Rotate the **Perspective** viewport to see the grid aligned with the trimmed hole.


CHAPTER 7

To create a custom construction plane perpendicular to a curve

With a line normal to a surface and a construction plane perpendicular to that normal line, you can define a tangent construction plane at any given point on the surface

- Start the CPlane command with the 1 Previous option (Viewport title rightclick menu: Set CPlane > Undo CPlane Change).
- Use the Line command with the 2 Normal option (Curve menu: Line > Normal to Surface) to draw a line normal to the underlying surface at a point near the center of the trimmed hole.







Set the command-line option for **IgnoreTrims=Yes** so that the line can be drawn from a point inside the trimmed hole in the surface.

- 3 Start the **CPlane** command with the Curve option (View menu: Set CPlane > Perpendicular to Curve).
- 4 Pick the normal.
- 5 Use the **End** object snap and pick the end of the normal where it intersects the surface.

The construction plane is set perpendicular to the normal line.







To create a custom construction plane to a surface


This function sets the construction plane to match a surface. The placement is constrained so that the construction plane is tangent to the surface at any given point on the surface. This works like the previous method without the need to make the normal line.


- Start the CPlane command with the 1 Previous option (Viewport title rightclick menu: Set CPlane > Undo CPlane Change).
- Delete the Normal line. 2
- 3 Start the **CPlane** command (View menu: Set CPlane > Origin) with the Surface option.
- 4 Pick the surface.
- 5 For the **CPlane origin**, change the IgnoreTrims option to Yes, then pick a point near the center of the hole.
- 6 For the **X axis direction**, pick a point in the direction of the long dimension of the trim curve.

The construction plane is set tangent to the surface at the origin.









To create a construction plane fit through points

Using the **PlaneThroughPt** command to create a surface through a sample of extracted point objects will generate a plane that best fits the points. The **CPlane** command with the **Object** option places a construction plane with its origin on the center of the plane. This is a good choice in the case of the button in this file. There are several curves from which the points can be extracted—the edge of the button itself, or from the trimmed hole in the surrounding surface.


- 1 Start the **CPlane** command with the **Previous** option (*Viewport title right-click menu: Set CPlane > Undo CPlane Change*).
- 2 Turn on the **Surfaces** and the **Curves** layer. Make the **Curves** layer the current layer.
- 3 Start the **DupEdge** command (*Curve menu > Curve from objects > Duplicate edge*) to duplicate the top edge of the button surface, press **Enter**.
- 4 **Copy** the duplicated curve vertically twice.


The vertical position of these curves will determine the shape of the button.


- 5 Use the Divide command (Curve menu: Point Object > Divide curve by > Number of segments) to mark off the top copied curve with 50 points. Set the command-line options to Split=No and GroupOutput=Yes
- 6 Use **SelLast** to select the points just created.
- 7 Use the PlaneThroughPt command (Surface menu: Plane > Through Points) with the selected points.
- 8 Press the **Delete** key to delete the point objects that are still selected.


A rectangular plane is fit through the selected points.

9









Use the **CPlane** command with the **Object** option (*View menu: Set CPlane > To Object*) to align the construction plane with the plane.

10 From the View menu, select Set CPlane, click Named CPlanes, then click the SaveAs icon to save and name the custom construction plane Button Top.

This will allow you to restore this custom construction plane at any time.

11 Delete the surface you used to create the **Button Top** construction plane.

Rhinoceros	(i) 🙁
Named CPlanes	
Rexee	
Save as	
No named CPlanes have be	een saved

Rhinoceros	(i) (i)
Named CPlanes	
∃ピX⊵❷	
Button Top	

To loft the button


- **1** Set the **Surfaces** layer as the current layer.
- 2 Use Loft to make the button.
- **3** Select the top edge of the surface and the two copied curves.
- 4 After selecting the curves, click **Point** on the command-line.
- 5 For the Loft endpoint, make sure the view that has the custom construction plane is the current view, then type 0 (zero) and press Enter.


The loft will end at a point in the middle of the plane, which is the origin of the construction plane.

6 In the Loft Options dialog, under Style, choose Loose, press OK.

With the **Loose** option, the control points of the input curves become the control points of the resulting surface, as opposed to the **Normal** option, in which the lofted surface is interpolated through the curves.

🖌 Loft Options 🛛 📃 📥
<u>S</u> tyle
Loose
Closed loft
Match start tangent
Match end tangent
Split at tangents
Cross-section curve options Align Curves O Do not simplify
Rebuild with 10 control points
Refit within 0.001 millimeters
OK Cancel Preview Help






- 7 Turn on control points on the lofted surface.
- **8** Select the next ring of points out from the center.

Select one point and use **SelV** or **SelU** to select the whole ring of points.

9 Use the SetPt command (Transform menu: Set XYZ Coordinates) to set the points to the same
Z-elevation as the point in the center. Set the radio button in the dialog to Align to CPlane.

Remember, this elevation is relative to the current construction plane.





Note: You can use **History** when creating the loft, in which case the **SetPt** operation should be applied to the topmost curve in the loft, not to the loft surface control points.


To use a patch surface to make the button

- 1 Use the **DupEdge** command to duplicate the top edge of the surface.
- **2 Move** the duplicated curve in the World Z-direction a small amount.
- 3 Use **Divide** to mark off this curve with **50** points as before.
- **4** Use the **PlaneThroughPt** command with the selected points, and then delete the points like the previous exercise.
- **5** Use the **CPlane** command with the **Object** option to set the construction plane to the planar surface.
- **6** Make a circle or ellipse centered on the origin of the custom construction plane.
- 7 Use the **Patch** command, selecting the top edge of the button and the ellipse or circle.


The surface is tangent to the edge and concave on the top.








The size and vertical position of the circle/ellipse will affect the shape of the surface.







Note: If you recorded **History** for the patch, you can select the ellipse and move it up and down or scale it in two dimensions to modify the patch shape.


The **Gumball** control is perfect for making these adjustments. Make sure the Gumball alignment is set to **CPlane**.


To use a rail revolve surface to make the button


- **1** Use the **DupEdge** command to duplicate the top edge of the surface.
- 2 Move the duplicated curve in the World Z-direction a small amount.
- 3 Set a **CPlane** to this curve using **Divide** and **PlaneThroughPt** as before.
- 4 Use **Line** with the **Vertical** option to make a line of any convenient length from the origin of the construction plane down towards the button surface.
- **5** Use the **Extend** command (*Curve* menu: Extend Curve > By Line) to extend the edge at the seam through the rectangular surface.
- 6 Use the **Intersect** command (*Curve menu: Curve From Objects* > *Intersection*) to find the intersection between the extended line and the rectangular surface.
- 7 Use the Curve command to draw a curve from the end of the normal line, using the intersection point as the middle control point, to the end of the seam to use as a profile curve.
- 8 Start the **RailRevolve** command (*Surface menu: Rail Revolve*). Set the **ScaleHeight** option to **Yes**.
- 9 Select the curve you just created (1) as the profile curve, the top edge of the surface (2) as the path curve. Select the upper end of the vertical line (3) as one end of the revolve axis and the lower end as the other end of the revolve axis.
















10 RailRevolve does not pay attention to continuity during the surface creation so you will need to match the new surface to the vertical sides of the button for tangency or curvature with the **MatchSrf** command.





Creased surfaces

Often a surface needs to be built with a crease that may start at a particular angle and change to another angle or diminish to zero. The crease in the car body in the image is an example of this. The following exercise covers two possible situations.




Exercise 21—Surfaces with a crease

The key to the following exercise is to get two surfaces that match with different continuity at each end. At one end, we will match the surface with a 10-degree angle, and at the other end, we will match the surface with tangency continuity. To accomplish this we will create a dummy surface at the correct angles and use this to match the lower edge of the upper surface. When the dummy surface is deleted or hidden, the crease appears between the two surfaces we want to keep.

- 1 Open the model Crease 01.3dm.
- 2 Turn on the Curve and Loft layers.
- **3** Make the **Loft** layer current.
- 4 Use the **Loft** command to make a surface from the three curves.

The **Loft** command remembers the settings across sessions. Make sure the **Loft style** is set to **Normal** and **Do not simplify**.



5 We are going to make a surface that includes all the curves but has a crease along the middle curve.

Use the middle curve to **Split** the resulting surface into two pieces.

6 Use the **ShrinkTrimmedSrf** command (Surface menu: Surface Edit Tools > Shrink Trimmed Surface) on both surfaces.

With a surface that results from a split at an isocurve, shrinking it will allow the edge to be an untrimmed edge because the trim corresponds to the natural untrimmed surface edge.

By trimming with a curve used in the loft, the curve is in effect an isocurve.

You can also use the Isocurve option in the **Split** command when the object to be split is a single surface.

7 Hide the lower surface and turn off the Curve layer.

To create the dummy surface

We will change the top surface by matching it to a new dummy surface.


The dummy surface will be made from one or more line segments along the bottom edge of the top surface that are set at varying angles to it.


To get a line that is not tangent but is at a given angle from tangent, the easiest method is to use the transform tools to place the line tangent and then to rotate it by the desired increment.


End


- 1 Change to the **Dummy Curve** layer.
- 2 In the **Top** viewport, draw a line 20 units long.

- **3** Start the **OrientCrvToEdge** command (*Transform menu: Orient > Curve To Edge*).
- 4 For the **Curve to orient**, select the line.
- **5** For the **Target surface edge**, select the lower edge of the surface.











- 6 For the **Pick target edge point**, change the command-line option to **Copy=Yes**, and snap to an endpoint of the edge.
- 7 For the **Pick target edge point**, snap to the other endpoint.
- 8 Press Enter.

The result should look like the images above.

9 In the Perspective viewport, use the Viewport title right-click menu and select Set CPlane > Perpendicular to curve to set a construction plane perpendicular to the lower edge of the surface, snapping to the left end point of the lower edge for the construction plane origin.





Set up the rail line


 Select the line segment at the left end and start the **Rotate** command. Set the center of rotation at the origin of the new custom construction plane. Rotate the segment **10** degrees.


The result should be like the image on the right.



- **3** Use the **Sweep1** command (*Surface menu: Sweep 1 Rail*) to create the dummy surface.
- **4** Select the lower edge of the upper surface (1) as the rail and the two line segments (2 & 3) as cross-section curves.


Make sure to use the surface edge and not the original input curve as the rail for the sweep.






This option causes the sweep surface to derive from the cross section curves its angle relative to the base surface at its edge. A shape curve tangent to the base surface will hold that tangency as it sweeps along the edge, unless another shape curve with a different angle to the surface is encountered, in which case there will be a smooth transition from one to the next

🖌 Sweep 1 Rail Options 🛛 🗾
<u>S</u> tyle
Align with surface 🔹
Closed sweep Global shape blending Untrimmed Miters
Cross-section curve options Align Shapes Do not simplify Rebuild with 5 control points
Rebuild with 5 control points Refit within J.01 Simple sweep
Refit rail
OK Cancel Preview Help



To match the surface to the dummy surface


- **1** Use the **MatchSrf** command to match the upper surface to the dummy surface.
- **2** Select the lower edge of the upper surface.



- **3** Select the upper edge of the dummy surface.
- 4 In the Match Surface dialog, choose Tangency and check Match edges by closest points.

This will keep distortion to a minimum.

Continuity Fosition Tangency Curvature Preserve other end None Fosition Tangency Curvature Average surfaces Match edges by closest points Refine match Distance Distance Distance Distance O.001 units Tangency: 1.0 degrees Curvature: D.05 percent Iscourve direction adjustment Automatic Freserve isocurve direction Match target isocurve direction	🛃 Match Surface		X		
 None Fosition Tangency Curvature Average surfaces Match edges by closest points Refine match Distance 0.001 units Tangency: 1.0 degrees Curvature: 0.05 percent scourve direction adjustment Automatic Freserve isocurve direction Match target isocurve direction 	 Position Tangency Curvature 				
Average surfaces Match edges by closest points Refine match Distance. 0.001 units Tangeney: 1.0 degrees Curvature: 0.05 percent scourve direction adjustment Automatic Freserve isocurve direction Match target isocurve direction	 None Fosition Tangency 				
Distance: 0.001 units Tangeney: 1.0 degrees Curvature: 0.05 percent Iscourve direction adjustment	 Average surfaces Match edges by closest points 				
Socurve direction adjustment Socurve direction Automatic Treserve isocurve direction Match target isocurve direction	Distance Tangeney:				
 Freserve isocurve direction Match target isocurve direction 	isccurve direction adjustment				
Make perpendicular to target edge OK Cancel Ca					



Show the lower surface and **hide** the dummy surface. 5

Join the lower surface with the upper surface. 6

Because the surfaces are untrimmed, you have the option to merge the surfaces back into one surface.

The crease fades smoothly from one end to the other of the polysurface. If more control is needed over the angles of the crease, more segments can be placed to create the dummy surface.

Exercise 22—Surfaces with a crease (Part 2)


In this exercise, there is no convenient relationship between the crease curve and the surface. While similar to the other example, the upper surface is made with a two-rail sweep.


To create a crease with trimmed surfaces


- 1 Open the model Crease 02.3dm.
- Use the **Line** command (*Curve menu: Line > Single Line*) to draw a single 2 line anywhere in the **Top** or **Perspective** viewport.


We will use this line to make a dummy surface.


- Use the **OrientCrvToEdge** command (Transform menu: Orient > Curve 3 to Edge) to copy the curve for the dummy surface to the upper edge of the lower surface.
- 4 Place a line at each end of the edge and somewhere in the middle of the edge.












5 Move each line segment by moving its upper end to the lower end of the same segment.


End




6 Use the **CPlane** command (*View menu: Set CPlane* > *Perpendicular to Curve*) to set the construction plane to align with the line at the left of the surface.

7 Use the **Rotate** command *(Transform menu: Rotate)* to rotate the line **15** degrees as shown in the illustration on the right.

8 Repeat these steps for the line in the middle of the surface.





To make the dummy surface

- 1 Use the **Sweep1** command to create the dummy surface.
- **2** Select the upper edge of the lower surface as the rail and the three line segments as cross-section curves. Use the Align with surface style for the sweep.

Hide the original surface. 3


4 Use the **Sweep2** command to make the upper surface.


Choose the upper edge of the dummy surface as a rail (1) and the long curve at the top as the other rail (2).


Choose the curves at both ends as the cross-section curves (3) and (4).


- 5 In the Sweep 2 Rails Options dialog, for the Rail continuity of edge **A**, choose **Tangency**.
- **6 Delete** the dummy surface.
- 7 Use Show or Show Selected (Edit menu>Visibility>Show selected) to show the original lower surface.
- Join the lower surface with the 8 upper surface.
- 🥪 Sweep 2 Rail Options oss-section . ◎ Do not simplify ^{1 J} with |5 Cross-section curve options control points Refit within 0.01 Preserve first shape Preserve last shape 🔲 Maintain height Rail curve options A B Position 0 Tangency 💿 📀 Curvature 🔘 🔘 Closed sweep Add Slash Simple sweep OK. Cancel Preview Help

X









Curve fairing to control surface quality

Curves in Rhino can come from many sources, they can be:

- · Created in Rhino directly
- Imported from digitized data
- Imported from another application
- Section curves generated from a mesh

It is important to understand that many of these curves need to be optimized for quality.

Fairing is a technique used to simplify curves while improving their curvature graphs and keeping their shape within tolerance. It is especially important to fair curves that are generated from digitized data, intersections, extracted isocurves, or curves from two views.

Generally, curves that are single-span curves work better for this process. A single span curve is a curve that has one more control point than the degree. For examples a degree 3 curve with 4 control points, a degree 5 curve with 6 control points, or a degree 7 curve with 8 control points.


To analyze a lofted surface with curvature analysis

- 1 Open the model Fair Curves.3dm.
- 2 Select the curves and use the Loft command (Surface menu: Loft) with Style set to Normal and Cross-section curve options set to Do not simplify to make a surface.

The surface is very complex. It has many more isocurves than are needed to define the shape, because the knot structures of the curves are very different.

The surface also has compound curvature.





3 Select the lofted surface and start the **CurvatureAnalysis** command (*Analyze menu* > *Surface*>*Curvature analysis*).


This creates a so-called "False color" display using the same type of analysis meshes as the **Zebra** command.

The amount of curvature is mapped to a range of colors allowing you to analyze for areas of abruptly changing curvature or flat spots.

Choose Mean from the Style drop down.


This style is useful for showing discontinuities in the curvature—flat spots and dents. The mean is between the two curvature circle values at each point, mapped to a color value.

4 Push the **AutoRange** button.



5 Click the Adjust Mesh button and adjust the Minimum initial grid quads to have at least 5000 minimum grid quads to ensure a smooth display of the color range.

🐓 Polygon Mesh Detailed Options 🛛 📃				
	0.0			
Density:	0.0			
Maximum angle:	0.0			
Maximum aspect ratio:	3.0			
Minimum edge length:	0.0001			
Maximum edge length:	0.0			
Maximum distance, edge to surface:	0.0			
Minimum initial grid quads:	5000			
Refine mesh Jagged seams Pack Textures Simple planes				
OK Cancel Help Preview	V Simple Controls			




Note the streaky and inconsistent colors on the surface. This indicates abrupt changes in the surface.

6 Undo the loft.

To rebuild the curves

- 1 Change to the **Tangency Direction** layer.
- 2 Use the Line command (Curve menu: Line > Single Line) with the Extension option, to make a line that maintains the tangency direction of an original curve from each end point and coming back towards the curve, any length.



Make the lines long enough to cross one another.

- 3 Change to **Rebuilt Curves** layer, and **Lock** the **Tangency Direction** layer
- **4** Use the **Rebuild** command (*Edit menu: Rebuild*) to rebuild the curve.

Although there is a **Rebuild** option in the **Loft** command, rebuilding the curves before lofting them gives you control over the degree of the curves as well as the number of control points.

5 In the Rebuild Curve dialog, change the Degree to 5 and the Point Count to 6 points. Uncheck Delete input, check Create new object on current layer. Click the Preview button. Note how much the curves deviate from the originals.

🛃 Rebuild			×	
Point count: Degree:	(22) (3)	6		
Delete input				
Create new object on current layer Maximum deviation: 1.54464				
OK Cancel Preview				

This makes the curves into single-span curves. Single-span curves are Bézier curves. A single-span curve is a curve that has degree +1 control points. While this is not necessary to get high quality surfaces, it produces predictable results.

- 6 Lock the **Original Curves** layer. We need to see these curves but we do not want to be able to select them.
- 7 Select one of the rebuilt curves, and turn on the Control points and Curvature graph.
- 8 Fair the curve by adjusting points until it matches the original curve closely enough.

Start by moving the second point from each end of the rebuilt curve onto the tangent line. Use the Near object snap to drag along the tangent line.

9 Check the curvature graph to make sure the curve has smooth transitions.

The curves are fair when the points are adjusted so the rebuilt curves match the original locked curves closely, with good graphs.


10 Fair the other curves the same way.

Here are some things to keep in mind when adjusting the curves:


- If you want to keep the curve tangent direction consistent with the original curves, make sure the second point from each curve stays on the green tangent direction line- only move these points with the Near object snap pulling the point onto the line.
- The **DragMode** command, set to **ControlPolygon** will constrain point dragging to the curve control polygonyou can use this tool to keep the tangent directions constant.
- Where possible, when fairing a set of curves to be used as input to a single lofted surface, try to keep the control point arrangement on each curve similar to the neighboring curves. This will help keep the surface nicely aligned.
- When control point adjustment becomes difficult due to the small movements needed, try using the **Nudge** keys to nudge the points by small amounts. See **Help** for more information about **Nudge**.
- You can also use the **Gumball** to move points. When fine-tuning with very small point movements needed, you can set **GumballDragStrength** to something less than 100% to allow larger mouse movements to make small changes in the point locations.

To use PointDeviation to visualize the deviation while you edit the curves

- **1** Make a **Points** layer and make it **current**.
- 2 Select all of the original curves and start the **Divide** command (Curve menu: Point Object>Divide Curve by>Number of Points). Set the Number of segments to 32 and GroupOutput=Yes.
- **3** Deselect all objects, and select the grouped points.
- 4 Start the **PointDeviation** command (*Analyze menu: Surface>Point Set Deviation*), and at the **Select curves**, **surfaces**, **and polysurfs to test** prompt, select the, roughly faired, rebuilt curves.








5 When the Point/Surface Deviation dialog pops up, set the numbers as follows:
Good point = 0.1
Bad point = 0.5
Ignore = 1.0


The display shows the deviation between the points displayed on the original curves and the closest locations to these on the rebuilt curves.


6 Lock the **Points** and the **Original Curves** layers.



7 Continue to modify the rebuilt curves with the goal being that all points will turn blue, as good points.

Note: If you close the dialog, you lose the display and you need to start over with **PointDeviation**.





To make a surface with fair curves


1 Loft the new curves.


The shape and quality of the surface has very few isocurves but it is very close to the shape of the first surface.



Note the smooth transitions in the false color display, indicating smooth curvature transitions in the surface.

-¥





8 Use background bitmaps

This exercise describes the steps in creating a case for a small, hand held product, using bitmaps as templates. In this exercise, we will focus on making curves from bitmap images and using fairing techniques on the curves before making the surfaces.

We will begin by taking scanned sketches and placing them in three different viewports. The three hand-drawn images need to be placed in their respective viewports and scaled appropriately so that they match each other.

You can align images more easily if they have been aligned and cropped so that they share the same length in pixels. It helps to darken and slightly reduce the contrast of images that have a lot of bright white in them. This allows a greater range of colors to be seen against them when tracing them in Rhino.

Exercise 23—Handset

- 1 Open the model Handset.3dm.
- 2 From the **Tools** menu, click **Toolbar Layout**.
- 3 In the **Rhino Options** dialog, on the **Toolbars** page, check **Background Bitmap** to open the toolbar, and then close the dialog.

Use the toolbar buttons for the next part of the exercise.

The toolbar can also be accessed by flying out the **Background Bitmap** toolbar from the **Viewport Layout** tab across the top.

4 It will make it easier in this exercise if you **Split** the **Front** viewport **horizontally** and make the lower view the **Bottom** viewport. You can re-align the views like the illustration below.

Handset.3dm (34 KB) - Rhinoceros (Not For Resale Lab) (64-bit)				
File Edit View Curve Surface Solid Mesh Dimension Transform Tools Analyze Render Pan	els Help			
1 curve added to selection.		*		
Command: Hide		• •		
Standard CPlanes Set View Display Select Viewpot Layout Visibility Transform Curve Too	Is / Surface Tools / Solid Tools / Mesh Tools / Render			
		roois / Exaning / • ca		
ka o Top -	Perspective -	Prope 💙 Layers 🛞		
∧,=j	v	/iewport		
0 O		Litle Perspect		
		Width 345		
		Height 358		
		Projection Persp 💌		
Front F		Lens Le., 100.0		
Front •		XLocati 278.443		
		YLocati -387 494		
R 14		Z Locuti 265.581		
		Location Pla Bac		
A A A	2 U	arget 🖓 🔛		
××	×	X Target 0.000		
		YTarget -0.000 ZTarget 0.000		
		Location Place		
		Vallpaper		
		Filename (none)		
		Show 🔽		
	2	Gray 🔽		
	y			
Perspective Bottom Top Front Right ↔	1			
	Planar Osnap SmartTrack Gumball Record	History Filter I		
Orland x=12.004 y=10.200 Z 0.000 Willin Release Dicinaps Orld Shap Orld	Tranar Canap Sinar Tack Currual Record	natory Filter (


5 In Rhino Options, on the View page, in the Viewport properties section, check Linked viewports.This allows the viewports to stay aligned with each other when zooming and panning.

To place background bitmaps

We will begin by making reference geometry to help in placing the bitmaps.

- Make a horizontal line, from both sides of the origin of the Top viewport, 150 mm long.
- 2 Toggle the grid off in the viewports that you are using to place the bitmaps by pressing the **F7** key.

This will make it much easier to see the bitmap.



- **3** In the **Front** viewport, use the **BackgroundBitmap** command with the **Place** option (*View menu: Background Bitmap* > *Place*) to place the **HandsetElevation.bmp**.
- 4 Use the BackgroundBitmap command with the Align option (View menu: Background Bitmap > Align) to align the ends of the handset to the line. The commandline prompts will tell you the steps to


follow.

The **Align** option shows blips at the corners of the bitmap, so that it is precise to use **Point** object snap to specify them.


Pick two points on the bitmap—you can zoom way in to pick a point very accurately at this stage.

Pick the points at either extremity of the long shape. Next, you pick two points in space to which you would like to have the image points just selected to correspond—snap to the endpoints of the 150 mm line.

- **5** Change to the **Bottom** viewport.
- **6** Use the same technique to place and align the **HandsetBottom.bmp** in the **Bottom** viewport.



7 Repeat these steps for the **Top** viewport.



To build the case

The most useful tool for tracing freeform curves is a control point curve.

Place the fewest number of points that will accurately describe the curve. Do not fall into the trap of trying to be 100% accurate with every point placement. With some experience you will be able to place about the right number of points in about the right places and then point edit the curve into its final shape.

In this example, the 2-D curves can all be drawn quite accurately with a degree-3 curve using five or at most six control points.

Remember to pay attention to the placement of the second points of the curves to maintain tangency across the pointed end of the object.


×


1 In the **Front** viewport, trace two curves to define the form of the case.


The front view curves describing the top and bottom edges of the case should extend on the right past the form in the background image.

2 In the **Bottom** viewport, trace one curve to define the form of the case.

Since the bottom view of the object is symmetrical, you can make one curve. Extend the curve past the background image approximately the same distance as you did with the curves in the **Front** viewport.







3 Draw the curve in the **Front** viewport that defines the parting line separating the top and bottom halves of the case.

This curve is the front view of the plan view's edge curves. It should be extended to the right the same distance as the other edge curves.

- 4 **Trim** both bottom view and front view form curves with a single cutting plane or use the **SetPt** command to set the points at the same plane.
- **5** In the **Perspective** viewport, select the parting line curve and the outline curve that you created in the **Bottom** viewport.
- 6 Use the **Crv2View** command (*Curve menu: Curve From 2 Views*) to create a curve based on the selected curves.

A 3-D curve is created.

7 Hide or **Lock** the two original curves.


Now there are three curves.


8 Turn on the control points for the curves.


Notice the number of control points and the spacing. This is an example of curves that need to be faired before you can create a good surface from them.


- **9** Fair the curves, using the same technique as in the previous exercise.
- **10 Mirror** the 3-D curve for the other side.


The macros ! Mirror 0 1,0,0 and ! Mirror 0 0,1,0 are very useful for accomplishing this quickly if they are assigned to a command alias and if the geometry is symmetrical about the x- or y-axis.






















11 Loft the faired curves with the **Closed loft** option checked.

Notice the quality of the surface and how few isocurves there are.

A closed loft will have a seam.






To build the case (alternate technique 1)

- **1 Undo** until your back to step **7** of the previous part of the exercise.
- **2 Mirror** the 3-D curve for the other side.
- 3 Loft the curves, using the **Rebuild** option to **18** points.

The isocurves all true up and everything looks clean, but if you look at the tip, it falls away from the input curves.


The **Rebuild** option does not sample more in areas of high curvature but just divides the curves up evenly.

Loft Options		X		
<u>S</u> tyle				
Normal		•		
🔽 Closed loft				
Match start tang	lent			
Match end tangent				
Split at tangents				
Cross-section curve of Align Curves	options —			
O not simplify		1		
Rebuild with	18	control points		
Refit within	0.001	millimeters		
OK Canc	el Pre	view Help		



To fair the surface

- 1 Hide the **background bitmaps** and set the viewport to wireframe.
- 2 Turn on surface points.




3 In the **Top** or **Bottom** viewport, move points on one side of the surface in the y-direction to get the surface to match.

A few points moved should do it.

Now, how do we get the other side exactly the same?

4 Undo all the moves and instead of moving the points, select opposite pairs of points and **Scale1D** in Y to move them symmetrically.

The base of the scale should be a middle point, use Ortho to keep the scale axis true to $\ensuremath{\mathsf{Y}}.$



Show the Organic toolbar and use the Expand Y and Compress Y 5 nudge controls to do the same thing in small increments.

These buttons are macros of Scale1D using the origin as the scale origin.

Use similar techniques for adjusting points in the elevation view. Since the 6 points in this view are not symmetrical in the z-axis, do one side at a time, moving rather than scaling the points.

Nudge keys or the Move in Z nudge controls in the **Organic** toolbar also work.


To build the case using the CSec command (alternate technique 2)


The **CSec** command creates cross-section curves through profile curves.

- 1 **Undo** back to the four input curves.
- 2 Start the **CSec** command (Curve *menu > Cross section profiles*).
- Select the curves in order as if lofting 3 them, make sure the **Closed** option is Yes, press Enter when done.
- 4 For the **Start cross-section line**, in Front viewport, pick a point on either side of the 4 curves.
- For the **End of cross-section line**, use **Ortho**, and pick a point on the other side of the 4 curves. 5
- Continue this process until you have 6-10 cross-section curves, evenly 6 spaced along the four curves.


Make sure to add one section snapping to the endpoints at the open end of the set of curves.








USE BACKGROUND BITMAPS



- **7** Window the section curves and the original long curves.
- 8 Start the **NetworkSrf** command (*Surface menu > Curve Network*) to make the surface.



9 An approach to modeling

A common question that users have when modeling, is "Where do I start?" In this section, we will discuss various approaches to the modeling process.

There are two things to consider before your begin modeling: if reflections, fluid flow, air flow, or the ability to edit using control points are important in the finished model, you will want to begin your models with geometry that consists of cubic (degree 3) or quintic (degree 5) curves. If these are not important, you can use a combination of linear (degree 1), quadratic (degree 2), cubic or quintic curves.


Start with simple shapes, the details can be added later. Begin by creating layers for the different parts. This will help separate the parts for visualization, and help with matching the parts as you go.

We will review different products to try to determine which kind of surfaces are most important and some approaches to modeling the product.

Exercise 24—Cutout

This exercise shows an approach to making a cutout surface that blends smoothly and seamlessly into an existing curved surface. The new surface has an arbitrary relationship to the existing surface so the general strategy can be used in other cases.

For this exercise, we have created additional models for each stage of the exercise. The models are for reference and include notes to explain the procedure for the steps in that stage of the exercise. There will be a note at each stage to indicate which model to open if needed.




- 1 Open the model Scoop.3dm.
- 2 Make the Cut-out Curves layer current, turn on the Original Surface layer, and turn off the Completed Scoop layer.
- **3** In the **Top** viewport, select the curves.
- 4 Start the **Project** command (Curve menu: Curve From Objects > Project).
- **5** Select the surface and press **Enter**.


The curves will be projected onto the surface.

- 6 Start the **ExtendCrvOnSrf** command (*Curve menu: Extend Curve > Curve* on Surface).
- 7 For the **Curve to extend**, select the outer curve on the surface.
- 8 Select the surface.

The ends of the curve are extended to the edge of the surface.











- **9** Use the **Trim** command *(Edit menu: Trim)* to trim the curves with each other.
- 10 Join the three small curves into one.
- **11 Copy InPlace** the surface and hide the copy.
- **12** Use the joined curve to trim away the part of the surface that is outside the curve.






This leaves a small trapezoidal surface. This surface is a dummy that will be used to match to a new surface.

13 Use the ShrinkTrimmedSrf

command (Surface menu: Edit Tools > Shrink Trimmed Surface) to make this surface easier to see since it will reset the isocurves to the new surface size.




To make the curves for the floor of the scoop (Open Scoop 001.3dm if needed)


Next, we will make a surface for the bottom of the cutout. The cutout is rounded at one end, but we will build a rectangular surface and trim it to be round at one end. This approach allows for a much lighter, more easily controlled surface than trying hitting the edges exactly while building the surface.

In this part, we will make one curve with as few points as possible that shows the shape of the part that will become the bottom of the scoop. When making the curve, try to look at it from various views while you work. Use a degree 5 curve and six points for a very smooth curve. Check the curve with the curvature graph to get a nice fair curve.

 Use the **Curve** command to draw a control point curve in the **Front** viewport. On the **Status bar**, turn **Planar** mode on. This will keep the curve in a single plane for the moment.

Snap the first point of the curve to the corner of the small dummy surface in any convenient view. Then switch to the **Front** viewport to continue drawing.





Draw the curve approximately tangent to the edge of the dummy surface and finish it lower, defining the shape of the floor of the scoop.

2 Adjust the curve with point editing to get the right shape in the **Top** viewport.

Make sure to move the points only in the y-direction (Ortho will help), so that the shape in the **Front** viewport will not be altered.


Make the curve approximate the outermost of the original curves and extend somewhat past the rounded end.


3 Use the Match command (Curve menu: Curve Edit Tools > Match) to match the curve with Curvature continuity to the edge of the dummy surface.


Edit the curve further if needed but be sure to use Match again if you have moved any of the first three points in the curve.


- 4 **Copy** the curve to the other edge.
- **5** Adjust the curves by moving the control points until they look the way you want, and then **Match** the curve to the edge of the dummy surface.


If matching makes the curve distort too much add a knot and try again. Using the **EndBulge** command and further point editing may be needed.















To create the floor surface of the scoop (Open Scoop 002.3dm if needed)

There are a few surfacing techniques that can be used to create the surface.


A **2-Rail Sweep** would be one obvious choice, using the new curves as rails and the edge of the dummy surface as the cross section. The advantage of this is that other cross-sections can be used to define the floor shape if desired.

Since the rails are G2 to the dummy surface (Matched in the last sequence of steps), the surface will be very close to G2 to the dummy surface when created.

The **MatchSrf** command could fix any discontinuity, if needed. This is a good way to go and you may wish to try it now.



2-Rail Sweep using the new curves as rails and the surface edge as the cross-section.



2-Rail Sweep using the new curves as rails and the surface edge as the cross-section with the simple sweep option checked.

Another approach is to make a lofted surface between the two curves. The surface will need adjustment to match to the dummy surface and will provide the opportunity to explore some options in the **MatchSrf** command so we will outline this method below.

1 Use the **Loft** command (*Surface menu: Loft*) to create the surface between the two curves.

Because the lofted surface is flat, there will be a slight gap at the edge of the dummy surface.

2 Use the MatchSrf command (Surface menu: Surface Edit Tools > Match) to match the lofted surface to the edge of the dummy surface for curvature.

Use the **Preview** button to see how the match will look.

You may notice that the matched surface pulls around quite drastically to be perpendicular to the target edge.

If so, change the **Isocurve adjustment** from **Automatic** to **Preserve isocurve direction**, and try the **Preview** again. The surface should now match with much less distortion.

3 Use the **Zebra** command (*Analyze menu: Surface > Zebra*) to check the continuity of the two surfaces.

To make the sides of the cutout (Open Scoop 003.3dm if needed)


To make the sides of the cutout, we will extrude the projected outline with 10 degrees of draft and trim it with the lofted surface.


- **1** Select the outer projected curve.
- Use the ExtrudeCrvTapered command (Surface menu: Extrude curve > Tapered) to extrude the inner projected curve. Change the DraftAngle to 10. Pull the surface until it fully intersects with the bottom surface, but no more, and pick.

If you extrude the surface too far, you might get a polysurface instead of a single surface.

If this happens try to extrude again, but do not pull so far.


If you cannot pull it far enough to penetrate the floor without making a polysurface, extrude it a short distance instead.







AN APPROACH TO MODELING



Robert McNeel & Associates

3 Use the **ExtendSrf** command (*Surface menu: Extend Surface*) to extend it through the floor surface.

The extruded surface is a very dense surface.

4 Use the **FitSrf** command (*Surface menu: Surface Edit Tools* > *Refit to Tolerance*) to simplify the surface.

A Fitting tolerance of 0.001 with DeleteInput=Yes, ReTrim=Yes, UDegree=3, and VDegree=3 should work well.

To create the fillets

Now the surfaces are ready to be filleted.

- **1 Show** the main surface and **Hide** the dummy surface.
- 2 Use the FilletSrf command (Surface menu: Fillet Surface) with a Radius=5, Extend=No, and Trim=No to make the fillets between the bottom surface and the sides.
- **3** For the first surface to fillet, pick the bottom surface.
- **4** Pick the side surface near the same spot.
- **5** Repeat this for the side surface and the original surface.

The two fillets cross each other. We will trim them both back to their intersection points.

Trimming the fillet surfaces (Open Scoop 004.3dm if needed)

Both of the fillet surfaces are tangent to the tapered side of the scoop. Where the fillets cross they are tangent to each other.


If we trim the ends of the fillets to a plane, then the resulting trimmed edges will be tangent to each other. Trimming these surfaces will be helpful when creating the final surfaces that blend the fillets out between the scoop and main surfaces.


To create the plane, first make circles with the **AroundCurve** option around one edge of the fillet surfaces, then make planar surfaces from the circles.

- 1 Select the fillets and use the **Invert Hide** button in the **Visibility** toolbar to isolate them.
- 2 Start the **Circle** command, and use the **AroundCurve** option. Set the **Int** object snap only.


The **AroundCurve** option forces the **Circle** command to look for curves, including edge curves, to draw the circle around.

3 Click on the upper edge of the lower surface and snap to the intersection point.












- 4 Draw the circle out well past the width of the fillet surfaces.
- 5 Use the **PlanarSrf** command (*Surface menu: Planar Curves*) to create a circular surface at the intersection point.
- **6** Repeat these steps for the other intersection.







Trimming the sides of the scoop

You can use the trimmed fillets to trim back the side surface of the scoop.

- **1** Use **ShowSelected** to show the tapered side surface.
- **2** Use the fillet surfaces as trimming objects to trim the excess from the side surface.


It is often much faster to trim with curves than to use surfaces, especially if the surfaces are tangent to the object to be trimmed, as is the case with fillets.


Duplicate the two edges that are in contact with the side surface to use as trimming objects if you have a problem.


Trimming the main and floor surfaces (Open Scoop 005.3dm if needed)

The next task is to extend the edges of the fillets so that the main surface and the floor surface can be trimmed back. The inner, or lower, edge of the lower fillet will be extended off the end of the floor surface and the outer, or upper, edge of the upper fillet will be extended off past the end of the opening of the scoop as well. The extended curves will be projected onto the respective surfaces and used to trim them.

- In the **Top** viewport, use the **Extend** command with the **Type=Smooth** option to extend both bottom ends of the lower fillet edge past the front of the floor surface.
- 2 Use these curves, still in the **Top** viewport, to **Trim** the outer edges from the floor surface.









3 Use **Extend** to extend the outer edges of the upper fillet past the end of the floor surface.

Note that in the **Perspective** viewport these extended curves are off in space at their outer ends.

- **4 ShowSelected** the main surface if it is hidden.
- **5 Project** the curves onto the main surface from the **Top** viewport.
- 6 ShowSelected or turn on the layer for the original curves and **Project** the line segment onto the main surface.
- 7 **Trim** the projected curves with one another so that they form a closed loop.
- **8** Use the closed curves to **Trim** a hole in the main surface.











Set up the curves to create the surfaces (Open Scoop 006.3dm if needed).

We are now nearly ready to create the surfaces. As you can see there are nice rectangular gaps in the surfaces, we just need to arrange the curves and edges surrounding the gaps for use in making a 2-Rail Sweep or a surface from a Curve Network. Because one end of each open rectangle is bounded by the two tangent fillet edges, we need to create a single curve there to use as input. We will duplicate the four edges and join them into two s-shaped curves. The other end of each rectangle is bounded by a portion of the end of the hole in the main surface. We will split up that long edge into segments that correspond exactly to the ends of the rectangular openings.

- 1 Use **DupEdge** to create curves at the trimmed edges of the fillets.
- **2 Join** these four edges into two curves.
- 3 Use the SplitEdge command (Analyze menu: Edge Tools > Split Edge) and the End object snap to split the straight edge on the trimmed hole in the main surface to the end points of the floor surface's edge.





5


4 Use the **SplitEdge** command to split the long edges at the endpoints of the fillet edges.


This will help **NetworkSrf** find a solution more quickly.


Use the Sweep2 command with Rail continuity=Tangency or the

The surfaces start with the s-shaped curves that you duplicated and end

NetworkSrf command to create the last two surfaces.









6 (Open Scoop 006.3dm if needed) Join the cutout surfaces and then trim a hole at the bottom.

with a flat line at the split edges.

7 **Mirror** and Trim to get the other scoop.






Extra cross section curves

Open Scoop 007.3dm, if needed.


Use **Sweep2** or **NetworkSrf** to close the holes. Filling the larger of the two holes may benefit from extra cross section curves. To add cross-sections, use the **Blend** command to make tangent curves approximately one-third and two-thirds of the way along the edges of the opening. Use these curves as additional input for a network surface.




- 1 Start the **BlendCrv** command (*Curve menu: Blend Curves* > *Adjustable Curve Blend*).
- 2 At the command-line, select the Edges option. Set the Continuity=Tangency.
- **3** For the **Select surface edge to blend**, click approximately one-third of the way along one of the long edges of the rectangular opening.
- 4 For the other **Select surface edge to blend**, click on the edge opposite the first one.


The blend curve will be placed across the opening and a dialog will open.

5 In the **Adjust Curve Blend** dialog, set the **Continuity** to **Tangency** for both ends.






🔄 Adjust Curv	e Blend	X
Continuity	1 :	2
Position Tangency Curvature G3 G4 Reset		
Flip 1 Trim Join Show curve	Flip 2 sture	Help





Remember to include the new curves in the selection.



10 Applying 2-D graphics

Often you are asked to take an existing design from a 2-D graphics package and include it as part of a Rhino model.

In the following two exercises, we will move and position the graphic onto the model.

Exercise 25—Importing an Adobe Illustrator file

In this exercise, we will make a custom construction plane, import an Illustrator file, and place a logo on some surfaces.

- 1 Open the model Air Cleaner.3dm.
- 2 In Rhino Options, Modeling Aids, set the Construction planes to use Standard construction planes.

The following techniques will not work if the construction planes are set to use Universal construction planes.

To import a file

- **1** Start the **Import** command (*File menu: Import*).
- 2 Change the Files of type to Adobe Illustrator (*.ai), and choose the AirOne_Logo.ai to import.
- 3 In the AI Import Options dialog, click OK.

The logo curves appear at the origin of the Top construction plane, are selected, and on the Default layer.

Tip: If curves are not planar, use the **ProjectToCPlane** command (*Transform menu: Project to CPlane*).

- **4** While the imported geometry is still selected, use the **Group** command to group the various curves together. This makes it much easier to select all of the curves and not leave any behind in the following transform steps.
- **5** Start the **Layer** command.
- 6 Turn off the Logo layer in the Layer panel.
- 7 **Right-click** on the **Logo** layer, then click **Copy Objects to Layer** to make a copy of the logo on the Logo layer.


We will use this copy later for another part of the exercise.

8 Turn off all the layers except **Default** and **Top Surface**.

To create the custom construction plane

We need to set a construction plane to the flat surface. The **CPlane** command will allow us to do this but the X and Y directions of the new custom construction plane will be mapped to the u- and v-directions of the target surface respectively. The **Dir** command will tell you how the u- and v-direction are pointing on the surface, and allow you to change the directions of each.







AI Import Options
Scale
 Fit to default screen Preserve units
1 inch 👻 in Al 1 Rhino unit
· · · · · · · · · · · · · · · · · · ·
_
Nways use these settings. Do not show this dialog again.
OK Cancel Help

 Select the flat disc shaped surface, then from the Analyze menu, select Direction (Analyze menu: Direction).

This displays the current surface normal direction and the U/V directions. It is important to know the u- and v-directions of the surface.





The white arrows show the surface normals. A cursor with a red and green arrow appears when you move over the selected surface.

The red arrow indicates the U direction and the green arrow indicates the V direction.

2 At the command-line, notice the options for changing the directions of the surface. You can click on these to change the surface directions. The cursor and surface normals will update accordingly.

When all changes are made, press Enter to accept.

The goal is to have the U and V as in the second image.

In this way, the new construction plane will map to the surface accordingly and the geometry can be mapped to the construction plane predictably.

3 In the **Perspective** viewport, use the **CPlane** command with the **Object** option (*View menu: Set CPlane > To Object*) or (*Viewport title right-click menu: Set CPlane > To Object*) to set the construction plane to the surface.

The x- and y-axes are parallel to the u- and v-directions of the surface as you set them in the previous step.

4 You may want to save the new construction plane with the NamedCPlane command (Viewport title right-click menu: Set CPlane > Named CPlanes) to make it easy to retrieve later step.


To map the logo curves to the new construction plane

The command we will use to move the logo to the flat disk shaped surface uses the position of the object relative to a construction plane.

1 Select the curves in the **Top** viewport. Make sure the **Top** viewport is active, then start the **RemapCPlane** command (*Transform menu:* Orient > Remap To CPlane).

This command depends upon the active construction planes at each stage, so it is important to pick in the correct viewports.





2 Click in the **Perspective** viewport with the custom **CPlane**.

You could use the **Copy=Yes** option in this command so that a copy is remapped instead of the original.

The logo is positioned in the same relative position on the custom construction plane as it was in the active viewport.

3 Rotate, Move, or Scale the logo to a new position.

For an accurate view of the surface and the curves, you may want to use the **Plan** command in the **Perspective** viewport. This sets the view to a parallel projection looking straight on at the plane.

- 4 Use the ExtrudeCrv command (Solid menu: Extrude Planar Curve > Straight) with the BothSides option to make the text 3-D. The extrusion distance should be 1 mm.
- **5** Use the **BooleanDifference** command (*Solid menu: Difference*) to recess the text into the surface.


Exercise 26—Flow the logo onto a freeform surface with history


In this part of the exercise, we will use the copy of the logo that is on the Logo layer and position it on the cutout surface. This surface is not flat so we will use a different transform tool, **Flow along Surface**, to move it and bend it along the surface. **Flow along Surface** morphs objects from a source surface to a target surface. It uses the UV of the surfaces to determine how it flows. It is important that the source and target surfaces have the same relative UV direction.

To make the base surface


1 Start the **Layer** command and make the **Cutout** layer the current layer. Then, turn off all the layers except **Cutout** and **Logo**.











Use the BoundingBox command (Analyze menu: Bounding box) to 2 make a rectangle around the logo.

3 Use the PlanarSrf command (Surface menu: Planar Curves) to make a surface from the bounding box.

To flow the logo curves onto the cutout surface

- Use the **Dir** command to check the UV directions of the cutout surface. 1
- 2 Use the **Dir** command to adjust the UV directions of the base surface to match the direction of the cutout surface.
- In the status bar, make sure **Record History** is on. 3

If the text is not bold, click in the pane to turn on history recording.


Use the **FlowAlongSrf** command (*Transform menu: Flow along Surface*) 4 to move the logo onto the cutout surface.

Notice that the curve does not fit the surface.


Turn on the control points on the base surface and move them to make 5 the surface a little larger in all dimensions.

Since history was on when flowing the curve, any adjustment to the base surface changes the way the curve fits on the cutout surface.

- Use the **ChangeDegree** command (Edit menu: Change Degree) to 6 change the base surface to degree **3** in both the **U** and the **V** direction.
- Adjust the control points further to fine tune the way the curve fits on the 7 cutout surface.








APPLYING 2-D GRAPHICS







To raise the logo lettering and flow it onto the cutout surface


1 Use the **ExtrudeCrv** command with the **BothSides** option to make the text 3-D. The extrusion distance should be **1 mm**.

2 Use the **FlowAlongSrf** command to move the solid logo onto the cutout surface. Use the new base surface.

History is not needed this time, since all the needed adjustments were already done on the base surface.

3 Use the **BooleanUnion** command to join the logo with the cutout surface.

CHAPTER 10









Make a model from a 2-D drawing

One of the more difficult modeling tasks in modeling is to interpret a set of 2-D views into a 3-D model. Very often, the drawings are precise in some areas and inexact in areas where complex surface transitions must take place in three dimensions.

It is best to consult directly with the designer to clarify difficult areas, but this is not always possible. Usually there are discrepancies between the views.

If there is no physical model available as reference, some decisions must be made along the way about the best way to interpret the control drawing. For example, you will have to consider which view to consider the most accurate for a given feature.

In the following exercise, we will explore some strategies to create a blowmolded plastic bottle from a set of 2-D drawings. In this exercise, we have a control drawing showing three views of the bottle. It is roughly dimensioned, but we need to hold to the designer's curves wherever possible.

We will only have time to finish the first stage of this model in class. We will complete the bottle surfaces, but the details will be left out. Included in the models folder is a finished bottle for your review.

Exercise 27—Making a detergent bottle


To group the parts

- 1 Open the model Detergent Bottle.3dm.
- 2 In the **Top** viewport, window select the objects that make the top view (lower left) including the dimensions of the 2-D drawing.
- **3** Use the **Group** command to group the selected objects (*Edit menu: Groups* > *Group*).
- 4 Repeat the previous steps to group the objects for the front view (upper left) and the right view (upper right).

Each of the views is a separate group of objects.


To orient the Top view

- **1** Select the top view group.
- 2 Use the **ChangeLayer** command (*Edit menu: Layers > Change Object Layer*) to change the layer to the **2D Template Top** layer.
- **3** In the **Top** viewport, use the **Move** command to move the center of the circles to **0,0**.



Control drawing





To orient the Front view

- **1** Select the front view group.
- 2 Use the **ChangeLayer** command to change the layer to the **2D Template Front** layer.
- **3** In the **Top** viewport, use the **Move** command to move the intersection of the centerline and the horizontal line at the bottom to **0,0**.
- 4 While the front view group is still selected, start the **RemapCPlane** command (*Transform menu: Orient > Remap to CPlane*) in the **Top** viewport.
- 5 Click in the **Front** viewport.

The view is oriented in 3-D space.

To orient the Right view


- **1** In the **Top** or **Perspective** viewport, select the right view group.
- 2 Use the **ChangeLayer** command to change the layer to the **3D Template Right** layer.
- **3** In the **Top** viewport, use the **Move** command to move the intersection of the centerline and the horizontal line at the bottom to **0,0**.
- **4** Use **RemapCPlane** to map the right view curves to the Right construction plane.


The view is oriented in 3-D space.


Frequently 2-D curves for design control drawings will not be as carefully constructed as you like for making accurate geometry. Before building 3-D geometry from the 2-D curves, check the curves and correct any errors that can be found.

To create the 3-D curves

The inset part of the bottle will be cut into the surface later. For the moment, we just need to build the outer surfaces. The fillets at the top and bottom indicated in the curves can be left out of the initial surface building and added in as a separate operation. We will need to extend or redraw the edge curves to bypass the fillets and meet at hard corners before making the surfaces.









Several surfacing tools could be used to build the initial surfaces: A **2-Rail Sweep** or a **Surface from Network** of **Curves** are the obvious choices.

Network surfaces do not pay any attention to the curve structure, only the shape. All curves are refit and the resulting surface has its own point structure.

Other commands including the Sweep tools, lofting and edge surfaces do pay attention to the curve structure in at least one direction. In these cases, it often pays to use matched curves as cross sections. The choice of surfacing tools may well determine the way in which the actual input curves are created.

z y x

- 1 Select the groups you made in the previous step, use the **Ungroup** command *(Edit menu: Groups > Ungroup)* to ungroup them.
- 2 Select the curves from each 2-D template view that define the outer surface and **Copy** them to the **3D Curves** layer.

Since the bottle is symmetrical on both sides of the X-axis, you will only need to copy the curves on one side. They will be mirrored later.

- 3 Use the OneLayerOn command (*Edit menu: Layers > One Layer On*) to set the 3D Curves layer.
- 4 **Move** the curve defining the top surface of the bottle to the same height as the top of the vertical curves.

Use **SetPt** or **Move** with the **Vertical** option in the **Perspective** viewport.

5 The vertical curves now can be extended past the fillet curves so that they meet the top and bottom curves exactly on the endpoints of these curves.

One way is to extend the vertical curves using **Extend** with **Type = Smooth**. Snap to the **End** or **Quad** points of the top curve and the base curve at the bottom.

Extending the curves in this way will add complexity to the curves. If it is important to keep the curves simple and well matched, it may be better instead to adjust the points on the existing curves to extend them.


6 Undo the **Extend** operation, and instead point edit the curves directly.


You can make a duplicate set of curves and edit one of each leaving the original in place as a template.


7 Mirror the base, top and side curve visible from the right view to the other side.


The result should be a set of 8 curves that define the surface.

Most of these curves are essentially the original curves from the 2-D drawings but rearranged in 3-D.











8 Join the base curves and the top curves into a closed loop.

The curves are set up for a surface from a curve network or a two-rail sweep.





To make a surface for the bottle with a sweep

From the drawing these are the only curves we have available to define the shape, so we will use these curves directly to create the surface.

- 1 Change to the **Surfaces** layer.
- Window select the curves, and trySweep2 to make a surface thenShade the viewport.

Notice the shape gets severely out of control at the rounded side of the bottle.

3 Move this surface to the side for the moment.

While it is possible to rearrange or add curves to make the **Sweep2** work better, it is worth checking how a surface from a **Curve Network** will work with the same set of curves.

4 Select all of the curves, again, then use the **NetworkSrf** command to create the surface.

The **NetworkSrf** command handles this set of curves much more gracefully.


On your own


Make the inset surface and the handle.

Fillet the edges where indicated in the 2-D drawing.

Included in the model directory is a finished bottle, **Finished Detergent bottle.3dm**, for your review.







11 Surface analysis

Rhino has several tools to help you visually evaluate surface quality. In this exercise, we will use curve and surface analysis tools to help build clean, simple surfaces with good continuity.

Some models require more attention to continuity, primarily, because it will show when manufactured. For example, a blow-molded bottle will not show slight inconsistencies in the surface, but a car panel will.

Exercise 28—Surface analysis

The file, **Surface Analysis.3dm**, has a set of curves you will recognize from the previous exercise. Our task in the current exercise is to make curves that can create cleaner, simpler surfaces with good continuity. We will make use of the **CurvatureGraph**, **Zebra**, and **CurvatureAnalysis** to make sure we set things up for the best results. Lastly, we will compare the surface analysis results in this file with the surface analysis results in the previous exercise.

To evaluate the curves

First, let us look at the curvature graphs of the top and the bottom curves. These curves have a nice enough shape, but there is room for improvement from a surfacing continuity perspective.

- **1** Select the top and bottom curves.
- 2 Start the **CurvatureGraph** command (*Analyze menu: Curve* > *Curvature Graph On*) and set the **Display scale** to a value of **120**.


The graph tells us that both curves are tangent continuous but have curvature discontinuities in a couple of locations.


Assuming we want the surfaces we build from these curves to have curvature continuity throughout, we will be better off modifying these curves before creating the surfaces.

If we decide ahead of time what the surface arrangement will be, that will help us understand how to draw clean new curves.

Building a surface that has consistent curvature as a single surface is good modeling practice. Looking at the bottom curve, we can see two areas that are good candidates for creating the surfaces, so we will start there. There is an area of high curvature at the front (1) and a relatively flat stretch in the middle with a rapidly increasing curvature at the handle side (2). The top curve is smoother overall, but has similar corresponding regions of curvature.

By examining the current curves, we can identify two curves to build at the top and bottom. The white vertical curve intersects the top and bottom curves at the curvature discontinuity of the top curve, which is a modified circle, and on an abrupt change in curvature on the lower curve. This intersection is where we will start and end our modified curves.






To build the modified curves


1 Using the current curves as a reference, draw four new curves of degree five with six points.

The goal is to redraw the top and bottom curves in two parts each.

Keep in mind what you know about continuity, **CurvatureGraph**, tangent directions, and **EndBulge**.

Try to keep the control point locations even and progressive.





Analyze your curves with the **CurvatureGraph** command. 2

Try to get the graph clean with minimal, abrupt changes, while at the same time match the original curve shapes as closely as possible.

They cannot be exactly the same as the originals if they are to have better continuity, but it should be possible to get close.


To make the surfaces for the bottle from edge curves

There are four, single-span, curves that define each area for the surfaces. In this part of the exercise we will use the **EdgeSrf** command (Surface menu: Edge curves) to create the surfaces. This command is one that uses the input curve structure to create the surface. It works best if the curves on opposite sides of the rectangle match each other. The resulting surface will be simpler.

Since we have taken care to meet this criterion, all of the vertical curves are degree 3 with four points, and the curves we just made are degree five with six points, the resulting surfaces will share this structure.


- 1 Select four curves that define one of the surfaces.
- Start the EdgeSrf command (Surface menu: 2 Edge curves).
- Repeat steps 1 and 2 for the other surface. 3
- Check the surfaces with the **Zebra** command. 4


The zebra stripes have a nice even flow but the surfaces are clearly not tangent at the vertical edge.




U Canada de J

Ĥ









To match the surfaces for the bottle with MatchSrf

1 Use the MatchSrf command (Surface menu: Surface Edit Tools > Match) to match the surfaces for Curvature. Try matching in both directions, and with or without Average surfaces set.

In this case, the results are good no matter how the match is made, but it is worth looking at the control points on the surfaces in each case.

Matching the larger surface to the smaller one, without Average, results in a more erratic control point arrangement on the larger surface than any other combination, particularly the second row from the top. Other considerations being equal, the best choice is the surface with the most regular, even control point arrangement.

2 Check the surfaces with the **Zebra** command.

The zebra stripes have a nice even flow with no discontinuity at the common edge.


To match the surfaces for the bottle with Symmetry


In this section, we will make the other half of the bottle using the **Symmetry** command with **Record History** turned on. **Symmetry** mirrors curves and surfaces, makes the mirrored half tangent to the original, and with History recording active, when the original object is edited, the mirrored half updates to match the original.

- **1** Select the larger surface.
- 2 Use the **Symmetry** command (*Transform menu: Symmetry*) to mirror the surface across the x-axis. Make sure **Record History** is **on**.
- **3** For the **Select curve end or surface edge**, select the edge of the surface (1).
- 4 For the Start of symmetry plane, type 0 and press Enter.
- 5 For the End of symmetry plane, use Ortho to pick a point along the x-axis.









6 Repeat this process for the other surface.

If you edit either original surface, the mirrored part will update to match.

To analyze the matched surfaces

Check the surfaces with the **Zebra** command.

discontinuity at the common edge.

The zebra stripes have a nice even flow with no

At this point, we will use the **Curvature Analysis** tool to evaluate the matched surfaces. This can be useful in locating areas of extreme curvature, but may force the display to ignore more subtle changes. In any case, the display on each of these simple surfaces should be very smooth and clean.

- **1 Hide** all curves to get a good view of the transitions between surfaces.
- 2 Select all of the surfaces and turn on **Curvature Analysis** display (*Analyze menu: Surface > Curvature Analysis*).

Set the style to **Gaussian**, and click **Auto Range**. Make sure you have a fine analysis mesh for a good visual evaluation. Click back and forth between **Auto range** and **Max range**.


Auto Range attempts to find a range of color that will ignore extremes in curvature, while Max Range will map the maximum curvature to red and the minimum to blue.

The numbers are for Curvature, which is, 1/radius.

The goal when matching is to maintain as even and gradual a curvature display as possible, while meeting the continuity requirements.


Notice the edges that have been matched appear to have a smooth color transition.







SURFACE ANALYSIS



7


To analyze and compare different surfacing techniques

Next, we will make another surface for comparison.

- **1 Copy** the curves to one side.
- 2 Mirror and Join the top and base curves on the x-axis.
- **3 Mirror** the vertical side curve on x-axis to make a set of curves suitable for a surface form a curve network.
- **4** Use **NetworkSrf** to make a surface from these curves. Select the new surface and **Add** it to the **Curvature Analysis** display.

The denser network surface (2) has a less clean appearance in this display. The simple surfaces (1) still look cleaner at this point.

Since the color change is mapped across the entire range shown, it is important to remember that the Auto Range setting indicates a very narrow range of curvature and that the actual differences may be small even though the color change is great.



12 Sculpting

Designers can build a relatively undefined surface and then use a variety of transform and analysis tools to sculpt a surface in 3-D space in an intuitive and direct manner—design "as you go."


Place curves approximately. The curves should be edited copies of a single original if possible.

This ensures that they will be compatible when lofted, and create the simplest, most easily edited surface.

Start with the big changes and then make the detailed changes.

Use the **IncrementalSave** command to make copies of the model as you progress.

In the following exercise, we have created four curves for you to use. They describe a very simple dashboard from which to start your design. An added steering wheel, on a locked layer, is to help you get a sense of scale and positioning of any elements you might wish to add.



Tools to help in control point editing

Move **Control Points** by dragging, using the **Move**, **Rotate**, or **Scale** commands or other **Transform** commands.

Dragging, of course, is the most fluid and interactive way to edit the shape. However, there may be situations where the construction plane constraint for point movement is less than optimal. Here are some tools that can help with control point editing:

Gumball

Gumball works very well with control points. It is convenient to be able to switch easily among the various gumball orientation modes. Opening the **Gumball** toolbar will help.



When Gumball orientation is set to **Align to Object**, the blue axis orients itself to the surface normal for a selected control point. By dragging the blue arrow, the control point moves in the local surface normal direction. The red axis aligns to the surface U direction. Make fine adjustments by setting the Gumball drag strength to something less than 100%.

DragMode

DragMode lets you override the current construction plane constraints in several ways.



Command-line options

World

This constrains dragging as if the CPlane were always World Top. This is rarely used.

CPlane

The default constraint in Rhino. Dragging takes place parallel to the active CPlane.

View

Dragging takes place parallel to the current viewport. This can be useful in some oblique views.

UVN

Dragged surface control points with Ortho on (*Shift* key) are constrained to the surface u- and v-directions and with the *Ctrl* key are constrained to the surface normal direction. Curve points are constrained to the curve tangent and with *Ctrl* to the curve normal direction. For this exercise, this is most useful drag mode.

ControlPolygon

This mode constrains dragged curve and surface control points to the control polygon. In the case of multiple selected points, each moves along its own control polygon. This is an excellent tool for keeping points well organized in rows and columns.

As with the Gumball, having the **DragMode** toolbar open makes it easy to switch among modes while point editing. Notice the cursor changes to reflect the current drag mode. In general, you will probably find it easier to switch the **Gumball off** when dragging points using the special drag mode options.

MoveUVN

This tool opens a dialog box that allows you to move control points in increments according to a user set scale. The point movement can be along the U, V, and N (Normal) directions. In addition, there are smoothing tools in this dialog. These are very useful for smoothing out bunched or irregular control points to achieve a more regular grid.

Nudge

Use the arrow keys with **Alt**, **Alt+Shift** and **Alt+Ctrl** to move points in small increments. Note the settings in the (Options > Modeling aids > Nudge page) allow you to set the Nudge constraints similarly to some of the **DragMode** settings mentioned above.

Tip: You can use the knowledge gained in the User Interface portion of this course to create macros that make it easy to swap among the nudge modes.

SetPt

This allows you to true up points or rows of points in one, two, or all three dimensions.

Use any or all of the above tools to manipulate the surface points individually and in groups. Keep in mind the point selection tools: **SelU**, **SelV** and others in the **Select Points** toolbar.

You will see that with a relatively sparse set of control points, as we have on this starting surface, the edits you make tend to be large ones that affect the shape broadly. It is likely that you run out of control quickly.

In this case, you will find that you need have more localized control to add smaller details. You can add control by increasing the density of the control points. There are two similar tools for this:

InsertKnot

Inserts one or more knots, and rows of control points. Surface points are rearranged so that the shape of the surface does not change. In other words, except in special cases, the new points are not added at the same location as the new knot.

InsertControlPoint

Allows you to place the row of points where you want them to be, however the mechanism for adding these points does nothing to ensure that the shape of the surface stays the same. Generally, the shape will change.

Both **InsertKnot** and **InsertControlPoint** have advantages, but when you are making heavily curved and sculpted surfaces, **InsertKnot** may be the safer choice since it does not change the shape of the surface.

Some considerations when inserting knots

Insert as few knots as you can to get the control you need. Add more later if needed. Keep the surface as simple as possible while getting the control you need.

Where possible, insert knots so that they are as evenly spaced as possible. Try to place them halfway between existing knots.

Command-line options

Automatic

Adds knots halfway between existing knots to maintain as uniform a structure as possible. It increases the knot density of a curve or surface, and thus the control point density as well, while maintaining an even

knot distribution, which makes point editing more predictable than with unevenly spaced knots. Be careful with this option, as it adds a knot between each pair of existing knots, so a surface can become very dense in structure very quickly.

MidPoints


Places markers halfway between the existing knots/knot lines that can act as guides for inserting knots midway between existing knots. Use the **Point** object snap to place new knots at these markers.


Note: It is easy to get to a point where there are too many control points and you simply lose control of the shape. Therefore, it is a good idea, to use **IncrementalSave** before adding complexity to the object. This will allow you to go back to a simpler model without starting over if things get out of hand.

Exercise 29—Dashboard

- 1 Open the model Dash.3dm.
- 2 **Loft** the four curves together with the **Loose** option from the dropdown list.

Using the **Loose** style creates the simplest possible geometry and is essential to creating a surface with this technique. The surface will not touch the interior curves of the loft with this option, but it should be very smooth and clean looking.






3 Turn on the control points.

If you also turn on points for the input curves, you will see that the point structure of the surface exactly matches that of the four curves.

4 Turn off the **Curves** layer.


You can do at this point to sculpt the shape. The most obvious one is simply to move the surface control points around, so let us start there.


As mentioned, Rhino has several powerful tools to help in control point editing.



To edit and sculpt the surface

- 1 Turn on the points for the surface, with **Gumball** off for the moment.
- **2** Window select the three control points that are just to the right of the steering column centerline.
- **3** Use the **SetPt** command (*Transform menu: Set XYZ Coordinates*) to align the groups of points in the x direction in Top or Front snapping to the centerline.





Notice that when the points are selected, there is a red and a green line extending from the selected pointsthis indicates the positive u- and v-directions. 4

- Use this information with the point selection tools NextU, NextV, PrevU, or PrevV to shift the selection to the left or right to the next row of
- points. SetPt these points to the corresponding edge, left and right, of the steering wheel.
- Use **Gumball** to drag the lowest three 5 points near the steering wheel down to accent the shape.

The shape may not be symmetrical compared to the steering wheel.

- 6 Select the points nearest the top edge of the steering wheel and set them all to the same Z using **SetPt**.
- Now, let us add some definition to the 7 dash in the area of the steering wheel. Set the DragMode to **ControlPolygon**, and drag three of the points up very close to their neighbors.

The shape of the surface changes only slightly. It is still very soft, and there are no more points available to continue to edit there.

Use the InsertKnot command (Edit 8 menu: Control Points > Insert Knot) to add a row of points in the V direction.


> The surface currently has no interior knots so use the Automatic option once to add a single knot.


Now, with the extra points you can continue to slide points along the control polygon to sharpen up the surface in this area.


- Use the **IncrementalSave** command (*File menu: Incremental Save*) before going on to the next step. 9
- set the point weight of some of the points on the surface. For example, select the three middle points that are at the apex of the now sharply curved area we have been editing. Start the Weight command (Edit menu: Control Points > Edit Weight). Increase the weight of the points to **2**.


10 Another way to tweak the shape is to


Higher weight points, relative to neighboring points, tend to pull the surface toward them. Lower weight points cause the surface to fall away from the control points.











SCULPTING

Robert McNeel & Associates

To add and manipulate knots

CHAPTER 12

Try inserting knots in either direction, using the **Midpoints=Yes** setting to be able to snap to span midpoints. Insert some knows with **Midpoint=No** to insert knots close to existing ones to allow more local control.

- 1 Use the **IncrementalSave** command (*File menu: Incremental Save*) before going on to the next step.
- 2 Use **InsertKnot**, **Midpoints=Yes**, to insert some knots in the **U** direction. Snap to midpoints to keep knot spacing even.

Notice how the control point arrangement changes with each knot inserted. You may want to true up some rows of points in X using **SetPt** to keep the rows and columns organized.

- **3** Explore different shapes and design ideas using all of the tools mentioned above.
- 4 Select some points that are out of alignment. Start the MoveUVN command (Transform menu: MoveUVN). Use the Smooth sliders to smooth some of the points that are out of alignment.
- **5** Move some points to the right of the steering wheel closer to it to make the shape more symmetrical about the steering wheel.

Where possible, try to keep the control point arrangement even and progressive. As you might expect, there tend to be more control points in areas that have been edited and shaped the most.

6 Add some more knots in the area of the top of the steering wheel.


If you crowd a few knots in this area, you can pull out a localized feature that fades smoothly into the surrounding surface.


To make the offset surface


When you are satisfied with the overall shape of the surface, you can add details to make a more finished object.

The surface can be offset and trimmed as in the first illustration.

Best results are obtained when the surface has at least degree 3 in both directions. Check this with Object Properties.










Note: Offsetting surfaces generally results in a surface of one step lower in internal continuity. Surfaces that are only G1 internally may result in surfaces that have G0 continuity; that is, they may have a kink in them. Although Rhino allows these surfaces, this can lead to problems downstream.


For this reason, if you intend to offset surfaces, it is best where possible to create the initial surface from degree 3 or higher curves. These surfaces have at least G2 continuity so that offsetting them will result in at least G1 continuous surfaces. Changing the degree of a surface that has been created from degree-2 curves to at least degree 3 in both directions is not sufficient to ensure a G2 surface. Simply changing the degree after the fact does not improve internal continuity.

- 1 Change to the Cutting Curves layer.
- 2 Draw a **curve** that represents where you want to split the surface.
- **3** Use the **Offset** command (*Curve menu: Offset Curve*) to make a duplicate of the curve offset by one-half (**0.50**) inch.
- 4 Use the **Trim** command (*Edit menu: Trim*) to trim the surface between the curves.
- **5** Use the **OffsetSrf** command (*Surface menu: Offset Surface*) to offset the back surface by one-fourth (0.25) inch.











6 Delete the original surface.




Use the BlendSrf command (Surface menu: Blend Surface) to blend between the two surfaces. Set edge 1 to Curvature (G2) and edge 2 to Position (G0).

One of the things we are trying to show here is a quick way to make a "tucked" upholstery type transition.

Adjust the **BlendSrf** sliders so the cross-section looks like the example on the left.






8 Add details if time allows.



13 Deformation tools

Deformation tools allow you to deform meshes, lines, surfaces, polysurfaces, and solids without worrying about the integrity of the object.

Start the deformation commands from the **Transform** menu, or from the **Deformation Tools** toolbar:



lcon	Command	Description	
\mathcal{O}	FlowAlongSrf	Morphs objects from a source surface to a target surface.	
2	Splop	Copies, rotates, scales, and wraps objects on a surface, like pottery sprigging or appliqué.	
◇ ∠∎⁄	OrientOnSrf	ientOnSrf Moves or copies and rotates objects on a surface using the surface's normal direction for orientation.	
日田	Maelstrom	Deforms objects in a spiral.	
	Stretch	Scales selected areas of an object in one direction.	
∎Ž	Twist	Deforms objects by rotating them around an axis.	
	Bend	Deforms objects by bending along a spine arc.	
\square	Taper	er Deforms objects toward or away from a specified axis.	
\mathbb{P}	Flow	Re-aligns an object or group of objects from a base curve to a target curve.	
i¢:	CageEdit	Deforms objects smoothly using one-, two-, and three-dimensional cages.	
i¢:	Cage	Creates a box-shaped cage object to be used with the CageEdit command to deform other objects.	
Ó	ReleaseFromCage	Removes selected objects from the influence of a control object set up by the Cage or CageEdit command.	

Deforming objects

Exercise 30—Using cage editing to deform an object

To deform an object with CageEdit

- 1 Open the model CageEdit_Mug.3dm.
- 2 Open the **Cage** toolbar.



- **3** Start the **CageEdit** command (*Transform menu: Cage Editing > Cage Edit or Cage toolbar*) and select the mug as the **captive object**.
- 4 For the **control object**, choose **BoundingBox** and then **World**.
- **5** Specify four cage points and degree 3 in each direction.

The degree can be set up to degree 9. The point count must be greater than the degree value in each direction.

6 For the **Region to edit**, choose **Global**.

The deformation of captive objects will take place throughout 3-D space and will not end at the edges of the cage. This setting is important if some of the captive objects are outside of the cage.

7 Move the control points on the top of the cage vertically to deform the mug.

Cage points can be moved, dragged, scaled, sheared, rotated, bent, etc.

To limit the region to edit


To deform the handle only, a cage object is needed around the just the handle.


- 1 Use **ReleaseFromCage** (*Cage toolbar*) the mug from the cage object. **Delete** the cage.
- 2 Start the **Cage** command and create a freestanding cage object.
- 3 Move the cage into place and Scale it before attaching it to the mug
- 4 Start the CageEdit command.
- 5 For the **Select captive object**, select the mug.
- 6 For the **Select control object**, select the pre-positioned cage object.
- 7 For the Region to edit, choose Local and set a Falloff distance to 5.

This tells Rhino that the distortion of the cage will affect only the region inside the cage, plus a smooth falloff effective over 5 units moving out from the cage itself.

8 **Move** the two right-most vertical rows of cage points slightly to the right in the **Front** viewport to increase the size of the handle.












To CageEdit with a surface from the object

While it is possible to use any curve or surface as a control object in **CageEdit**, there are many cases where the most intuitive solution is to use a curve or surface that is already part of the object.

The **CageEdit** command lets you select a surface, including a surface from the captive object, to use as control object.

- **1 Open** the model **Salad_Cage.3dm**.
- 2 Select the salad fork and start CageEdit.
- 3 For the **Control object**, click on the top surface of the fork.


A copy of the surface is extracted from the object and turned into a control object.




- **4** Accept the defaults for the subsequent options.
- **5** When the control points are on, move the five points nearest the end vertically.

This gives the fork a little more bend to the front of the fork.

6 Undo.






To CageEdit with a curve from the object

A curve can also be used as a control object. In many cases, it makes sense to use a curve that already has the same basic shape as the object. You can draw such a curve or extract an isocurve from the object itself and use this as the control.


1 Re-open the model Salad_Cage.3dm without saving.

The red curve is an extracted isocurve from the bottom surface that has been extended slightly at each end.

- 2 Select the salad fork and start CageEdit.
- **3** Select the red curve as the **Control object**.



4 Edit the shape of the fork by point editing the **Control object**.




Exercise 31—Using other deformation tools

To stretch an object


The Stretch command allows you to scale a selected area of an object in one direction.


- 1 Open the model **StretchWrench.3dm**.
- 2 Select the wrench.
- **3** Start the **Stretch** command (*Transform menu: Stretch*).
- 4 For the **Start** and **End of axis**, snap to the two locked points.



5 For the **Point to stretch to**, pull the cursor to one side or another to stretch or compress the wrench.

The section of the wrench that falls between the points that set the stretch axis is the part that is deformed. The object outside of this initial axis is moved, but not deformed. The shape of working parts of the wrench at either end are not affected, but the overall object is made longer or shorter.





To place a small detail on an object

Here the goal is to place the small detail that is off to the side of the cup onto the cup handle. The detail is easy enough to build in a flat, orthographic orientation but would be quite tedious to build accurately in place on a curved surface.


The **OrientOnSrf** command can place an object on an arbitrarily curved and oriented surface with good control over the placement and can optionally also deform the object to match the curvature of the target surface.

- 1 Open the model OrientOnSrf_detail.3dm.
- 2 Start **OrientOnSrf**, and select the detail object.
- 3 For the **Base point**, snap to the point marked 1.

This will be the point that is placed on the target surface.

4 For the **Reference point**, snap to the point marked **2**.

This point and the line between it and the base point will be used to set scaling and orientation on the target surface. The current CPlane Z direction will be mapped to the target surface normal.



5 The **Surface to orient on** is the handle surface of the cup.

In the dialog, make sure **Rigid** is not checked.

This will allow the object to deform against the target surface.

Set **Scale** and **Rotation** to **Prompt** so that you can set these interactively as needed.

Rotation defaults to setting the line between the base and reference points set above to the U direction of the target surface.

Click **OK**.

6 For the **Point on surface to orient to**, snap to the point on the handle marked **3**.

Notice that in the preview the location corresponding to the base point is what tracks on the target surface.

With the command-line **Copy=Yes** option, you can place the object without disturbing the flat original and you can place multiple copies.

Set Copy=Yes.

There are other command-line options for **Flip**, in case the object maps to the wrong side of the surface, and **IgnoreTrims**. If **IgnoreTrims** is set to **Yes**, the object can be placed anywhere on the underlying surface of a trimmed face, otherwise location is restricted to the trimmed face.

7 Click to set the location point.

Since Scale was set to Prompt, you can drag interactively to scale the object or you can type in a scale factor at the command-line. In this case, a **Scale factor** of **.7** works well.

8 You can rotate the object on its base point. Holding Ortho can lock the angle to match the construction plane, or you can type in an angle at the command-line. In this case, the **Rotation angle** is **zero**.

After setting the angle, the object is mapped to the target surface.

9 At this stage, you can continue to add details to the handle or press **Enter** to end the command.

To deform an object in a spiral


In this example, we will deform the spokes of a wheel to give them a twisted look with the **Maelstrom** command.

- 1 Open the model Maelstrom.3dm.
- 2 Select the spokes of the wheel and start the **Maelstrom** command (*Deformation Tools toolbar*).
- 3 In the Front viewport, set the Center of Maelstrom at 0.
- **4** For the **Radius**, snap to the point on the locked circle near the center of the wheel (1).
- **5** For the **Second radius** snap to the point to the right of the wheel on the arc (2).












6 For the **Coil angle**, drag the cursor around the circle about 15 degrees to deform the spokes into a soft spiral shape.






To deform an object by flowing it along a curve

In this example, we will flow an object along a curve while recording history. This will allow us to do a secondary deformation of the original object and see the update on the flowed piece.

- 1 Open the model Flow & Twist.3dm.
- 2 On the Status bar, turn Record History on.
- **3** Right-click the **Record History** pane, and select the **Update Children** checkbox.




- **4** Select the polysurface and start the **Flow** command (*Transform menu: Flow Along Curve*).
- 5 Set Copy=Yes, Rigid=No, Local=No, and Stretch=Yes.
- **6** For the **Base curve** select the straight line (through the center of the polysurface).
- 7 For the **Target curve**, select the circle.

A copy of the polysurface flows around the circle.

- 8 Select the original polysurface, and start the **Twist** command (*Transform menu: Twist*).
- **9 Twist** the original polysurface **360** degrees, using the straight line as the twist axis.

The polysurface created with the **Flow** command and History updates to match the twisted polysurface.





14 Blocks

There are two main advantages to using blocks in Rhino:

- Identical objects can be edited or replaced at the same time.
- Since many identical objects refer to one definition, files with many repeated objects can be smaller, sometimes much smaller, than files where each of those is its own independently defined object.

In Rhino, a block appears as a collection of objects. These can be simple 2-D or complex 3-D objects. A block can be composed of lines, polylines, freeform curves, surfaces, polysurfaces, solids, dimensions, text, and even other blocks. When a block contains other blocks, these are said to be nested. The level of nesting that may be used is not limited.

Instances and definitions

Each block has a single definition. The definition is the set of objects that comprise the block. This definition is hidden from the user. Its purpose is to provide the definition for the instances of the block that appear in the model. There can be any number of instances of a block, but only one definition. Thus, when the user modifies a block definition, all of the instances of that block will reflect the changes.

Defining blocks

Blocks can be defined using the **Block** command. This adds a new block definition and leaves one instance of the block in place.

Block instances can be added by copying existing instances, or by using the **Insert** command. Insert allows you to choose from a list of existing block definitions, or to browse to an external file.

Note: There may be block definitions in a file for which no instances appear. Deleting an instance does nothing to the definition.

Insertion points

Each block has an insertion point. This is a base location for the block as a whole and is in fact the point used when a block instance is added using the **Insert** command.

Embedded and linked blocks

When the definition of a block is saved in the Rhino file, the block is said to be *embedded*. If the block definition exists as a separate file, the block is *linked*. In the latter case, saved changes to the external file are what govern the appearance of the block instances in all of the files into which it is inserted.

Layers and blocks

Layers can be confusing when using blocks. It is important to keep in mind that any instance of a block will exist on some layer just like any Rhino object. Typically, this is the layer that is current when the instance is inserted, but the instance layer can be changed, just like any other type of object. However, each object in the block definition also exists on some layer, independent of the block instance as a whole. For example, two instances of the same block can be on different layers, but the objects comprising the block definition will be on the same layers in each instance.

Turning on or off a layer containing an instance will show or hide the entire instance. Turning on or off layers of the objects contained in a block will show or hide that part in every instance of the block, regardless of what layer the instance is on.

Linked blocks' layers (*reference layers*) can be shown in the layer panel as normal layers, or displayed as special reference layers.

Here are some rules that are good to keep in mind when using blocks:

- The layer that is current when the block instance is inserted is called the reference layer. The inserted instance resides on this layer.
- The visibility of the entire block is controlled with the block reference layer.

- If you turn the block reference layer off, the entire block will not be visible, regards less of the layers to which the geometry is assigned.
- Objects in the block that have properties assigned *by parent*; will have a unique behavior when grouped together in a block.
- Object properties of display color, plot color, and plot width can be assigned by parent.
- Objects assigned *by parent* and grouped into a block have a *chameleon-like* property. They change to display the color and the plot weight of the block's reference layer.
- This powerful feature allows a block to look different, without creating a separate block.
- The layer that is current when the block is made does not have any bearing on the block definition itself. The layers of the objects in the block definition, and the layer that is current when an instance is inserted are important in how the block instances behave with respect to visibility.


Editing blocks


Block definitions are most easily edited using the **BlockEdit** command, or by double-clicking on a block instance. If the block is a linked block, editing will open the linked file in a new instance of Rhino and the current Rhino will be suspended until that second Rhino is closed.

Exercise 32—Block basics

To make a block

- **1** Start a new model.
- 2 Draw a box and a sphere somewhere near the origin.
- 3 Select the two objects
- 4 Use the **Block** command (*Edit menu: Blocks > Create Block Definition*) to make a block.
- 5 For the **Block Base Point**, snap to a corner of the box.





The point you select will become the insertion point for the block.


- 6 In the Block Definition Properties dialog Name field, type Test 1, press OK.
- 7 Use the **Insert** command (*File menu: Insert*) to insert the new block.
- 8 In the dropdown list at the top of the **Insert** dialog, select **Test 1**.


Make sure to insert as **Block Instance** and not as a **Group** or **Individual Objects**. Accept the defaults for **Scale** and **Rotation**.

9 Place the block in the Rhino scene.

Notice that the cursor follows the location that you set as the block base point when the block was created. This is the insertion point.

10 Select the block instance and make one or two more copies of this instance using the **Copy** command.





To redefine a block


CHAPTER 14


1 Double-click one of the block instances.

This opens the **Block Edit** dialog, returns the original geometry at the block location, and turns all of the other blocks to a dark shaded color. The sphere and box now select individually.

2 Use **FilletEdge** to fillet the edges of the box, **Move** the sphere slightly, and add a **Circle**.


Block Edit				
Add Object				
Remove Object				
Set Base Point				
Test 1				
OK Help				
L <i>l</i>				





3 Click **OK** on the **Block Edit** dialog.

Notice the other instances of the block placed and copied earlier are now updated and look like the redefined block. Instead of a box and a sphere, the blocks have a filleted box, a moved sphere, and a circle.



Exercise 33—Inserting files as blocks

The **Insert** command has options for insertion point, scale, and rotation. The block can be inserted as a block instance, a group, or individual objects.

To insert a block

- 1 Open the Blocks-mm.3dm model.
- 2 Make the Fasteners layer current.
- 3 Use the Insert command (*File menu: Insert*) to insert the FILH-M6-1.0-25.3dm model.
- 4 In the Insert dialog, choose Insert as Block Instance, and click OK.
- 5 In the Insert File Options dialog, choose Embed and link, click OK.

- 6 For the **Insertion point**, snap to the center of one of the holes in the cover.
- 7 **Copy** the cap screw around to all of the other holes.





To change the block

- 1 Start the **Block Manager** command (*Edit menu: Blocks > Block Manager*).
- 2 Select the block definition for the cap screw that you inserted.
- 3 Click the **Properties** button.
- 4 In the **Block Definition Name** box, type **Fastener**.
- 5 Under File name, choose Browse, select RH-M6-1.0-25.3dm, and click Open.
- 6 In the Block Definition Properties dialog, click OK.
- 7 In the **Block Manager**, click **Update**.

The cap screws change to the round head cap screws and the color changes to match the layer color of the insertion layer.

Note: Even on a small file like this, the size difference can be significant. If this file would have had the cap screws imported and then copied around, it would be 35-40 percent larger than it is with block instances. The use of blocks can help to reduce problems caused by large file sizes.



15 Troubleshooting

The troubleshooting tools are most often used for repairing files imported from other programs.

Some Rhino operations can make "bad objects" under certain circumstances. Bad objects may cause failure of commands, shade and render badly, or export incorrectly.

It is good practice to use the **Check** (*Analyze menu: Diagnostics > Check*) or **SelBadObjects** (*Analyze menu: Diagnostics > Select Bad Objects*) commands frequently during modeling. If errors can be caught right away the objects can often be fixed more easily than if the bad part is used to make other objects.

If the goal is to create a rendering or a polygon mesh object, some errors can safely be ignored so long as they do not get in the way of building the model itself in later stages.

For objects that must be exported as NURBS to other applications for further engineering or manufacturing, it is best to eliminate as many errors as possible.

General strategy

The troubleshooting steps will be the same, whether or not the file was created in Rhino or another application. Over time, you will discover patterns of problems and develop procedures to fix them.

Although the techniques used vary greatly depending on the individual file, we will focus on a general strategy for repairing problem files

Start with a clean file

When possible, spending a little time in the originating application to export a "clean" file will save a great deal of cleanup work later. Unfortunately, this is not always an option.

Guidelines for Repairing Files

- 1 Open the file.
- 2 Hide or delete extra data.

Use the **SelDup** command (*Edit menu: Select Objects > Duplicate Objects*) to find duplicate entities and delete them or move them to a "duplicate" layer in case you need them later.

3 Hide curves and points.

Use the **SelSrf** command (*Edit menu: Select Objects > Surfaces*) to select all the surfaces or the **SelPolysrf** command (*Edit menu: Select Objects > Polysurfaces*) to select all the polysurfaces, Invert (*Edit menu: Select Objects > Invert*) the selection, and move the selected items to another layer and turn it off. This will leave only surfaces or polysurfaces on the screen.

4 Check for bad surfaces.

The **Check** and **SelBadObjects** commands will determine if some of the surfaces in the model have problems in their data structures. Move these surfaces to a "bad surfaces" layer for later clean up.

If the bad object is a polysurface, use the **ExtractBadSrf** command to extract the bad surfaces from the original polysurface.

Then you can fix the bad surfaces and then use the **Join** command to reattach them to the good part of the polysurface.

5 Shade the viewport and visually inspect the model.

Does it look like you expected it would? Are there obviously missing surfaces? Do surfaces extend beyond where they should? The trimming curves needed to fix them may be on the "duplicate" layer.

6 Look at the **Absolute tolerance** setting in the **Document Properties** dialog on the **Units** page.

Is it reasonable? Free-form surface modeling requires an intelligent compromise in modeling tolerance. Surface edges are fitted to neighboring surface edges within the specified modeling tolerance. The tighter the tolerance, the more complex these surfaces become and system performance suffers. There is no point in fitting edges to a tight tolerance that is not supported by your down-stream manufacturing processes or by the precision of the input data.

7 Join (*Edit menu: Join*) the surfaces.

When joining, edges are joined if they fit within the specified modeling tolerance. If they are outside the tolerance, they are not joined. Joining does not alter the geometry. It only tags the edges as being close enough to be treated as coincident, and then one edge is discarded.

Look at the results on the command-line. Did you get as many polysurfaces as you thought you would? Sometimes there are double surfaces after importing an IGES file. Usually, one will be complete and the second one will be missing interior trims. When the **Join** happens, you have no control over which of the two surfaces it will select. If you suspect this has occurred, try joining two naked edges. If there is no nearby naked edge where one should be, **Undo** the **Join**, and select for duplicate surfaces. Delete the less complete surfaces and try the **Join** again.

8 Check for naked edges.

Naked edges are surface edges that are not joined to another surface. During the **Join** process, the two edges were farther apart than the specified modeling tolerance. This may be from sloppy initial modeling, a misleading tolerance setting in the imported IGES file, or duplicate surfaces. If there are too many naked edges showing when you run the **ShowEdges** command (*Analyze menu: Edge Tools > Show Edges*), consider undoing the **Join** and relaxing the absolute tolerance and try the **Join** again. It is likely that the original modeling was done to a more relaxed tolerance and then exported to a tighter tolerance.

Note: You cannot improve the tolerance fitting between surfaces without substantial remodeling.

9 Join naked edges or remodel.

The joining of naked edges can be a mixed blessing. It is a tradeoff and may cause problems down-stream. If your reason for joining the edges is for later import into a solid modeler as a solid, or a meshing operation like making an STL file, using the **JoinEdge** command (*Analyze menu: Edge Tools > Join 2 Naked Edges*) will not generally cause any problems. If you will be cutting sections and most other "curve harvesting" operations, the sections will have gaps as they cross edges that were joined outside of tolerance. The gap to be spanned is displayed prior to joining. If the gap is less than twice your tolerance setting, you can proceed without worry. If the gap is too wide, consider editing or rebuilding the surfaces to reduce the gap. **Join** and **JoinEdge** do not alter the surface geometry. They only tag edges as being coincident within the specified tolerance.

10 Repair the bad surfaces.

It is best to repair one bad surface at a time, and **Join** them into the polysurface as you go. In order of least destructive method to most radical, the problems that caused them to fail **Check** can be repaired by the following:

- Rebuild edges
- Detach trim curves and re-trim
- Rebuild surfaces (surfaces change shape)
- Replace surfaces harvest edges from surrounding surfaces, cut sections through bad surfaces and build replacement surfaces from the collected curves.

11 Check for bad objects.

Sometimes joining surfaces that pass check can result in a polysurface that fails check. Generally, this is caused by tiny segments in the edge or trimming curves that are shorter than the modeling tolerance. Extract the adjoining surfaces, check them, use the **MergeEdge** command (*Analyze menu: Edge Tools > Merge Edge*) to eliminate these tiny segments, and join them back in. You are finished when you have a closed polysurface that passes Check and has no naked edges. As you are joining and fixing surfaces, it is generally a good idea to run Check from time to time as you work.

12 Export.

Now that the model has been cleaned up and repaired, you can export it as IGES, Parasolid, or STEP for import into your application.

Exercise 34—Troubleshooting

To try these procedures


1 Open the model Check 01.3dm

This file has a bad object.

- **2** Find the bad object, fix it, retrim, and rejoin the surfaces.
- **3 Open** the file **Check 02.igs**.

This file has several problems. It is representative of commonly found problems with IGES files.

4 After repairing the bad object and trimming it, look for other objects that do not appear to be trimmed correctly.





16 Polygon meshes

A mesh defines a shape using a set of point locations. A mesh knows the location of vertices, but does not know about anything in between the vertices.

Although Rhino is a NURBS modeler, some tools are included to create and edit polygon mesh objects.


We will explore different methods for creating and editing meshes for different purposes. Downstream requirements are the most important considerations when determining which technique to use for meshing. If the mesh is going to be used for rendering, you will use different mesh settings than you would use for a mesh that will be used for manufacturing (machining or prototyping).

Render meshes

When meshing for rendering, appearance and speed are the most important considerations. You should strive to achieve a mesh with as few polygons as possible to get the look you require. The polygon count will affect performance, but too few polygons might not give you the quality you are after in the final rendering. Generally, if it looks good, then you have the right setting.

Meshes for manufacturing

Meshing for manufacturing is an entirely different situation. You should try to achieve the smallest deviation of the mesh from the NURBS surface. The mesh approximates the NURBS surface and deviation from the NURBS surface may be visible in the final manufactured part.



The original NURBS surface.



Meshing for manufacturing, if the mesh is not accurate enough, you will see visible polygon edges on your final products.




Using the same meshing setting, the rendering system can hide polygon edges and visually "smooth" the mesh to show a smooth look.

Exercise 35—Meshing

- 1 Open the model Meshing.3dm.
- 2 Shade the **Perspective** viewport and inspect the curved edge between the surfaces.

A series of angular gaps allows the background color to show.



Robert McNeel & Associates

Get back to a wireframe view. 3

> The edges appear to be exactly coincident. The gaps you saw in the shaded view were due to the polygon mesh Rhino uses to create shaded and rendered views. The polygons are so coarse at the edges that they are clearly visible as individual facets.

- In the Document Properties dialog, on the Mesh page, click Smooth & 4 slower.
- Inspect the curved edge between the surfaces. 5

The overall rounded surface is smoother and cleaner looking but the edges still have gaps.

Although it is possible to use the **Custom settings** to refine the shaded mesh enough to eliminate the jagged edges, this will affect all render meshes in the model. This will increase the amount of time necessary to create meshes and may decrease the performance of shading and rendering to unacceptable levels.

To eliminate the gaps without refining the mesh settings, join adjacent surfaces to each other.

Join the three surfaces together. 6

> The mesh is refined along each side of the joined edges so that they match exactly across the edge. This eliminates the gaps visible earlier.

Rhino saves these polygon meshes with the file in order to reduce the time needed to shade the model when it is reopened. These meshes can be very large and can increase the file size considerably.

7 On the File menu, click Save Small.

This saves the file without the render meshes and the bitmap preview, to conserve disk file space.

Note: The meshes created by render and shading modes on NURBS surfaces and polysurfaces are invisible in wireframe display, not editable, and cannot be separated from the NURBS object. Render meshes are managed for the current model in the Document Properties dialog, on the Mesh page. In addition, you can change per object Render Mesh Settings on the Object Properties dialog.


Meshes from NURBS objects

The meshes created by the **Mesh** command are visible and editable, and separate from the NURBS objects from which they were created.

Rhino has two methods for controlling mesh density: Simple Controls or Detailed Controls. With Simple Controls, a slider is used to roughly control the density and number of mesh polygons. With Detailed Controls, you can change any of seven settings and enable four check boxes to control the way the mesh is made.

The mesh is created in three steps based on the detailed criteria: initial guads, refinement, and adjustment for trim boundaries. These steps are not shown to you; it is all automatic.

In the following exercise, we will discuss each of the seven detailed controls and illustrate their influence on the model.





Polygon Mesh Detailed Options

😼 Polygon Mesh Detailed Options 🛛 🗾					
Density:	0.5				
Maximum angle:	0.0				
Maximum aspect ratio:	0.0				
Minimum edge length:	0.0001				
Maximum edge length:	0.0				
Maximum distance, edge to surface:	0.0				
Minimum initial grid quads:	0				
✓ Refine mesh Jagged seams ✓ Pack Textures Simple planes OK Cancel Help Preview Simple Controls					

Density

Uses a formula to control how close the polygon edges are to the original surface. Values between 0 and 1. Larger values result in a mesh with a higher polygon count.

Maximum angle

The maximum angle between adjacent faces in the mesh. Smaller values result in slower meshing, more accurate meshes, and higher polygon count.

Maximum aspect ratio

The maximum ratio length to width of triangles in the initial grid quads.

Minimum edge length

Bigger values result in faster meshing, less accurate meshes and lower polygon count. Controls the minimum length of the sides of quads and triangles of the mesh.

Maximum edge length

Smaller values result in slower meshing and higher polygon count with more equally sized polygons. When **Refine mesh** is selected, polygons are refined until all polygon edges are shorter than this value. This is also approximately the maximum edge length of the quads in the initial mesh grid.

Maximum distance, edge to surface

Smaller values result in slower meshing, more accurate meshes, and higher polygon count. When **Refine** is selected, polygons are refined until the distance from a polygon edge midpoint to the NURBS surface is smaller than this value. This is also approximately the maximum distance from polygon edge midpoints to the NURBS surface in the initial mesh grid.

Minimum initial grid quads

Bigger values result in slower meshing, more accurate meshes, and higher polygon count with more evenly distributed polygons. This is the minimum number of quads in the mesh before any of the other refinements are applied. If you set a number for this and set all other values to 0, this will be the mesh returned.

To create a mesh using detailed controls

- **1** Select the object.
- 2 Start the **Mesh** command (*Mesh menu: From NURBS Object*).


🔛 Polygon	Mesh Options	x
Fewer polygons	· · · · · · · · · · · · ·	More polygons
ОК	Cancel Help Preview Detailed	Controls

The Polygon Mesh Options dialog appears.

3 In the Polygon Mesh Options dialog, click Detailed Controls.

The **Polygon Mesh Detailed Options** dialog appears. These settings are saved to the Windows Registry when you exit Rhino.

In the Polygon Mesh Detailed Options dialog, set the following, if they are not already set: Density=0.5 Maximum angle=0.0 Maximum aspect ratio=0.0 Minimum edge length=0.0001 Maximum distance, edge to surface=0.0 Minimum initial grid quads=0 Check Refine mesh. Uncheck Jagged seams. Uncheck Simple planes. Check Pack Textures. Click OK.



A mesh is created using the default settings.

Finde the original polysurface, change the viewport display mode to
 Rendered, and use the Flat Shade display mode to view the output.


The **Flat Shade** display mode shows what the model would look like if it were output for prototyping or machining at this mesh density.


 6 Undo the previous operation, repeat the Mesh command, and then make the following changes in the Polygon Mesh Detailed Options dialog: Maximum angle=0.0 Maximum aspect ratio=2.0 Click OK.


Note the changes in polygon count, the shape of the mesh, and the quality of the flat-shaded mesh.


 7 Undo the previous operation, repeat the Mesh command, and then make the following changes in the Polygon Mesh Detailed Options dialog: Minimum initial grid quads=16


Note the changes in polygon count, the shape of the mesh, and the quality of the flat-shaded mesh.














 8 Undo the previous operation, repeat the Mesh command, and then make the following changes in the Polygon Mesh Detailed Options dialog: Minimum initial grid quads=500


Note the changes in polygon count, the shape of the mesh, and the quality of the flat-shaded mesh.


 9 Undo the previous operation, repeat the Mesh command, and then make the following changes in the Polygon Mesh Detailed Options dialog: Maximum distance, edge to surface=0.01 Minimum initial grid quads=0

Note the changes in polygon count, the shape of the mesh, and the quality of the flat-shaded object.









PART IV: Rendering

17 Rendering

With Rhino, creating design renderings of Rhino models is easy. Simply add materials, lights, and render.

There are several controls in the basic Rhino renderer that allows you to create some interesting special effects.

In the following exercise, we will render with and without isocurves, adjust colors, transparency, and ambient light to create images with special effects.

Exercise 36—Rhino rendering

- 1 Open the model Finished Detergent Bottle.3dm.
- 2 On the **Render** menu, click **Current Renderer**, and then click **Rhino Render**.
- 3 In the **Document Properties** dialog, on the **Rhino Render** page, scroll down to the **Miscellaneous** section and check **Use lights on layers that** are off.
- 4 Select the bottle and use the Properties command, on the Material page, to assign it a Basic color of Light Gray. Set the Gloss Color to Light Blue (R=163, G=163, B=194) and the Gloss Finish to 60. Name the material Blue plastic.
- 5 Select the cap and use the Properties command, on the Material page, to assign it a Basic color of Tan (R=222, G=172, B=112). Set the Gloss Color to White and the Gloss Finish to 90. Name the material Tan plastic.




6 Render the Perspective viewport.

To render with isocurves displayed

- **1** Start the **DocumentProperties** command.
- 2 In the **Document Properties** dialog, on the **Rhino Render** page, scroll down to the **Miscellaneous** section and check **Render surface edges and isocurves**.
- 3 Render the Perspective viewport.

The wire color is the same as the layer color because the object's wire color is set to By Layer.



4 Use the **Properties** command, on the **Object** page, to change the **Display Color** to **black**, and then **Render** the **Perspective** viewport.

The objects are rendered with black isocurves.

To render a transparent material with isocurves displayed


1 Use the **Properties** command, on the **Material** page, to change **Transparency** to **70**, and then **Render** the **Perspective** viewport.


The objects are rendered with black isocurves and the material is transparent.

2 Use the **Properties** command, on the **Object** page, to change the **Display** color to white, and then **Render** the **Perspective** viewport.

The objects are rendered with white isocurves and the material is transparent.

- **3** Experiment with these adjustments to get the desired effect.
- **4** Turn on the **Lights** layer and adjust the properties of the lights for more subtle changes.







Rendering properties

With Rhino's Material Editor, you can assign any combination of color, reflectivity, transparency, highlight, multiple bitmaps, and environments.

In the following exercise, we will add environment settings, add materials and lights, create custom materials, edit materials, add decals to objects, and render a scene.

Exercise 37—Rendering a scene


To set up the rendering properties

The rendering properties include environment settings, render, and ambient light settings.

- 1 Open the model Mug.3dm.
- 2 From the **Panels** menu, click **Environments** and **Ground Plane** to open the panels we will use to set a background environment, and to add an infinite ground plane to the scene.

This can also be accomplished by right-clicking on the Properties panel tab.

- 3 In the **Environments** panel, set the background to **Environment** and click **[+]** to add an environment.
- 4 In the **Open** dialog, double-click **Environments**, click **Rhino Interior.renv**, and then click **Open**.




5 In the Ground Plane panel, check On for Ground plane options.

The ground plane will automatically be set for the default material.

🚫 Properties 📚 Layers 🕒 Environments 🛁 Ground Plane 🛛 🛞						
Ground plane options						
📝 On						
Show underside						
Height above world XY plane: 0.0						
Material						
Default material	-					
🕂 New 🗡 Edit	Duplicate					
Name						
Default material						
Basic Settings +						
Textures +						
Advanced Settings +						
Notes +						

6 Render the Perspective viewport.



To assign materials to layers

- 1 In the Layers panel, select the Floss Blister layer, and click in its Material column.
- 2 From the Layer Material dialog, choose Thin Clear Plastic from the dropdown list, and click OK.
- **3** In the **Layers** panel, select the **Floss Container** and **Toothpaste Tube** layers, and click in the **Material** column of one of them.
- 4 From the Layer Material dialog, choose White Shiny from the dropdown list, and click OK.


Scene lighting

So far, we have used the default lighting in Rhino. This invisible light comes from over the viewer's left shoulder. It is enough to illuminate the model and to give you a starting point. The default light is on only if no other lights are on in the scene and it cannot be modified. In order to control the lighting, we are going to add our own lights.


To add lights

- 1 From the **Render** menu, click **Create Spotlight**.
- 2 Make a large spotlight that shines on the scene from the front and slightly above as shown on the right.


Use elevator mode, or turn on the spotlight's control points and drag them to move the light into position.



Spotlight, front view



Spotlight, right view



Spotlight, perspective view

3 Adjust the Properties of the light as shown: Shadow intensity=40 Spotlight hardness=50 Light intensity=50


Rhinoceros	(i) 😒 🙁
O Properties	
0 8	
<u>C</u> olor	
	-
☑ <u>O</u> n	
Intensity	
50	_
Shadow intensity	
40	_
Spotlight hardness	
50	

4 Render the Perspective viewport.

This makes a nicer image, but two or three lights in a scene improve the rendering. We are going to add another light to create highlights on the mug.

To add a second light

- **1** Select the first light.
- 2 In the **Top** viewport, **Mirror** the light across the vertical axis.
- 3 Adjust the Properties of the light as shown: Shadow intensity=60 Spotlight hardness=30 Light intensity=40




Spotlight, front view

4 Render the Perspective viewport.



To add a third light

- **1** From the **Render** menu, click **Create Spotlight**.
- **2** Make a large spotlight that shines on the scene from the below.
- This light will be used to add a little light to the underside of the toothpaste tube and the floss packet.
- 3 Adjust the Properties of the light as shown: Shadow intensity=0 Spotlight hardness=25 Light intensity=20



Spotlight, front view

5 **Render** the **Perspective** viewport.

It is important to turn the shadow intensity to 0 so that the light will penetrate through the ground plane.

To make a material from scratch and assign it to a layer

- **1** Open the **Layers** dialog.
- 2 In the **Layers** dialog, select the **Mug** layer, and click in the **Material** column.
- 3 In the Layer Material dialog, click More Types.
- 4 In the **Types** dialog, click on **Basic Material** and then click **OK**.
- 5 Name the material **Green Ceramic**.


Set the following: **Color** to **Green** (R=21, G=210, B=180) **Gloss finish** to **90 Gloss color** to (R=198, G=247, B=255) **Reflectivity** to **30 Reflectivity color** to (R=21, G=225, B=180)

6 Render the Perspective viewport.

Image and bump maps

Instead of simply using color for your material, you can use an image of a material. You can scan photographs and real objects like wallpaper and carpet, create patterns in a paint program, or use images from libraries of textures from other renderers, or other sources of bitmap images.

Image mapping uses bitmap images to add detail to the material. You can use images to alter many attributes of the material's surface including its color pattern and apparent three-dimensional surface quality (bump). Procedural bumps add a random roughness or knurled quality to the surface.





To create a new material from an existing material

- 1 In the **Materials** panel, right-click **White shiny**, and then click, **Duplicate**.
- 2 Name the duplicated material Toothpaste Cap.
- 3 In the **Textures** section, under **Color**, click (empty click to assign).
- 4 In the **Open** dialog, double-click on **Tube Bump.png**.
- 5 In the **Textures** section, click on **Tube Bump** to see additional settings.
- 6 In the **Mapping** section, set the **U Repeat** to **8**.

Mapping	-
Offset Repeat U r 0.0 r 8.0 ∨ L 0.0 r L 1.0	Rotation Image: Constraint of the second
 Wew based Environment map Automatic Screen WCS 	▼ Preview local mapping V
 WCS (box style) Mapping Channel 	Display In Viewport

- 7 Assign the new material to the **Toothpaste Cap** layer or assign it to the object. Adjust the mapping as necessary.
- 8 Render the Perspective viewport.

The cap has a grooved appearance. The repeat number determines how close together the grooves appear.



Decals

A decal is the method Rhino uses to apply an image bitmap to a specific area of an object.

The decal mapping type tells Rhino how to project the decal onto your object. The four mapping types, planar, cylindrical, spherical, and UV, are described below.

Decal options

Planar

The planar mapping type is the most common mapping type. It is appropriate when mapping to flat or gently curved objects.

Cylindrical

The cylindrical mapping type is useful for placing decals onto objects that curve in one direction, such as labels on wine bottles.

The cylindrical projection maps the bitmap onto the mapping cylinder with the bitmap's vertical axis along the cylinder's axis, and the horizontal axis around the cylinder, like a wine bottle label.

Spherical

The spherical mapping type is useful for placing images onto objects that curve in two directions. The spherical projection maps the bitmap onto the mapping sphere with the bitmap's vertical axis (height), curving from pole to pole, and the horizontal axis curving around the equator.

Initially the mapping sphere's equator is assumed to be parallel to the current construction plane, and the sphere's axis is parallel to the construction plane z-axis. Later you can modify its orientation.


UV


UV mapping stretches the image to fit the whole surface. The U- and V-directions of the surface determine which direction the map is applied. There are no controls.

UV mapping works well for organic shapes, hair, skin, and plant structures.

To map a decal with planar projection

- 1 Turn on the **Decal reference planes** layer.
- **2** Select the toothpaste box.
- 3 In the **Properties** panel, on the **Decals** page, click **Add**
- 4 Select the Minty Green-Box Upper.jpg.
- 5 Click Open.
- 6 Click **Planar** and then **OK**.





7 Using object snaps, pick locations for the decal **Location** (1), the **Width** (2), and **Height** (3) direction of the decal.

These three points define the decal plane's location and extents. The decal plane must lie on or behind the surface of the object. The decal projects up from the decal plane. Portions of the surface that lie behind the decal plane will not show the decal.

After the decal is placed, you can click the control points on the decal control wireframe to move, rotate, or stretch the decal.

8 Press Enter or right-click to set the location.

Place more decals


- **1** Continue to place bitmaps on the sides, flaps, and ends of the box.
- **2** Use planar mapping to put the decals on the floss container and the toothpaste tube.

The magenta rectangles were created to assist with placement of the decals.


3 Render the Perspective viewport.

To map a decal with cylindrical projection

The circle of the mapping cylinder is initially parallel to the current construction plane, and the cylinder's axis is parallel to the construction plane z-axis.







- 1 Select the mug.
- 2 Start the **Properties** command (*Edit menu: Object Properties*).
- 3 In the **Properties** panel, on the **Decals** page, click **Add**.
- 4 Select the Sailboat-002.tif.
- 5 In the Decal Mapping Style dialog, click Cylindrical.
- 6 Use the magenta circle for the **Center of cylinder** and a **Radius** or **Diameter** for the decal.

The controls then let you click the control points on the decal control wireframe to move, rotate, or stretch the decal cylinder.

- 7 Press Enter or right-click to set the location.
- 8 Render the Perspective viewport.



- **9** Turn on the toothbrush layers.
- **10** Adjust the materials settings and lighting as needed to get the desired results.

